

AVBAVA-SE (15 June 71) 2nd Ind  
SUBJECT: Technical Report of Army Aircraft Accident, CH-47A, 64-13116,  
243D ASHC, 10th CAB, Occurring 31 May 1971, Pilot: Moree

DA, HEADQUARTERS, 243D ASSAULT SUPPORT HELICOPTER COMPANY, APO 96377, 21 Jun 71

TO: Commanding Officer, 10th Combat Aviation Battalion, APO 96377

1. The 243D ASHC concurs with the accident investigation board's cause factors and recommendations with the following exceptions:

[REDACTED]

2. The following corrective actions have been taken:

- a. All unit aviators have been briefed on the circumstances surrounding this accident.
- b. Safety classes have been conducted to re-emphasize the board's findings on the CH-47A autorotative corridor, wind direction factors, and single engine characteristics.
- c. The importance of good preflights and post-flights have been re-emphasized to all aviators and crewmembers. Maintenance personnel have been reminded to prevent FOD when performing maintenance on aircraft.
- d. Prior to aircraft refueling, the flight engineer will show the aircraft commander the fuel sample taken from that particular fuel source. Also, an effective SOP for inspection of fuel sources is being written.

"FOR OFFICIAL USE ONLY"

AVBAVA-SE (15 June 71) 2nd Ind  
SUBJECT: Technical Report of Army Aircraft Accident, CH-47A, 64-13116  
243D ASHC, 10th CAB, Occurring 31 May 1971, Pilot: [REDACTED]



FRANK T. PETERLIN  
MAJ, FA  
COMMANDING

"FOR OFFICIAL USE ONLY"

AVBAV-CO (15 Jun 71) 4th Ind  
SUBJECT: Technical Report of Army Aircraft Accident, CH-47 SN 64-13116,  
243rd ASHC, 10th CAB, Occurring 31 May 1971, Pilot: MOREE

DA, HEADQUARTERS, 17TH COMBAT AVIATION GROUP, APO SF 96316, 9 JUL 71

TO: Commanding General, 1st Aviation Brigade, ATTN: AVTASA, APO SF 96384

1. Concur with the findings and recommendations of the Accident  
✓ Investigation Board except as follows: DA Form 2397, item 2: add  
flight surgeons recommendations from DA Form 2297-8.

2. Corrective action taken is deemed adequate and appropriate.

3. A Collateral Investigation is being conducted.

4. Messages have been sent from this Headquarters:

A. Requesting a factory assistance team from ARADMAC, HAMILTON STANDARD  
or LYCOMING, thru 1st Aviation Brigade, to inspect all fuel controls on this  
type of aircraft.

B. Directing that units discuss and conduct Ground Safety Classes on  
HEIGHT-VELOCITY Diagrams in their monthly safety meetings.

C. Directing that units forward a copy of their Safety and Standards  
SOP to this Headquarters. (Ref DA Form 2397, item #2, recommendation #5.)



JAMES H. MERRYMAN  
Colonel, FA  
Commanding

This document is CANCELLED when separated from  
the original bearing a protective marking.

**FOR OFFICIAL USE ONLY**

*Analysis deleted IAW EX. 5, FOIA*

AVBASA (15 Jun 71) 5th Ind  
SUBJECT: Army Aircraft Accident Report, CH-47A, SN 64-13116, 31 May 71,  
Pilot: MOREL

DA, Headquarters, 1st Aviation Brigade, APO 96384 18 JUL 1971

TO: Commanding General, USARV, ATTN: AVHAV-S, APO 96375

1. Concur with the findings and recommendations of the investigating board as amended by the 4th indorsement with the following changes.

[REDACTED]

2. Corrective action appears adequate.

FOR THE COMMANDER:

*F. M. Mc Cullar*

F. M. Mc CULLAR  
Colonel, Infantry  
Deputy Brigade Commander/Admin

1 Incl  
nc

Copy Furn:  
CO, 17th CAG  
CO, 10th CAB  
CO, 243d ASHC

This marking is CANCELLED when separated from the material bearing a protective marking.

FOR OFFICIAL USE ONLY

AIRCRAFT ACCIDENT REPORT CHECK LIST  
(AR 95-5)

Aircraft Type, Model, Series CH-47A	Serial Number 64-13116	Date of Accident 31 May 1971	
Reports	Inclosed	Not Applicable	See Remarks
TAB A - Findings and Recommendations (DA Form 2397)	X		
TAB B - Narrative of Accident (DA Form 2397-3)	X		
TAB C - General Information (DA Form 2397-1 & 2)	X		
TAB D - Witness Statements (DA Form 2397-4)	X		
TAB E - Wreckage Distribution (DA Form 2397-5)	X		
TAB F - Failure or Malfunction (DA Form 2397-6)	X		
TAB G - Flight Surgeon Analysis and Recommendations (DA Form 2397-8)	X		
TAB H - Flight Surgeon's General Information (DA Form 2397-7)	X		
TAB I - Copy of DD Form 1322 (Autopsy Report)			X
TAB J - Copy of A/C Records (DA Form 2408-12, 13, 14)	X		X
TAB K - Copy of A/C Clearance (DD Form 175 or 1080)	X		

REMARKS:

TAB I - Autopsy Report will be forwarded upon receipt.

TAB J - The Aircraft Logbook with the current DA 2408-12, -13, -14, and -18 was destroyed by fire. The previous day's DA2408-13 is enclosed. No other copies of the DA 2408-14, and -18 were available.

"FOR OFFICIAL USE ONLY"

**SUMMARY OF TECHNICAL REPORT  
OF U.S. ARMY AIRCRAFT IDENT**

For use of this form, see AR 95-5, 385-40;  
the proponent agency is Office of  
Chief of Staff for Force Development

REPORTS CONTROL SYMBOL  
CSFOR-3(R1)

**FINDINGS AND RECOMMENDATIONS**

**1. FINDINGS**

**A. ESTABLISHED CAUSE FACTORS**

1. **Material Failure:** The N1 governor driveshaft in the #2 engine fuel control unit boost pump was excessively worn, causing fuel control unit failure and the failure of the #2 engine.
2. **Operation:** The aircraft was outside of the flight envelope for successful recovery from a single engine failure at the point of the #2 engine failure.

**B. PROBABLE OR SUSPECTED CAUSE FACTORS**

1. **PROBABLE: Material Failure:** The #1 engine failed due to an instantaneous power demand that was beyond the capabilities of the engine to deliver.
2. **SUSPECTED:** The instructor pilot was unable to manipulate the cyclic and thrust controls after both engines had failed due to the combination of feedback forces caused by excessively low rotor rpm, declining hydraulic pressure, and the loss (CONT'D)

**C. NONRELATED FACTORS**

1. **Operation:** The departure route of the aircraft was downwind from the reported prevailing winds. The importance of the prevailing winds in assisting recovery from a single engine failure is indicated in TM 55-1520-209-10, pg. 14-38, fig. 14-28.
2. **Inspections:** The presence of non-related foreign objects in several areas of the aircraft on a pre-flight inspection indicates a failure of maintenance personnel (CONT'D)

**2. RECOMMENDATIONS (Recommended Corrective Actions in Order of Importance)**

The Board recommends that:

1. Command action be taken to initiate a one-time inspection of all fuel control boost pump N1 governor driveshafts (FSN 2915-963-0978, P/N 02-13920) installed on CH-47 aircraft in this command in order to prevent a recurrence of this type of failure.
2. All CH-47 aviators be briefed on the height-velocity diagrams for safe landing after a single engine failure and the single engine landing and autorotative corridor, with special emphasis on avoidance areas.
3. All CH-47 aviators be briefed on the importance of wind direction to the (CONT'D)

**BOARD MEMBERS (Signature, Grade, Branch and Rating)**

<b>PRESIDENT</b> <i>John L. Shanahan Jr.</i> JOHN L. SHANAHAN JR., CPT, AR, ARAV ADDRESS AND TELEPHONE NUMBER 92nd AHC, APO 96377, Dong Ba Thin 185	<b>MEMBER</b> <i>Charles S. Ferrer</i> CHARLES S. FERRER, CW3, AVN, SRARAV <b>MEMBER</b> <i>Wilford J. Shelton, CW2</i> WILFORD J. SHELTON, CW2, AVN, ARAV <b>MEMBER</b>
<b>RECORDED</b> <i>Thomas E. Wright</i> THOMAS E. WRIGHT, WO1, AVN, ARAV ADDRESS AND TELEPHONE NUMBER 92nd AHC, APO 96377, Dong Ba Thin 185	<b>MEMBER</b>
<b>MEMBER</b> <i>Clifford G. Hudson</i> CLIFFORD G. HUDSON, CPT, TC/AVO	<b>MEMBER</b>

**REVIEWING OFFICIAL**

STATEMENT OF REVIEWER WILL INCLUDE CONCURRENCE, NON-CONCURRENCE AND CORRECTIVE ACTIONS TAKEN

1. Concur with the findings and recommendations of the accident investigation board.
2. This headquarters has taken the following steps to preclude recurrence of a similar mishap.
  - a. This accident will be discussed at the monthly Battalion Safety Council meeting at which all unit commanders will be present.
  - b. A letter has been sent to all units placing increased command emphasis on each individual aviator knowing the flight envelope for his particular type of aircraft.
3. A collateral investigation is being conducted.
4. Corrective actions taken by the unit commander to preclude recurrence are considered appropriate.

<b>DATE</b> 20 June 71	<b>GRADE, BRANCH, RATING &amp; ORGANIZATION</b> JAMES O. HEGDAHL, LTC, IN Commanding, 10th Cbt Avn Bn	<b>SIGNATURE</b> <i>James O. Hegdahl</i>
---------------------------	---	---

**APPROVAL AUTHORITY**

REMARKS OF APPROVING AUTHORITY  
1. The findings and recommendations of the accident investigation board, as amended by the 2nd, 4th and 5th indorsements, are approved with the following amendments to the 5th indorsement:

<b>DATE</b> 29 Jul 71	<b>GRADE</b> Brigadier General USA	<b>SIGNATURE</b> <i>Jack W. Hemingway</i> JACK W. HEMINGWAY, Aviation Officer	<b>EX. 5</b>
--------------------------	--	---	--------------

DA FORM 2397  
1 JUN 66

REPLACES DA FORM 2397, 1 APR 61, WHICH IS OBSOLETE

PPC-Japan

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT  
PART I (Continuation)

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (See format above for Part I)

1. FINDINGS (CONT'D)

b. Probable or Suspected cause factors

2. (Cont'd) of power to the SAS system upon generator power failure below 204 rotor rpm and blade separation at initial impact.

c. Nonrelated factors

2. (Cont'd) to inspect their work areas and possibly a failure to properly perform the previous post-flight inspection.

3. Supervision: The failure of the crew to consistently remember how fuel samples were taken and checked prior to each refueling indicates a lack of an effective SOP to insure a complete check of POL facilities prior to each refueling.

2. RECOMMENDATIONS (CONT'D)

3. (Cont'd) recovery of single engine failures.

4. FOD inspections be re-emphasized at all supervisory levels.

5. An effective SOP be developed for checking each individual fuel source prior to each refueling of CH-47 aircraft to prevent the possibility of partial fuel cell contamination and assure positive inspection procedures.

"FOR OFFICIAL USE ONLY"

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

PART I (Continuation)

REPORTS CONTROL SYMBOL  
CSFOR-3(R1)


For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

DA Form 2397 Approval Authority, (Continued)

 Ex. 5

2. Corrective actions are adequate.

  
JACK W. HEMINGWAY  
Brigadier General  
Aviation Officer

"FOR OFFICIAL USE ONLY"

DA FORM 2397-3  
1 JUN 66

REPLACES DA FORM 2397-3, 1 APR 61, WHICH IS OBSOLETE  
EFFECTIVE 1 JAN 67

☆ GPO: 1968 O-348-780/103



For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

1. GENERAL:

The president of the accident investigation board received notification from the 10th Combat Aviation Battalion Safety Officer at 1600 hours, 31 May 1971, to investigate the facts and circumstances surrounding the accident of Army aircraft CH-47A, serial number 64-13116, assigned to the 243rd Assault Support Helicopter Company, AFO 96377, located at Dong Ba Thin, RVN. The board consisted of CPT John L. Shanahan, Jr., president; WO1 Thomas E. Wright, recorder; and CPT Clifford C. Hudson, MC/AFO. After a briefing by the 10th Combat Aviation Battalion Safety Officer, the board departed DBT, at 1700 hours, 31 May 71, and after making an aerial survey of the crash site at the 28th Regiment, 9th AOKA (White Horse) Infantry Division RCI, Phu Heip, RVN, arrived at approximately 1810 hours at Headquarters, 17th Combat Aviation Group, Tuy Hoa, AAF, RVN to receive further briefing from the 17th Combat Aviation Group Safety Officer. The 17th CAG Safety Officer had already initiated a fuel contamination check of the Tuy Hoa POL point, recovery of deceased personnel, security of the site by a Military Police detail, and had also obtained preliminary witness statements from the crew, who had already returned to DBT. Because of impending darkness and the totally burned wreckage, the board decided to postpone the ground investigation until the following day, which would allow additional members and technical consultants to be present. The board arrived at the accident site at 0900 hours, 1 Jun 71 accompanied by CW2 Wilford J. Shelton, board member, and USAAVSCOM technical representatives, Robert J. Heady, a CH-47 airframe and airframe equipment specialist and George D. Simpson, a T-55 engine equipment specialist. After surveying the wreckage and completing the preliminary investigation at the site, the board determined that neither engine had been developing power at impact, without apparent cause. Because of the nearly simultaneous engine failure, and the negative report of fuel contamination, it was the opinion of the board and the technical consultants that further investigative assistance should be requested from USAMMA, Fort Rucker, Alabama. This request was forwarded through the 17th CAG but was denied by the 1st Aviation Brigade and USARV Safety offices on the grounds that sufficient technical assistance was available at the scene and through the teardown and analysis program. The board then returned to DBT and initiated a check of maintenance records. The board interviewed the crew members individually on 2 Jun 71 at DBT and continued its check of the maintenance records. Returning to Phu Heip on 3 Jun 71, the board acquired CW3 Charles S. Ferber as an additional member, and completed final investigation and disassembly of the wreckage. The parts selected for teardown and analysis were removed and secured at the 79th Maintenance Company (DS) at Tuy Hoa AAF, RVN. The crewmembers were interviewed collectively on 4 June 1971 and after a final check of the maintenance records, the aircraft was released to the Commanding Officer of the 243rd ASHC on 7 Jun 71 for turn-in of parts and disposal of the wreckage.

2. IDENTIFICATION:

- a. Aircraft involved: CH-47A, serial number 64-13116
- b. Personnel involved:

<u>NAME</u>	<u>RANK</u>	<u>SCAN</u>	<u>DUTY</u>	<u>INJURIES</u>
[REDACTED]	CW2	[REDACTED]	IP	Minor
Rex A. Scheib	WO1	479 58 5741	P	Minor
Stanley J. Kearns	SF5	[REDACTED]	PE	Fatal

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

d. Time and Date: 1300(H) local, 31 May 1971

3. DESCRIPTION:

On 31 May 1971, at 0218 hours, Army aircraft OH-4A, serial number 64-13116 departed DTF enroute to Phu Hiep, RVN on a routine re-supply mission in support of the 28th Regiment, 9th AKA Infantry Division. Upon stopping at the 9th Division Pad in Binh Hoa, a squeal was noted in the SAS system, but after recycling the system the squeal disappeared, and the aircraft on-loaded 15 passengers. Aircraft #116 continued its flight to Tuy Hoa AB, dropped off two passengers and refueled at the OH-47 POL point. Returning to the 28th RCF, the aircraft discharged 15 passengers, picked up the Korean liaison NCO, and began its mission. After hauling five slingloads of supplies, aircraft #116 returned to the Tuy Hoa POL point for refueling, and then carried an additional five slingloads. Returning to Tuy Hoa at approximately 1230 hours, the aircraft was again refueled from the same POL point, and the crew prepared to return to Phu Hiep to carry the last two loads of the day. With WO1 Scheib at the controls, a hover check was made which indicated approximately 440 lbs of torque, and WO1 Scheib then departed to the south enroute to Phu Hiep. WO1 Scheib made an approach to a hover in alignment with the landing strip at the RCF (160) and hovered left to the resupply pad to pick up the load. The load consisted of several boxes of supplies (unmarked) a loaded fuel bladder, and a large water container in three separate slings, weighing a total of approximately 6000 lbs. After lifting the three slings (approximately 30' long) 40 - 50 feet clear of the ground, WO1 Scheib made a right pedal turn to align the aircraft with the takeoff heading and make a hover check. The hover check indicated that #1 engine had 90.5% N<sub>1</sub> at 5/0 lbs of torque. WO1 Scheib then began the takeoff by making a slight cyclic/pedal turn to the right and then to the left to align the aircraft with the cleared path (240°) which is normally used for takeoff to avoid buildings in case of a dropped load. As the aircraft entered translational lift at approximately 20 - 30 knots and 100', the #2 engine failed, causing the rotor rpm to drop and the aircraft to begin to settle. CW2 [redacted] took control of the aircraft, noted that the #2 engine N<sub>1</sub> decreased through 55%, and instructed the flight engineer to release the load (WO1 Scheib also activated his cyclic release button at this time). The load dropped approximately 30 feet to the ground, causing the fuel and water container to burst. At load release (approximately 60' altitude), CW2 [redacted] noted the #1 engine reach 780 lbs of torque and then decrease rapidly. The aircraft lurched slightly forward and assumed a nose high attitude. CW2 [redacted] was unable to lower the thrust control and states that the cyclic traveled rearward in three short, rapid movements to the full aft position against his control pressures. With rotor rpm continuing to deteriorate, the aircraft struck a 9' high sand berm which was covered with concertina wire. The left aft gear dug an 18" hole in the berm, causing the gear strut upper attaching point to fail. Simultaneously, the aft rotor system contacted two fence posts on the berm, causing two 9' 6" sections from separate aft blades to separate from the aircraft. The aft section of the aircraft again became airborne and pivoted counter-clockwise around the forward rotor system, which was already in contact with the ground. The fuselage of the aircraft impacted vertically on its right side on the inner perimeter fence of the 28th RCF, detonating at least one claymore mine and two trip flares. Fire was instantaneous on impact of the aft section. The pilot exited through the right cockpit jettisonable door which had opened on impact, followed by the instructor pilot and the crewchief. The gunner exited either through this door or the right chin bubble. The flight engineer, who was in the vicinity of the bottom hatch, and the Korean liaison NCO, who was sitting in a troop seat beside the hatch, were thrown towards the rear of the aircraft when it entered the nose-high configuration, and were not seen by any member of the crew after impact. After clearing the aircraft, the instructor pilot immediately went to a phone and notified 28th Aviation Liaison operations and procured medevac assistance. The fire consumed the entire aircraft within five minutes/

"FOR OFFICIAL USE ONLY"

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

4. Investigation:

a. The investigation of this accident was conducted as follows:

1. 1 June 1971- Initial site and wreckage investigation.
2. 2 June 1971- Individual crewmember interviews.
3. 3 June 1971- Final site and wreckage investigation.
4. 4 June 1971- Collective crewmember interview.
5. 1-4 June 1971- Maintenance check.
6. 4 June 1971- Aircraft released to the 243rd ASHC for turn in of parts tear-down/analysis and disposition of wreckage.

b. General: Prior to the arrival of the board, the following actions were completed:

1. Fuel sample from Tuy Hoa AAF was turned in for contamination analysis by the 17th CAG Aviation Safety Officer.
2. Crew was examined and released by 8th Army Field Hospital, Tuy Hoa AAF.
3. Fatally injured personnel were removed from the wreckage by the graves registration section, 8th Army Field Hospital.
4. Initial witness statements were taken by the 17th CAG Aviation safety officer.
5. Site security by a U.S. military police/infantry detail was provided by the 17th CAG safety officer.

c. Initial site and wreckage investigations:

1. No reliable map or diagram of the mined perimeter area did exist; after the immediate area was cleared by an EOD team, it was determined from parts and markers and pieces of fuselage that at least one claymore mine and two trip flares were detonated by the aircraft impact and were a factor in the resultant fire.
2. All wreckage was located and suitably diagrammed; 99% of the aircraft was located at the point of main impact.
3. No witnesses to the accident were found; no english-speaking witnesses existed; and no Korean-speaking personnel could relate a coherent account which would indicate that they actually observed the accident sequence.
4. The aircraft fuselage impacted vertically on its right side.
5. The slingload showed very little evidence of forward speed and impacted vertically on a hard surface, bursting the fuel and water containers; the supply boxes were unmarked and their contents had already been removed.
6. The intense fire after impact burned aluminum and magnesium parts and caused severe material and structural deformation; no evidence of fire prior to impact was found or reported.
7. No remains of the aircraft log book could be found.
8. The remains of all weapons reported to be on board were found and recovered.
9. Both engines were intact and inspection indicated that neither was developing power at impact; #2 engine was not operating; #1 engine showed possible evidence of very very low or no turbine RPM at impact; #1 engine fuel control actuators: n1-full open, n2-76%; #2 engine fuel control actuators: n1-full open, n2-72%.
10. All blade structures were in the immediate area of the impact and suffered extensive damage; all blades indicated very low rotor RPM at impact. The front rotor system stopped turning first and the aft blades separated from the rotor head at the attaching points; no evidence of blades colliding or striking the fuselage was found; the position of the two separated aft 9' 6" blade sections indicated that they separated from the rotor system in the vicinity of the first impact prior to the main impact of the aircraft.
11. All main drive train gears and couplings that remained showed no evidence of failure; the second forward drive shaft section showed a torque failure,

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

Caused by the sudden stoppage of the front rotor system at impact; the aft rotor head shorn of blades, continued to turn after impact; there was a three foot deep hole dug by the aft rotor head.

12. The fuel system crossfeed valve was found in a closed position; the #2 engine fuel shutoff valve was found in the open position; only the motor for the #1 engine fuel shutoff valve was found.

d. Individual crew member interviews:

1. Some confusion existed among the crew as to the crash/impact sequence, due to their respective locations, division of attention, and the rapidity of impact after the initial failure.

2. The parts (3/8 bolt, nut, pieces of shrapnel, rivets, cotter keys, washers) found on preflight were not identifiable as coming from the section of the aircraft in which they were found or any other specific area. It was determined that these foreign objects did not contribute to this mishap.

3. [REDACTED]

4. [REDACTED]

5. [REDACTED]

6. [REDACTED]

7. [REDACTED]

8. [REDACTED]

9. CW2 Moree [REDACTED]

10. CW2 Moree [REDACTED]

*From confidential witness statements  
deleted TAW Ex. 5, FOIA*

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

d. 11.

[REDACTED]

12.

[REDACTED]

13.

[REDACTED]

14.

[REDACTED]

e. Final site and wreckage investigation:

1. The aircraft data plate and the data plates of both engines were recovered. #1 engine data plate indicated n1 topping 97.2% and #2 engine data plate indicated n1 topping at 95.4%
2. Most fuel system components in the right fuel tank were recovered in good condition and were set aside for tear down/analysis
3. As the #2 engine was being removed from the wreckage, the fuel control unit, which had significant fire damage, became partially disassembled. Close inspection of the unit indicated that the n1 governor driveshaft (FSN 2915-963-0978, P/N 02-13920) showed excessive wear on the small gear splines. Although this shaft showed no indication of heat or fire damage or dynamic failure, the gear splines were worn nearly smooth on the shaft to a degree sufficient to cause booster pump failure, apparently through normal wear factors. The unit was set aside for teardown/analysis.
4. #1 engine was largely intact and showed no apparent external cause or effect of failure.
5. Both engines and several other components (listed in TAB 10, Aircraft Release) were removed from the wreckage at this time and secured at the 79th Maint Co (DS) at Tuy Hoa AAF for turn-in for teardown and analysis.

f. Collective Crewmember interviews:

1.

2.

3.

[REDACTED]

g. Maintenance Records check:

1. All prior oil and hydraulic samples were normal.
2. All prior D.E.R. checks were normal.

For use of this form, see AR 385-40 and AR 95-5; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

SECTION G - NARRATIVE OF ACCIDENT

NARRATIVE ACCOUNT OF INVESTIGATION (Use format shown in "Reporting Procedures", AR 95-5. Use continuation sheets as necessary.)

- g. (continued)
  - 3. The DA 2408-14 forms and DA 2408-19 forms for the aircraft were in the log-book which was burned in the aircraft.
  - 4. Fuel control unit, SN: 52257, was installed on #1 engine (SN: LEO 4957) and had 1898 hours since it was new with no overhauls.
  - 5. Fuel control unit, SN: 41441, was installed on #2 engine (SN: LEO 4918) and had 911 hours since overhaul. It is known that the unit was only overhauled once but time since new is unknown due to a missing DA 2404-5 form.
  - 6. The part number of the a/t transmission was 114D 2200-5.

h. Other:

- 1. The upper flight control boost actuators on both rotor heads were found intact in the wreckage and measurements of all actuators were taken. On 2 June 1971, Mr Robert Heady, AVSCOM representative and the 243rd ASHC maintenance officer attempted to duplicate the measured upper boost extensions on a CH-47A SN: 65-8021, in order to determine relative cockpit control positions. The following is the best approximation obtained:

64-13116:	simulated 65-8021:
Forward pivoting actuator (rt) 4 1/4"	Extension 4 3/4"
Forward pivoting actuator (lt) 8 7/8"	Extension 9 1/4"
AFT pivoting actuator (lt) 6 1/2"	Extension 5 3/4"
AFT pivoting (swivel) (rt) 9 16/32"	Extension 9 16/32"

From these dimensions, the cockpit controls were found to be:

- a. Cyclic- 2 1/2" forward (trim indicator)
- b. Thrust- centered (7 1/2" up)
- c. Pedals 3 3/8" rt (c/l to c/l)

- 2. The lower flight control boost actuators were found burned but intact in the wreckage, but no identification was possible from their position only the pitch actuator could be identified by serial number from historical records. By matching the remaining actuators, these substantiate the positions in 4h/1 above, with two exceptions. The actuator which is thought to be the roll actuator indicates a full right cyclic position, and the identified pitch actuator indicates an aft cyclic position.

- 3. No useable information could be determined from the cockpit controls or instruments due to crash damage and fire.

- 4. The results of the fuel contamination sample from Tuy Hoa ABF were negative and no aircraft reported contamination problems from this FOL point on this date.

5. Analysis:

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

[REDACTED]

Analysis deleted IAW Ex. 5, FOIA

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

PART I

(AR 65-5 and AR 385-40)

MAJOR  
 MINOR

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

TO: (Headquarters of Reviewing Authority)

Commanding General  
HQ, USARV  
APO 96375

THRU: (Organization of Reviewing Official)

Commanding Officer  
10th CAB  
APO 96377

FROM: (Organization Submitting Accident Report)

Commanding Officer  
243rd ASHC  
APO 96377

SECTION A - LOCATION AND TIME

1. a. DATE OF ACCIDENT: 31 May 1971  
b. TIME OF ACCIDENT (Local): 1300 (H)  
2. DISTANCE AND DIRECTION FROM NEAREST MILITARY INSTL: at the 28th ROKA RCP, Phu Hiep, RVN  
3. PLACE OF ACCIDENT (State, Foreign Country, Town, Distance and Direction): 48P CQ 2523 Phu Hiep, RVN  
4. ACCIDENT OCCURRED:  
 DAWN  DAY  
 DUSK  NIGHT

SECTION B - AIRCRAFT

1. TYPE, MODEL AND VARIANTS: CH-47A  
2. AIRCRAFT SERIAL NUMBER: 64-13116  
3. INSTL WHERE AIRCRAFT ASSIGNED: 243rd ASHC, Dong Ba Thin, RVN  
4. ORGANIZATION UNDER WHOSE CONTROL THE AIRCRAFT WAS OPERATING: 243rd ASHC, APO 96377  
5. WHAT WAS MISSION?  
 SERVICE  COMBAT  
 TRAINING  TEST FLIGHT  
 OTHER (Specify)

SECTION C - WEATHER

WEATHER  WAS  WAS NOT CONSIDERED A FACTOR IN THIS ACCIDENT.  
A WEATHER REPORT IS INCLUDED UNDER TAB. 3

SECTION D - AIRPORT AND/OR AIRWAY FACILITIES

(Use this section if the airport, its facilities, or airway facilities were a factor or contributing factor in the accident.)

BRIEF EXPLANATION OF CIRCUMSTANCE

N/A

"FOR OFFICIAL USE ONLY"

SECTION E - PERSONNEL INVOLVED

1. NUMBER OF AIRCRAFT OCCUPANTS INVOLVED	MILITARY		CIVILIAN			
	5 US 1 ROKA					
2. NUMBER OF BYSTANDERS INVOLVED	0		0			
3. NUMBER OF PEOPLE INJURED (By type classification shown)	NO INJURY	MINOR	MAJOR	FATAL	UNKNOWN	MISSING
a. MILITARY OCCUPANTS OF AIRCRAFT	0	4 US	0	1 US, 1 ROKA	0	0
b. OTHER OCCUPANTS OF AIRCRAFT	0	0	0	0	0	0
c. MILITARY BYSTANDERS	0	0	0	0	0	0
d. OTHER BYSTANDERS	0	0	0	0	0	0

DA FORM 2397-1  
JUN 66

REPLACES DA FORM 2397-1, 1 APR 61, WHICH IS OBSOLETE  
EFFECTIVE 1 JAN 67.

FFG-Japan

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT  
 PART I (Continuation)  
 (AR 95-5 and AR 385-40)

REPORTS CONTROL SYMBOL  
 CSFOR-3(RI)

SECTION F - OPERATOR  
 (If additional space is required, use a blank sheet and identify it as Part I, Section F.)

1. NAME (Last, First, Middle Initial)			2. GRADE/RANK	3. SERVICE NO.
[REDACTED]			GW 2	[REDACTED]
4. BRANCH OF SERVICE (Army, Navy, National Guard, etc.)	5a. PRESENT AERONAUTICAL RATING		6. DATE RECEIVED	8. CREW DUTY AT TIME OF ACCIDENT
Army	ARAV		15 Jul 69	IP
7a. TYPE INSTRUMENT RATING	5b. EXPIRATION DATE	8. TIME AT CONTROLS THIS FLIGHT	12a. NO. OF PREVIOUS ACCIDENTS	5. DATES
R/W TAC	8 Jun 72	3.5		
9. NO. LANDINGS THIS FLIGHT	10. NO. DUTY HOURS LAST 24 HOURS	11. NO. HOURS FLOWN LAST 24 HOURS	0	
6	13.0	3.5		
13. OPERATOR'S FLYING EXPERIENCE (List all flight time to nearest hour)			PILOT	CO-PILOT
a. TOTAL FLYING HOURS (Army, Student, Accredited Time)				
FIXED WING HOURS				
LAST 6 MONTHS				
LAST 30 DAYS				
ROTARY WING HOURS				
LAST 6 MONTHS				
LAST 30 DAYS				
b. HOURS THIS TYPE MODEL AIRCRAFT				
LAST 6 MONTHS				
LAST 30 DAYS				
c. WEATHER/HOOD HOURS (All aircraft)				
LAST 6 MONTHS				
LAST 30 DAYS				
d. NIGHT HOURS (All aircraft)				
LAST 6 MONTHS				
LAST 30 DAYS				

14. AVIATION SCHOOLS ATTENDED AND DATE GRADUATED

WORMAC 15 Jul 69

CH 47 PTC 16 Sept 69

IP-PTC CH 47 4 Feb 71

"FOR OFFICIAL USE ONLY"

15. INITIAL TRAINING THIS TYPE, MODEL AIRCRAFT (List date of training, organization and number of flight hours)

In country orientation - 24 Feb 71, 3.4 hrs., 243 ASHC

A/C checkride - 26 Feb 70, (IP check), 1.4 Hrs., 243 ASHC

90 day stan. ride - 7 May 71, 2.4 hrs, 243 ASHC

NOTE: If other pilots were logging time on this flight, complete individual sheets for each pilot.



PERSONAL DATA

INSTRUCTIONS: For each aircraft accident, complete for each aviator at the controls of the aircraft involved. Information provided by this form is to be used for an interim study pending revision of regulations. It replaces information of Section F, Crew Experience, USARV Form 232, dated 16 September 66, and Items 6 through 8 and 10 through 13 of DA Form 2397-2, dated July 1966. Forward as per instructions pertinent to USARV Form 232 and DA Form 2397.

1. ROLE OF THIS INDIVIDUAL IN THE CAUSE OF THE MISHAP:

- A. PRIMARY ROLE  
 1. DEFINITE  2. PROBABLE  3. POSSIBLE  4. DEFINITE  5. PROBABLE  6. POSSIBLE  7. NONE  8. UNK

2. FLYING EXPERIENCE	ROTOR WING	FIXED WING
	A. TOTAL FLYING HOURS (include Army, student and other accredited time)	1492
B. ALL AIRCRAFT, TOTAL HOURS (military only)	1492	
1ST PILOT	431	
INSTRUCTOR PILOT	156	
AIRCRAFT COMMANDER	598	
WEATHER INSTRUMENT, HOOD	67	
NIGHT	46	
LAST 30 DAYS	59.6	
LAST 90 DAYS	191.8	
C. THIS MODEL, INCLUDE 1ST PILOT, INSTRUCTOR PILOT, AND AIRCRAFT COMMANDER HOURS FLOWN:		
LAST 30 DAYS	59.6	
LAST 90 DAYS	191.2	
D. TOTAL HOURS, THIS MODEL	1260	
E. THIS MODEL, HOURS FLOWN AS:	448	
1ST PILOT	156	
INSTRUCTOR PILOT	598	
AIRCRAFT COMMANDER	26	
WEATHER INSTRUMENTS, HOOD	26	
NIGHT		
F. DATE OF MOST RECENT FLIGHT, THIS MODEL PRIOR TO THIS MISHAP	30 May 71	
G. DURATION OF MOST RECENT FLIGHT, THIS MODEL PRIOR TO THIS MISHAP	0.5	
H. DATE OF LAST PROFICIENCY CHECK, THIS MODEL	7 May 71	

3. INDICATE INSTRUMENT FLIGHT QUALIFICATIONS:

- A.  R/W TACTICAL D.  F/W STANDARD G.  EXPIRED-E.G. RVN WAIVER  
 B.  R/W STANDARD E.  F/W SPECIAL H.  NONE  
 C.  R/W SPECIAL F.  EXAMINER

4. COMBAT AREA EXPERIENCE

- A. THIS TOUR, NUMBER OF MONTHS IN COUNTRY 3.5  
 B. TOTAL HRS FLOWN THIS TOUR 253 R/W \_\_\_\_\_ F/W \_\_\_\_\_  
 C. TOTAL COMBAT FLYING HRS 1137 R/W \_\_\_\_\_ F/W \_\_\_\_\_

5. BACKGROUND DATA

- |   |   |  |  |
|---|---|--|--|
| A. DATE OF BIRTH <u>[REDACTED]</u>                    | E. DATE OF LAST AIRCREW DUTY <u>30 May 71</u>       | G. HOURS CONTINUOUSLY AWAKE PRIOR TO MISHAP <u>7.0</u>                 |  |
| B. DATE LAST LEAVE ENDED <u>31 Nov 70</u>             | F. HOURS FLOWN IN LAST 24 HOURS <u>4.0</u>          | H. HOURS DURATION OF LAST SLEEP PERIOD <u>7.5</u>                      |  |
| C. DAYS DURATION LAST LEAVE <u>30</u>                 | G. HOURS FLOWN IN LAST 48 HOURS <u>4.0</u>          | I. TIME IN COCKPIT PRIOR TO FLIGHT: <u>00+15</u> HOURS*                |  |
| D. TYPE OF LAST LEAVE TAKEN                           | H. FLIGHTS/SORTIES FLOWN LAST 24 HRS <u>2/10</u>    | J. DURATION THIS FLIGHT: <u>3.5</u> HOURS*                             |  |
| 1. ORDINARY <input checked="" type="checkbox"/>       | I. FLIGHTS/SORTIES FLOWN LAST 48 HRS <u>2/10</u>    | K. DUTY HOURS REMAINING THIS DAY, HAD NOT ACCIDENT OCCURRED <u>5.0</u> |  |
| 2. EMERGENCY <input type="checkbox"/>                 | J. HOURS WORKED IN LAST 24 HOURS <u>13.0</u>        | *Hours to nearest tenth  |  |
| 3. REENLISTMENT <input type="checkbox"/>              | K. HOURS WORKED IN LAST 48 HOURS <u>21.0</u>        |  |  |
| 4. GRADUATION <input type="checkbox"/>                | L. HOURS SLEPT IN LAST 24 HOURS <u>7.5</u>          |  |  |
| 5. SICK OR CONVALESCENT <input type="checkbox"/>      | M. HOURS SLEPT IN LAST 48 HOURS <u>12.0</u>         |  |  |
| 6. DELAY EN ROUTE <input checked="" type="checkbox"/> | N. HOURS CONTINUOUS DUTY PRIOR TO MISHAP <u>7.0</u> |  |  |
| 7. REST & RELAXATION (R&R) <input type="checkbox"/>   |   |  |  |
| 8. UNKNOWN <input type="checkbox"/>                   |   |  |  |

6. NUMBER AND TYPE OF PRIOR MISHAPS (for past 12 months)

- |                              |                              |                   |                         |                                |                  |  |
|------------------------------|------------------------------|-------------------|-------------------------|--------------------------------|------------------|--|
| A. MAJOR ACCIDENT <u>N/A</u> | B. MINOR ACCIDENT <u>N/A</u> | C. INCIDENT _____ | D. FORCED LANDING _____ | E. PRECAUTIONARY LANDING _____ | F. UNKNOWN _____ | G. DATE OF MOST RECENT OCCURRENCE <u>22</u> DAY <u>Apr</u> MO <u>71</u> YR   |
|                              |                              |                   |                         |                                |                  | AND TYPE: A. <input type="checkbox"/> B. <input type="checkbox"/> C. <input type="checkbox"/> D. <input type="checkbox"/> E. <input checked="" type="checkbox"/> |

7. LIST REMARKS OR CONTINUATION OF ABOVE:

NAME/RANK

SERIAL/SSA NUMBER

DUTY ABOARD AIRCRAFT  
IP

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

PART I (Continuation)  
AR 95-5 and AR 185-40

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

SECTION F - OPERATOR

(If additional space is required, use a blank sheet and identify it as Part I, Section F.)

1. NAME (Last, First, Middle Initial) <b>Scheib, Rex A.</b>		2. GRADE/RANK <b>WO1</b>	3. SERVICE NO. <b>479-58-5741</b>
4. BRANCH OF SERVICE (Army, Navy, National Guard, etc.) <b>ARMY</b>	5. PRESENT AERONAUTICAL RATING <b>ACAV</b>	6. DATE RECEIVED <b>26 Jan 71</b>	7. CREW RITY AT TIME OF ACCIDENT <b>Pilot</b>
7a. TYPE INSTRUMENT RATING <b>R/W AAC</b>	8. EXPIRATION DATE <b>22 Jan 72</b>	9. TIME AT CONTROLS THIS FLIGHT <b>3.5</b>	10. NO. OF PREVIOUS ACCIDENTS <b>0</b>
9. NO. LANDINGS THIS FLIGHT <b>6</b>	10. NO. DUTY HOURS LAST 24 HOURS <b>13.0</b>	11. NO. HOURS FLOWN LAST 24 HOURS <b>4.0</b>	

13. OPERATOR'S FLYING EXPERIENCE (List all flight time to nearest hour)	PILOT	CO-PILOT	INSTRUMENT PILOT	TOTAL HOURS
a. TOTAL FLYING HOURS (Army, Student, Accredited Time)				
FIXED WING HOURS				
LAST 6 MONTHS				
LAST 30 DAYS				
ROTARY WING HOURS				
LAST 6 MONTHS				
LAST 30 DAYS				
b. HOURS THIS TYPE MODEL AIRCRAFT				
LAST 6 MONTHS				
LAST 30 DAYS				
c. WEATHER/HOOD HOURS (All aircraft)				
LAST 6 MONTHS				
LAST 30 DAYS				
d. NIGHT HOURS (All aircraft)				
LAST 6 MONTHS				
LAST 30 DAYS				

14. AVIATION SCHOOLS ATTENDED AND DATE GRADUATED

WCOMAC 26 Jan 1971 and Transition  
OH 47 AQC 24 Mar 1971

"FOR OFFICIAL USE ONLY"

15. INITIAL TRAINING THIS TYPE MODEL AIRCRAFT (List date of training, organization and number of flight hours)

In country check ride - Due after first 25 hours with 1r.  
In country orientation- 17 May 71, 4.0 hrs, 243 AHC  
A/G check ride- N/A  
90 day stan. ride- N/A

NOTE: If other pilots were logging time on this flight, complete individual sheets for each pilot.

PERSONAL DATA

INSTRUCTIONS: For each aircraft accident, complete for each aviator at the controls of the aircraft involved. Information provided by this form is to be used for an interim study pending revision of regulations. It replaces information of Section F, Crew Experience, USARV Form 232, dated 16 September 66, and items 6 through 8 and 10 through 13 of DA Form 2397-2, dated July 1966. Forward as per instructions pertinent to USARV Form 232 and DA Form 2397.

1. ROLE OF THIS INDIVIDUAL IN THE CAUSE OF THE MISHAP:

A. PRIMARY ROLE  
 1. DEFINITE  2. PROBABLE  3. POSSIBLE  4. DEFINITE  5. PROBABLE  6. POSSIBLE  7. NONE  8. UNK

B. CONTRIBUTING CAUSE  
 1. DEFINITE  2. PROBABLE  3. POSSIBLE  4. DEFINITE  5. PROBABLE  6. POSSIBLE  7. NONE  8. UNK

2. FLYING EXPERIENCE

	ROTARY WING	FIXED WING
A. TOTAL FLYING HOURS (include Army, student and other accredited time).....	284	7
B. ALL AIRCRAFT, TOTAL HOURS (military only).....	277	
1ST PILOT.....	44	
INSTRUCTOR PILOT.....	---	
AIRCRAFT COMMANDER.....	---	
WEATHER INSTRUMENT, HOOD.....	16.5	
NIGHT.....	20.0	
LAST 30 DAYS.....	3.0	
LAST 90 DAYS.....	55.0	
C. THIS MODEL, INCLUDE 1ST PILOT, INSTRUCTOR PILOT, AND AIRCRAFT COMMANDER HOURS FLOWN:		
LAST 30 DAYS.....	0.0	
LAST 90 DAYS.....	32.6	
D. TOTAL HOURS, THIS MODEL.....	72.0	
E. THIS MODEL, HOURS FLOWN AS:	32.6	
1ST PILOT.....	---	
INSTRUCTOR PILOT.....	---	
AIRCRAFT COMMANDER.....	---	
WEATHER INSTRUMENTS, HOOD.....	---	
NIGHT.....	6.0	
F. DATE OF MOST RECENT FLIGHT, THIS MODEL PRIOR TO THIS MISHAP.....	30 May 71	
G. DURATION OF MOST RECENT FLIGHT, THIS MODEL PRIOR TO THIS MISHAP.....	0.5	
H. DATE OF LAST PROFICIENCY CHECK, THIS MODEL.....	17 May 71	

3. INDICATE INSTRUMENT FLIGHT QUALIFICATIONS:

A.  R/W TACTICAL D.  F/W STANDARD G.  EXPIRED-E.G. RVN WAIVER  
 B.  R/W STANDARD E.  F/W SPECIAL H.  NONE  
 C.  R/W SPECIAL F.  EXAMINER

4. COMBAT AREA EXPERIENCE

A. THIS TOUR, NUMBER OF MONTHS IN COUNTRY 1  
 B. TOTAL HRS FLOWN THIS TOUR 8.0 R/W --- F/W  
 C. TOTAL COMBAT FLYING HRS 8.0 R/W --- F/W

5. BACKGROUND DATA

A. DATE OF BIRTH 22 Jul 50 E. DATE OF LAST AIRCREW DUTY 30 May 71 O. HOURS CONTINUOUSLY AWAKE PRIOR TO MISHAP 7.0  
 B. DATE LAST LEAVE ENDED 1 May 71 F. HOURS FLOWN IN LAST 24 HOURS 4.0 P. HOURS DURATION OF LAST SLEEP PERIOD 6.0  
 C. DAYS DURATION LAST LEAVE 35 G. HOURS FLOWN IN LAST 48 HOURS 4.0 Q. TIME IN COCKPIT PRIOR TO FLIGHT: 00+15 HOURS\*  
 D. TYPE OF LAST LEAVE TAKEN  ORDINARY  EMERGENCY  REENLISTMENT  GRADUATION  SICK OR CONVALESCENT  DELAY EN ROUTE  REST & RELAXATION (RARI)  UNKNOWN   
 H. FLIGHTS/SORTIES FLOWN LAST 24 HRS 2/10 I. FLIGHTS/SORTIES FLOWN LAST 48 HRS 2/10 R. DURATION THIS FLIGHT: 3.5 HOURS\*  
 J. HOURS WORKED IN LAST 24 HOURS 13.0 K. HOURS WORKED IN LAST 48 HOURS 21.0 S. DUTY HOURS REMAINING THIS DAY, HAD NOT ACCIDENT OCCURRED 5.0  
 L. HOURS SLEPT IN LAST 24 HOURS 3.0 M. HOURS SLEPT IN LAST 48 HOURS 13.0 N. HOURS CONTINUOUS DUTY PRIOR TO MISHAP 7.0  
 \*Hours to nearest tenth

6. NUMBER AND TYPE OF PRIOR MISHAPS (for past 12 months)

	F/W	R/W	F/W	R/W
A. MAJOR ACCIDENT.....	1/A	1/A		
B. MINOR ACCIDENT.....				
C. INCIDENT.....				
D. FORCED LANDING.....				
E. PRECAUTIONARY LANDING.....				2
F. UNKNOWN.....				
G. DATE OF MOST RECENT OCCURRENCE <u>9 May</u> MO <u>71</u> YR				
H. AND TYPES: A. <input type="checkbox"/> B. <input type="checkbox"/> C. <input type="checkbox"/> D. <input type="checkbox"/> E. <input checked="" type="checkbox"/>				

7. LIST REMARKS OR CONTINUATION OF ABOVE:

"FOR OFFICIAL USE ONLY"

NAME/RANK Scheib, Rex A. SERIAL/SSA NUMBER 500-26-5741 DUTY ABOARD AIRCRAFT Pilot

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

PART I (Continuation)  
(AR 95-5 and AR 385-40)

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

SECTION H - WITNESS STATEMENT

NAME OF WITNESS [REDACTED] OCCUPATION Instructor Pilot AGE 31

ADDRESS (Include ZIP Code) 243D Assault Support Helicopter Company ARU 96377 TELEPHONE NUMBER Dong Sa Thin 243, 175 DATE OF ACCIDENT 31 May 1971 DATE STATEMENT MADE 2 June 1971

AVIATION EXPERIENCE AND BACKGROUND 16 Months in country INTERVIEWER CPT John L. Shanahan, Jr.

THIS STATEMENT MAY NOT BE USED AS EVIDENCE OR TO OBTAIN EVIDENCE IN DETERMINING LINE OF DUTY STATUS OF ANY PERSONNEL; AS EVIDENCE BEFORE EVALUATION BOARDS; AS EVIDENCE TO DETERMINE LIABILITY IN CLAIMS AGAINST THE GOVERNMENT; OR AS EVIDENCE TO DETERMINE PECUNIARY LIABILITY. THE SOLE PURPOSE OF THIS STATEMENT IS TO AID IN THE PREVENTION OF ACCIDENTS. (Reference Section I, Paragraph 4, AR 385-40)

Having been advised by CPT John L. Shanahan, Jr, Aircraft Investigating Officer that he has no authority to compel me to give a statement regarding my knowledge of the aircraft accident of 31 May 1971, involving the US Army aircraft 64-13116 and having been advised that I may elect to make a statement which will be used only by the Department of the Army Safety Personnel for the sole purpose of accident prevention. I elect to make a statement in confidence, without this promise I would not make this statement. I understand that the confidential status of this statement means that it will not be used as evidence to obtain evidence to determine misconduct or line of duty status, as evidenced before an evaluation board, or to determine pecuniary liability in claims involving the government or any other party.

[REDACTED]

Confidential witness statements deleted IAW Ex. 5, FOIA

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

PART I (Continuation)  
(AR 95-3 and AR 385-40)

SECTION H - WITNESS STATEMENT

NAME OF WITNESS	OCCUPATION	AGE
Schieb, Rex A.	Pilot	20
ADDRESS (Include ZIP Code)	TELEPHONE NUMBER	DATE OF ACCIDENT
243rd Assault Support Helicopter Company APO 96377	Dong Ba Thin 243, 175	31 May 1971
AVIATION EXPERIENCE AND BACKGROUND	INTERVIEWER	DATE STATEMENT MADE
284 hours	CPT John L. Shanahan, Jr.	2 June 1971

THIS STATEMENT MAY NOT BE USED AS EVIDENCE OR TO OBTAIN EVIDENCE IN DETERMINING LINE OF DUTY STATUS OF ANY PERSONNEL; AS EVIDENCE BEFORE EVALUATION BOARDS; AS EVIDENCE TO DETERMINE LIABILITY IN CLAIMS AGAINST THE GOVERNMENT; OR AS EVIDENCE TO DETERMINE PECUNIARY LIABILITY. THE SOLE PURPOSE OF THIS STATEMENT IS TO AID IN THE PREVENTION OF ACCIDENTS. (Reference Section I, Paragraph 4, AR 385-40)

Having been advised by CPT John L. Shanahan, Jr., Aircraft Investigating officer that he has no authority to compel me to give a statement regarding my knowledge of the aircraft accident of 31 May 1971, involving US Army aircraft 64-13116 and having been advised that I may elect to make a statement which will be used only by the Department of the Army Safety Personnel for the sole purpose of accident prevention. I elect to make a statement in confidence, without this promise I would not make this statement. I understand that the confidential status of this statement means that it will not be used as evidence before flight evaluation boards, or to determine pecuniary liability in claims involving the government or any other party.

*Rex A. Schieb*  
Rex A. Schieb

On the morning of 31 May, I got up at 0600 hours, went and ate, and then into operations at 0645. I filled out the 1080 and CW2 Moree and I went to the aircraft (116) for our preflight. We made a very thorough pre-flight. I say this because I found some old rivets laying in the forward pylon where the driveshaft is and I also found a nut lying between some hydraulic lines under the first tunnel cover. I showed them to CW2 Moree and he personally inspected everything under the tunnel cover and he found a bolt about 3/4" long. This didn't make us very happy and we knew we would have to pull a very thorough pre-flight. Then we went into the cockpit and went through our run-up and everything was OK. We took-off at approximately 0815 with a crew of five and two Red Cross workers. We stopped at division pad in Ninh Hoa and picked up some more passengers and started our sling load missions. All morning everything was fine and I did not detect anything wrong. We refueled at Tuy Hoa every time and at approximately 1230 hours we refueled for the last time. We proceeded back to RCP for more sling loads and then we would be through with our mission. I was flying the aircraft and picked up a sling load about 30' from the bottom of the aircraft. I turned in the direction of take-off and CW2 Moree read off the power readings. Approximately 600 lbs of torque and I think 90 or 91% on each engine. I then proceeded with my take-off down a little dirt road in the compound and approximately 75 or 100' off the ground when the #2 engine quit. CW2 Moree took the controls and told the flight engineer who was in the hole to punch the load. At almost the same time CW2 Moree took control of the aircraft the #1 engine quit. I think the load dragged on the ground for a second before we could get it punched off. I also punched my button after the chief punched his just to make sure it released. At this time we were about 25' feet off the ground. The aircraft attitude was almost level then we seemed to pitch forward and then back. By this time we hit the ground tail low and I thought I saw a berm or a built up area which I thought hit the belly and then we rolled to the right. The rotor blades started beating themselves on the ground and the aircraft felt like it was going to break into pieces. Sometime during all this my door broke out and there was a hole on my side. The ship was laying on its right side and after everything stopped I unbuckled my seat belt and crawled out through my door. CW2 Moree was right behind me, then Martin and Hood. When I got out I ran around the front of the aircraft to see if I could get to the back to see if the other guys were getting out. The bottom of the aircraft was all in flames from the hole on back so I knew there nothing I could do and we all ran from the aircraft in fear if it blowing up and that was the end. The whole ship was soon engulfed in flame and ammunition started exploding. The flight engineer, SP5 Kearns and a Korean were left in the aircraft.

"FOR OFFICIAL USE ONLY"

Witness Statement of WO1 Rex A. Schieb continued

- Q. How much fuel did you have after refueling at Tuy Hoa? A. 4000 lbs.
- Q. Before the accident was the aircraft operating normally? A. Yes.
- Q. What were the hover check readings at Tuy Hoa? A. About 400 lbs torque.
- Q. What did you do with your hands after punching the release? A. I braced them against the windshield crossmembers and grabbed the bar on the door.
- Q. Did you see any warning lights or remember any instrument readings after the #2 engine failed? A. No, I was looking at the ground ahead of the aircraft.
- Q. How low was the rotor RPM? A. I don't know, but I could see by the blades that it was declining rapidly and was very low.
- Q. Do you have any knowledge of flight control problems? A. Not other than what CW2 Moree said: I wasn't at the controls.
- Q. Did you see what position the controls were in? A. No I was looking outside.
- Q. Did you know if there was any fire before impact? A. No, I don't know of any.
- Q. Did you hear any explosions at or after impact? A. No, Just the sound of the aircraft hitting the ground and breaking up.
- Q. Could you tell if the parts found on the preflight came from any specific area? A. No, they were just left laying there.
- Q. Did you have any other problems with the aircraft? A. Only a squeal in the SAS system at Ninh Hoa; we recycled the SAS system and made a full check and it went away.
- Q. Were any movements of the cyclic or thrust made after impact or while exiting the aircraft? A. I don't remember.       END

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)


PART I (Continuation)  
(AR 95-3 and AR 385-40)

SECTION H - WITNESS STATEMENT

NAME OF WITNESS [REDACTED]		OCCUPATION Crew Chief		AGE 21
ADDRESS (Include ZIP Code) 243rd Assault Support Helicopter Company AIO 96377		TELEPHONE NUMBER Don, Ba Thin 243, 175	DATE OF ACCIDENT 31 May 1971	
AVIATION EXPERIENCE AND BACKGROUND 13 months as crewchief/Flight engineer		INTERVIEWER CPT John L. Shanahan Jr.		

THIS STATEMENT MAY NOT BE USED AS EVIDENCE OR TO OBTAIN EVIDENCE IN DETERMINING LINE OF DUTY STATUS OF ANY PERSONNEL; AS EVIDENCE BEFORE EVALUATION BOARDS; AS EVIDENCE TO DETERMINE LIABILITY IN CLAIMS AGAINST THE GOVERNMENT; OR AS EVIDENCE TO DETERMINE PECUNIARY LIABILITY. THE SOLE PURPOSE OF THIS STATEMENT IS TO AID IN THE PREVENTION OF ACCIDENTS. (Reference Section I, Paragraph 4, AR 385-40)

Having been advised by CPT John L. Shanahan Jr., Aircraft Investigating officer that he has no authority to compel me to give a statement regarding my knowledge of the aircraft accident of 31 May 1971, involving US Army aircraft 64-13116 and having been advised that I may elect to make a statement which will be used only by the Department of the Army Safety Personnel for the sole purpose of accident prevention. I elect to make a statement in confidence, without this promise I would not make this statement. I understand that the confidential status of this statement means that it will not be used as evidence before flight evaluation boards, or to determine pecuniary liability in claims involving the government or any other party.



Confidential w. Army statement deleted IAW Ex 5 for

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

PART I (Continuation)  
(AR 95-5 and AR 385-40)

SECTION H - WITNESS STATEMENT

NAME OF WITNESS [REDACTED]	OCCUPATION Gunner	AGE 20
ADDRESS (Include ZIP Code) 243rd Assault Support Helicopter Company APO 96377	TELEPHONE NUMBER Dong Ba Thin 243, 175	DATE OF ACCIDENT 31 May 1971
AVIATION EXPERIENCE AND BACKGROUND 2 and one half months	DATE STATEMENT MADE 2 June 1971	
INTERVIEWER CPT John L. Shanahan Jr.		

THIS STATEMENT MAY NOT BE USED AS EVIDENCE OR TO OBTAIN EVIDENCE IN DETERMINING LINE OF DUTY STATUS OF ANY PERSONNEL; AS EVIDENCE BEFORE EVALUATION BOARDS; AS EVIDENCE TO DETERMINE LIABILITY IN CLAIMS AGAINST THE GOVERNMENT; OR AS EVIDENCE TO DETERMINE PECUNIARY LIABILITY. THE SOLE PURPOSE OF THIS STATEMENT IS TO AID IN THE PREVENTION OF ACCIDENTS. (Reference Section I, Paragraph 4, AR 385-40)

Having been advised by CPT John L. Shanahan Jr, Aircraft investigating officer that he has no authority to compel me to give a statement regarding my knowledge of the aircraft accident of 31 May 1971, involving US Army Aircraft 64-13116 and having been advised that I may elect to make a statement which will be used only by the department of the Army Safety Personnel for the sole purpose of accident prevention. I elect to make a statement in confidence, without this promise I would not make this statement. I understand that the confidential status of this statement means that it will not be used as evidence before flight evaluation boards, or to determine pecuniary liability in claims involving the government or any other party.

[REDACTED]

Confidential witness statement - EAS EX S FOZA

"FOR OFFICIAL USE ONLY"



TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT


PART I (Continuation)  
(AR 95-5 and AR 385-40)

REPORTS CONTROL SYMBOL  
CSFOR-5(R1)

SECTION I - WRECKAGE DISTRIBUTION

Show principal ground impact points and distribution of wreckage. Indicate distance, direction of north, direction of wind, wind velocity, position of witnesses, etc.

SCALE OF DIAGRAM: 1" equals 40 yds.



"FOR OFFICIAL USE ONLY"

1. external cargo
2. blade struck fence post
3. A/C left aft wheel impact (18" hole)
4. piece of left aft gear strut, upper attaching point
5. actuator shaft, rescue hatch lower door
6. first aid kit
7. fire bottle holder

DA FORM 2397-5  
1 JUN 66

REPLACES DA FORM 2397-5, 1 APR 61, WHICH IS OBSOLETE  
EFFECTIVE 1 JAN 67

DFC-Japan

DA FORM 2397-5

**TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT**  
**PART II - MAINTENANCE AND ENGINEERING**  
(AR 95-5 and AR 385-40)

REPORTS CONTROL SYMBOL  
 CSFOR-5(R1)

**SECTION A - FAILURE OR MALFUNCTION**  
(Use this Section if accident involved inadequacy, malfunction or failure of material.) (Attach Photo(s))

1. WERE COMPONENTS OR FLUIDS SENT TO LAB FOR ANALYSIS? (If "Yes" explain in Item 5h)  YES  NO  
 2a. EIR CONTROL NUMBER: **E53230/E53231**  
 b. DATE: **6 June 71**

3. WAS FUEL, OIL OR HYDRAULIC SYSTEM A FACTOR? (If "Yes" explain in Item 5h)  
 YES  NO

4. FAILURE/MALFUNCTION OF ENGINE(S) (Explain circumstances)  
 Suspected failure of the #1 gov. driveshaft in #2 Engine fuel control followed by failure of #1 Engine.

ENGINE(S) MODEL	ENGINE SERIAL NO.	HR SINCE LAST OVERHAUL	OVERHAUL FACILITY	DATE	TOTAL ENGINE HR TO DATE
(#1) T55-L7	LEO-4957	26	ARADMAC	18 Nov 71	1434
(#2) T55-L7	LEO-4918	17	ARADMAC	18 Nov 69	1494

5a. COMPONENT NOMENCLATURE: **FUEL CONTROL**  
 b. COMPONENT FSN: **2915-761-0002**  
 c. PART NUMBER: **592964L13**  
 d. TIME SINCE LAST OVERHAUL: **14**  
 e. OVERHAUL FACILITY: **ARADMAC**  
 f. DATE: **UNK**  
 g. TOTAL TIME: **570**

h. FAILURE/MALFUNCTION OF COMPONENT(S) (Statement as to why failure or malfunction occurred)

- Awaiting return of teardown/analysis reports
- (#1) T55-L7, LEO-4957,
  - Engine, aircraft, turbo-prop.
  - FSN: 2840-950-6875
  - 2-000-030-18
  - Hr. since last overhaul: 26
  - Overhaul facility: ARADMAC
  - Date: 18 Nov. 71
  - Total time: 1434
  - (1) Fuel Control: failure of N1 gov. driveshaft, FSN 2915-963-0972 Part no. 02-13920, due to excessively worn small splines.
  - (2) #1 Engine/Failure: Awaiting return of teardown/analysis report.

6. STATEMENT OF MAINTENANCE OFFICER, MECHANIC AND OTHERS AS TO WHAT FAILED AND PROBABLE REASONS. (If maintenance or inspection error is known or suspected, indicate where maintenance was performed (field, garrison, etc.); weather condition, day or night, and experience level and training of the mechanic or inspector. Make recommendations to prevent this type error and/or failure.)

To the best of my knowledge there was no mechanical defects on Army Helicopter 64-13116 when it departed the company on 31 May 71. We were not notified of any suspected or developing problems prior to the accident.

"FOR OFFICIAL USE ONLY"

7. DID FIRE OCCUR? (If "Yes", attach sheet and describe in detail) (See Chapter 14, AR 95-5 for instructions)  YES  NO  
 8. DID SEAT FAILURE OCCUR? (If "Yes", attach sheet and describe in detail) (See Chapter 14, AR 95-5 for instructions)  YES  NO

TYPED NAME, GRADE AND STATION OF MAINTENANCE OFFICER: **LARRY K. MARTIN C1T TC**  
 SIGNATURE: *Larry K Martin*

DA FORM 2397-6 JUN 66

REPLACES DA FORM 2397-6, 1 APR 61, WHICH IS OBSOLETE  
 EFFECTIVE 1 JAN 67

PPC-Japan

PPC-Japan

DA Form 2397-6

6 June 71

Item 7:

- (1) Post crash fire occurred.
- (2) Fire was caused by impact and detonation of Claymore Mine and trip flare.
- (3) Fire was not extinguished due to nonavailability of fire fighting equipment.
- (4) Detecting and extinguishing equipment not available at time of crash.

"FOR OFFICIAL USE ONLY"

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT

PART III (Continuation)  
(AR 95-5 and AR 385-40)

REPORTS CONTROL SYMBOL  
CSFOR-5 (R1)

SECTION B - TRAUMA INFORMATION

(Complete on all individuals with physical, psychological or physiological trauma. Give detailed injury description to include exact location and extent. Under Item 4 include equipment failure and phase of accident, if applicable.)

1a. LAST NAME	b. SERVICE NUMBER	2. TRAUMA DESCRIPTION	3. CAUSE OF DEATH		4. METHOD AND AGENTS OF PRODUCTION
			YES	NO	
1.) SCHEIB	479-58-5741	Barbed wire scratch (L) leg		N/A	Caused by running through wire to clear burning ship
2.) [REDACTED]	[REDACTED]	[REDACTED]		N/A	Unclear; possibly caused by striking door or while climbing out.
3.) [REDACTED]	[REDACTED]	[REDACTED]		N/A	1) Struck back on hoist drum. 2) ? Struck by gun moutg.
4.) [REDACTED]	[REDACTED]	[REDACTED]		N/A	Injuries result of being tossed around during impact.
5.) KEARNS	[REDACTED]	[REDACTED]	YES		Trapped in burning wreckage; possibly knocked unconscious by impact.

5. AUTOPSY


YES (Report Attached) Autopsy pending  
 NO (Will be forwarded when available)

6. BLOOD OR TISSUE SPECIMENS

YES (Report Attached)  
 NO (Will be forwarded when available)

SECTION C - FLIGHT SURGEON'S ANALYSIS AND RECOMMENDATIONS

6.) KOREAN PASSENGER Unkown 4th degree burns over 100% of body. YES Trapped in burning wreckage.



RECOMMENDATIONS: A seat allowing free movement while at the same time securing and protecting the doorgunner and crewchief should be designed and instituted in the Chinook. At present the doorgunner and crewchief usually pile up ammunition boxes and sit on them. Also some study should be given to the protection and restraining of the flight engineer in his very vulnerable position lying over the load hatch (hole). I am informed this position is essential to the correct performance of his duties.

Deleted Jan Ex 5, Fo 14

DATE OF REPORT: 4 Jun 1971  
 FLIGHT SURGEON'S TYPED NAME AND GRADE: CLIFFORD C. HUBSON, CPT, MC/AMO  
 SIGNATURE: *Clifford C. Hubson*

DA FORM 2397-8 1 JUN 66

REPLACES DA FORM 2397-8, 1 APR 61, WHICH IS OBSOLETE EFFECTIVE 1 JAN 67.

**TECHNICAL REPORT OF U.S. ARMY AIRCRAFT ACCIDENT**

PART III - FLIGHT SURGEON

For use of this form, see AR 95-5 and AR 385-40; the proponent agency is Office of the Assistant Chief of Staff for Force Development.

REPORTS CONTROL SYMBOL  
CSFOR-3(R1)

**SECTION A - GENERAL INFORMATION**

1. WAS ACCIDENT SURVIVABLE? (If "No" check one of the boxes in item 2)  
 YES     NO     PARTIALLY
2.  DECELERATIVE FORCES     STRUCTURAL COLLAPSE     FIRE

3. LIST PERSONS INVOLVED

LAST NAME	SERVICE NUMBER	DUTY/STATUS	INJURY CODE*
SCHEIB	179-58-5741	Pilot	2
[REDACTED]	[REDACTED]	A/C	2
[REDACTED]	[REDACTED]	Crewchief	2
[REDACTED]	[REDACTED]	Gunner	2
KEARIS	[REDACTED]	Flight engineer	4
[REDACTED]	Unknown	Passenger	4

4. HUMAN FACTORS CONTRIBUTING TO CAUSE OF ACCIDENT (Indicate "Yes", "No" or "Suspected")

	PRESENT	CONTRIBUTED
a. PRE-EXISTING PATHOLOGICAL CONDITIONS (From Medical records)	No	No
b. PHYSIOLOGICAL FACTORS (Alcohol, CO, Fatigue, etc.)	No	No
c. PSYCHOLOGICAL FACTORS (Pre-occupation, Fear, etc.)	No	No
d. SUPERVISORY PROBLEMS	No	No
e. FAULTY PRE-FLIGHT TECHNIQUE	No	No
f. INEXPERIENCE OR TRAINING FACTORS	No	No
g. DESIGN INADEQUACIES (Instrumentation, Switches, etc.)	No	No
h. COMMUNICATION PROBLEMS	No	No
i. ENVIRONMENTAL FACTORS (Obls, Smoke, Cold, etc.)	No	No

5. IF "YES" OR "SUSPECTED" WAS ENTERED IN ITEM 4, EXPLAIN CIRCUMSTANCE AND/OR CONDITIONS (Use additional sheets as required)

6. INJURY FACTORS (Indicate "Yes", "No" or "Suspected")

	PRESENT	CONTRIBUTED TO INJURY	NO. OF PERSONS INJURED	CONTRIBUTED TO FATALITY	NO. OF FATALITIES
a. TIE-DOWN CHAIN FAILURE (Shoulder Harness, Safety Belt)	No	No	---	---	---
b. SHOULDER HARNESS, SEAT BELT NOT WORN BY CREW MEMBERS	Yes	Yes	3	1	1
c. HELMETS, BOOTS, GLOVES, FIRE RETARDANT CLOTHING NOT WORN BY CREW MEMBERS (Circle appropriate word(s))	No	No	---	---	---
d. HELMET LOSS	No	No	---	---	---
e. FIRE	Yes	Yes	2	2	2
f. RESTRAINT DEVICES NOT WORN BY PASSENGERS	No	No	---	---	---
g. RESCUE DIFFICULTIES	No	No	---	---	---
h. POST CRASH SURVIVAL DIFFICULTIES	No	No	---	---	---
i. SURVIVAL EQUIPMENT INADEQUACIES	No	No	---	---	---
j. ESCAPE FROM AIRCRAFT DIFFICULTIES	Suspected	Yes	2	2	2
k. BAILOUT	No	No	---	---	---
l. EJECTION	No	No	---	---	---

7. IF ANY FACTOR LISTED IN ITEM 6 WAS PRESENT AND CONTRIBUTED TO AN INJURY, EXPLAIN AND PROVIDE PICTURES, DIAGRAMS AND EQUIPMENT DESIGNATIONS; ALSO IDENTIFY INDIVIDUALS CONCERNED. (Use additional sheets as required)

- b.) Flight engineer, crewchief and gunner were not restrained. The injuries of the crewchief and gunner were directly related to this, and this may have contributed directly to the death of the flight engineer.
- e.) The flight engineer and Korean passenger were profoundly burned in the post-accident fire, and this was the most probable cause of their death.
- j.) The flight engineer and Korean passenger were possibly trapped in the wreckage, though this is unclear.

\*INJURY CODE: 1-NONE    2-MINOR    3-MAJOR    4-FATAL    5-MISSING    6-UNKNOWN

DA FORM 2397-7 JUN 66

FORM 2397-7, 1 APR 61, WHICH IS OBSOLETE

1. DATE		2. MODEL		3. SERIAL NUMBER					4. ORGANIZATION					5. STATION	
6. LAST NAME - FIRST INITIAL - GRADE - SERVICE NUMBER		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
7. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
8. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
9. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
10. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
11. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
12. [REDACTED]		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	
13. OTHER		[REDACTED]		[REDACTED]					[REDACTED]					[REDACTED]	

14. SIGNATURE  
*[Handwritten Signature]*

15. DATE  
[REDACTED]

A. ENTER DUTY SYMBOL IN UPPER LEFT BOX  
 B. ENTER FLIGHT SYMBOL IN UPPER RIGHT BOX  
 C. ENTER HOURS FLOWN ON LINE THEREUNDER

7	8	9	10	11	12

"FOR OFFICIAL USE ONLY"

MISSION SYMBOL LANDINGS

FROM TO

MISSION SYMBOL LANDINGS

FROM TO

MISSION SYMBOL LANDINGS

FROM TO

MISSION SYMBOL LANDINGS

FROM TO

MISSION SYMBOL LANDINGS

FROM TO

SUBTOTAL  
(Enter on Reverse Side)

DATE: 30 May 71  
 MODEL: C-17A  
 SERIAL NO: 42-3116  
 NAME OF CREW CHIEF/MECHANIC: [Signature]  
 STATION: [Signature]  
 PAGE NO: 2  
 NO. OF PAGES: 2

STATUS TODAY		AIRCRAFT TIME		NEXT INSPECTION DUE		HOT STARTS		LANDINGS		OTHER	
AIRCRAFT	ELECT. ARM. TONIC	TIME TO DATE	OTHER	INTIME NO. 1	TIME	NO. 1 ENGINE	NO. 2 ENGINE	NO. 1	NO. 2	OTHER	BY
1	X	06:10		06:10	06:10	0	0	15	0	0	
2	X	06:10		06:10	06:10	0	0	11	0	0	
3		06:10		06:10	06:10	0	0	0	0	0	
TOTAL		06:10		06:10	06:10	0	0	26	0	0	

FUEL (Gals or Lbs)		OIL (Quarts)		OXYGEN (PSI)		ANTI-ICING FLUID (Gals)	
SERV. NO	GRADE	ADDED	TOTAL IN TANKS	ADDED	TOTAL IN TANKS	ADDED	TOTAL
1	71	100	100	10	10	0	0
2	71	100	100	10	10	0	0
3	71	100	100	10	10	0	0
4	71	100	100	10	10	0	0
5	71	100	100	10	10	0	0
6							
7							
TOTAL							

17. FAULTS AND/OR REMARKS: [Blank]

18. ACTION TAKEN: [Blank]

19. SIGNATURE: [Signature]

20. STATION: [Blank]

16. STATUS SYMBOL	17. FAULTS AND/OR REMARKS	18. ACTION TAKEN	19. SIGNATURE
<del>2</del>	(5) (100%) ...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...
	...	...	...

INTE  
0: the  
for Lo

JSEL



1. DATE May 71		2. MODEL C-47A		3. SERIAL NO. 54-13116		4. NAME OF CREW CHIEF/MECHANIC [REDACTED]		5. STATION A. O. 377		6. PAGE NO. 2		8. NO. OF PAGES 2	
7. STATUS TODAY		8. AIRCRAFT TIME		9. NEXT INSPECTION DUE		10. HOT STARTS		11. LANDINGS		12. OTHER			
AIRCRAFT ELECT. ARMAMENT		TIME TO DATE		INTIMED NO.		NO. 1 ENGINE		NO. 2 ENGINE		OTHER			
OTHER		TIME TODAY		P. E. NO.		PREVIOUS		TODAY		TOTAL			
1. 4		TOTAL TIME		OTHER		TOTAL		TOTAL		TOTAL			
2. 5		TOTAL TIME		OTHER		TOTAL		TOTAL		TOTAL			
3. 6		TOTAL TIME		OTHER		TOTAL		TOTAL		TOTAL			
11. FUEL (Gals or Lbs)		12. OIL (Quarts)		13. OXYGEN (PSI)		14. ANTI-ICING FLUID (Gals)		15. BY		16. STATION			
SERV. NO.		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
1		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
2		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
3		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
4		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
5		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
6		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
7		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
TOTAL		TOTAL GRADE		TOTAL IN TANKS		TOTAL ADDED		TOTAL IN TANKS		TOTAL IN APU			
16. STATUS		17. FAULTS AND/OR REMARKS		18. ACTION TAKEN		19. SIGNATURE		20. SIGNATURE		21. SIGNATURE			
X		(5 May 71) rno 55-1500-210-2022 install soft retaining bolts in fuselage extendible links n/c/w daily inspection on rot and bolts upon receipt of rno kit 4/C stats will be ungraded to red x		rno 55-1500-210-2022 install soft retaining bolts in fuselage extendible links 14 May 71		John L. Whemba John L. Whemba		G Vance					

DA FORM 2408-13, 1 DEC 66 REPLACES EDITION OF 1 JAN 64, WHICH WILL BE USED (TM 38-737) AIRCRAFT INSPECTION AND MAINTENANCE RECORD  
 For use of this form, see TM 38-737; the provisions of TM 38-737  
 Office of The Deputy Chief of Staff for Logistics

II. STATUS SYMBOL	III. FAULTS AND/OR REMARKS	IV. ACTION TAKEN	V. SIGNATURE
	(14 Jan 70) 55-1520-209-30/62 install check	not recd. on A/C	S Kearns
	hydr. valve		
	(14 Jan 70) 55-1520-210-20/2 provisions for XI-41	not recd. on A/C	"
	(14 Jan 70) 55-1520-209-30/66 protect blade tie-down hole from erosion	not recd. on A/C	"
	(14 Jan 70) 55-1520-209-30/34 hinge kit closet error	not recd. on A/C	"
	(14 Jan 70) 55-1520-209-30/118 insp of hyd. check valve	not recd. on A/C	"
	(15 May 71) aft xmsn oil lvl. lt. wires broken	repl. lt. and connected wires	"
	" aft xmsn oil lvl lt lens covr rmd.	not recd. on A/C	"
X	removed speed trim amp.	J. Turnbow insp. OK repl. with amp	A Nichols
	box s/n C4016 A Nichols	box s/n 10027	
	fit #1 ok D Boynton		
	post fit insp due D Boynton	Comp. 30 May 71	D Boynton

LOCAL FLIGHT CLEARANCE

Unit: 243 Avn. Co.		DATE: 31 May 1971
A/C	A/C NO. 64-13116	MISSION: Phu Hiep

State whether crew or passengers. List additional on reverse.  
 NAME AND INITIALS GRADE SERVICE NO. HOME STATION

[REDACTED]	CN 2	DMT
Scheib, R.	WO 1	"
Kearns, S.	SP/5	"
[REDACTED]	SF/5	"
[REDACTED]	SP/4	"
[REDACTED]	Civ.	" A.C. 01 *
[REDACTED]	Civ.	" " " *

Certified to be a true copy  
*John L. Shanahan Jr.*  
 CPT John L. Shanahan Jr.

BASE (home base)	HOURS OF FUEL, MILITARY BASE	FIRST INTENDED LANDING
------------------	------------------------------	------------------------

FORM FILED AT DATE FILED (DAY, MONTH) 1 Mar. 1971

PILOT IS FORECAST TO REMAIN VFR FOR THE DURATION OF THIS FLIGHT. I AM FAMILIAR WITH ALL CURRENT REGULATIONS AFFECTING THIS FLIGHT AND THIS FLIGHT WILL BE CONDUCTED IN ACCORDANCE WITH SUCH REGULATIONS.

PILOTS SIGNATURE Rex A. Scheib	PILOTS SIGNATURE Rex A. Scheib
DEPARTURE 0315	ACTUAL ARRIVAL 1330

REMARKS V1-V3 Down C4 223 350 \* One way only. D/O Tuy Hoa

DD FORM 1080 REPLACES A FORM 11, 1 NOV 51, WHICH MAY BE USED.

1 JAN 53  
 "FOR [REDACTED] USE ONLY"

ARMY AIRCRAFT ACCIDENT REPORT CHECK LIST  
(AR 95-5)

Aircraft Type, Model, and Series	Serial Number	Date of Accident		
CH-47A	64-13116	31 May, 1971		
Exhibits	Inclosed	Not Applicable	See Remarks	
TAB 1 - Copy of Crash Facts Message	X			
TAB 2 - Copy of Orders Appointing Investigating Board of Officers	X			
TAB 3 - Weather Reports	X			
TAB 4 - Certificate of Damage	X			
TAB 5 - Copy of Equipment Improvement Record (DA Form 2407)	X			
TAB 6 - Special Technical Reports and Laboratory Analysis			X	
TAB 7 - Weight and Balance (DD Form 365F)	X			
TAB 8 - Copy of Directive, Regulation, etc.		X		
TAB 9 - Diagrams and/or Photograph	X			

TAB 10 - Other (List)

- a. Copy of Aircraft Release
- b. Letter, Request for Assistance from UCABAAR, 17th CAG Safety Officer.
- c. Report, George D. Simpson, T-55 Representative, USAAVSCOM
- d. Report, Robert J. Heady, CH-47 Representative, USAAVSCOM

REMARKS: e. Performance Charts, TM 55-1520-209-10

TAB 6 - ~~Fuel Contamination Report will be forwarded upon receipt.~~  
Teardown/Analysis Reports will be forwarded upon receipt.

"FOR OFFICIAL USE ONLY"

1 JUN SWF S

W  
PP AAANHA  
DE AAANHAE 168G9 /1520230  
ANR UUUU  
P 010030 Z MAY 71  
FM: CO 10 TH CAB DBT RVN  
TO: AAANHA/ CO 17 TH CBT AVN GP TUY RVN  
ZEN/ ACSFOR DQ  
ZEN/CSA WASH DC  
AEN/ DIR USAVSCOM ST LOUIS MO  
ZEN/CINCUSARPAC HAWAII  
ZEN/CG USARV LBN RVN  
ZEN/CO 34 TH GEN SPT GP SGN RVN  
ZEN 243 RD ASH CO COURIER

BT  
UNCLAS 6-1 F O U O  
AVBAVA-SE DIR FOR ARMY AVN CINCUSARPAC FOR GPOP- AV  
USARV FOR AVHAV- S.  
SUBJECT: ARMY AIRCRAFT MAJOR ACCIDENT CRASH FACT S MESSAGE  
REPORT PCS CSGPA-459.  
1. 31 MAY 71, 1300(H) LOCAL, DAY  
2. PHU HIEP, 10 MILES SOUTH OF TUY HOA, RVN; CQ 252 345  
3. CH-47A SN: 64-13116  
4. 243RD ASSAULT SUPPORT HELICOPTER COMPANY, APO 96377  
5. MAJOR ACCIDENT; TOTAL LOSS

PAGE TWO (2) UNCLASS AAANHAE 1689 F O U O  
6. INSTRUCTOR PILOT: [REDACTED], CW2, [REDACTED]  
243 RD ASSAULT SUPPORT HELICOPTER COMPANY, APO 96377, NO INJURIES  
7. PILOT: SCHEIG, REX A., WO1, 479-58-5741, 243RD ASSAULT  
SUPPORT HELICOPTER COMPANY, APO 96377, ON INJURIES. CE:  
[REDACTED] SP5, [REDACTED] 243 RD ASSAULT SUPPORT HELICOPTER  
COMPANY, APO 96377, NO INJURIES. FE: KEARNS, STEVEN J., SP5,  
[REDACTED], 243RD ASSAULT SUPPORT HELICOPTER COMPANY, APO  
96344, FATAL INJURIES. GUNNER: [REDACTED] SP4,  
[REDACTED] 243RD ASSAULT SUPPORT HELICOPTER COMPANY, APO  
96377, NO INJURIES.  
8. CORPORAL IN THE ROK ARMY RECEIVED FATAL INJURIES; IDENTITY  
IS UNKNOWN AT THIS TIME.  
9. DCA, VFR, PHU HIEP, 0.5 HOURS  
10. TAKE - OFF WITH SIING LOAD  
11. UPON DEPARTING THE 28 TH RCP, THE ,9. 2 ENGINE FAILED AT 40-  
50 K OTS OF AIRSPEED AND 75 TO 100 ABOVE THE GROUND. THE IP  
TOOK CONTROL OF THE AIRCRAFT NAD IMMEDIATELY JETTISONED THE  
CYCLIC DIPPED SLIGHTLY FORWARD. THE NO. 1 ENGINE FAILED AND THE  
CYCLIC DIPPED SLIGHTLY FORWARD. THE NO. 1 ENGINE FAILED AND THE

PAGE THREE (3) UNCLASS AAANHAE 1689 F O U O  
TOLLED HARDOVER TO THE REAR AND FROZE IN THE AFT POSITION.  
THE IP TRIED TO LOWER THE THRUST ROD BUT IT WAS ALSO FROZEN.  
WITHIN 20-30 SECONDS AFTER THE INITIAL ENGINE FAILURE, THE  
AIRCRAFT IMPACTED IN A TAIL LOW ATTITUDE, ROLLED ON ITS RIGHT  
SIDE, AND THE CARGO SECTION BURST INTO FLAMES. THE SURVIVING  
CREW EXITED THE AIRCRAFT FROM THE PILOTS EMERGENCY EXIT.  
12. WEATHER WAS NOT A FACTOR.  
13. NONE  
14. UNKNOWN  
15. NONE  
16. A. NA B. NONE C. NA D. NO E. NO  
17. GPT [REDACTED], 243RD ASSAULT SUPPORT  
HELICOPTER COMPANY. APO 96344, ( TELEPHONE DBT 236).  
18. YES  
19. NO  
20. A SUPPLEMENTAL TO FOLLOW  
21. "FOR OFICIAL USE ONLY"., PROTECTIVE MARKINGS WILL BE REMOVED  
AFTER THREE DAYS.  
1689

"FOR OFFICIAL USE ONLY"

NNNN

HEADQUARTERS, 1st COMBAT AVIATION BATTALION  
APO San Francisco 96377

SPECIAL ORDERS  
HERNER 100  
EXTRACT.

12 June 1971

7. TO 454. Following BOARD/COMMITTEE appointed subject to call of the Pres/Chmn there of, and will consist of members as indicated.

SMITHMAN, JOHN L. J. [REDACTED] CPT 1201 1928 1st Lt Hel) (MAX6AA) AR (pres)  
SMELTON, WILLIAM J. [REDACTED] CW2 19070 Co 9/227th, 1st CA (MAX6AA) AV (leader)  
WRIGHT, THOMAS E. [REDACTED] WO1 19070 22d Avn Co (1st Lt Hel) (MAX6AA) 96377 AV (br)  
HUNSON, CLIFORD G. [REDACTED] CPT 05139 190 13th Cbt Avn Co (MAX6AA) 100 1st Surgeon

Authority: AF 35-5, AF 35-10 100 100 V or 305-10

Name of Board/Committee: Accident Investigating Board

Members: Same as SHL

Period: Indefinite

Purpose: To investigate facts and circumstances surrounding aircraft accident occurring on 31 May 1971, (grid Coord) CQ252345, 1st Hiep, AV involving a CM-47A Ser 74-13116, (C) C2 Moore, of the 243d Avn Co 9377

Effective Date: 31 May 1971

Special Instructions: Board will submit report in original and two copies to this headquarters ATTN: Safety Officer MLT 15 June 1971. Officers are released from all other duties until investigation is complete.

8. TO 453. Following individual APPOINTED/DELEGATED/CERTIFIED as indicated.

VANIELS, EDWARD L. [REDACTED] CPT 1201 1928 1st Lt Hel) (MAX6AA) 96321 FA

Authority: Para 26b, AF 305-10 and AF 15-6

Designated as: SA

Certified as: SA

Appointed as: Collateral Investigation Officer

Period: Indefinite

Purpose: To conduct Collateral investigation on facts and circumstances surrounding aircraft accident occurring on 25 May 1971 involving: 44-11 (A-1573)

Effective Date: June 1971

Special Instructions: Investigation will be directed toward determining negligence claims or pecuniary responsibility. Completed report to reach this headquarters 15 June 1971. Officers released from all other duties until investigation is complete.

"FOR OFFICIAL USE ONLY"

Para 7 S: 10th Co 1st Bn 13th Avn Co (Inf) 96377 (Cont) 12 June 1971  
THOMPSON, DONALD S. [REDACTED] 10th Co 1st Bn 13th Avn Co (Inf) (M) 96377 CC

Authority: 10th Co-1st Bn  
Assigned as: [REDACTED]  
Certified as: [REDACTED]  
Appointed as: Investigator  
Period: Indefinite

Purpose: To conduct a formal line of duty investigation on MOSS, WILLIAM E. APO  
76-144-1372 of the 13th Fed Det APO 96377

Effective Date: 11 June 1971

Special Instructions: Completed report to reach this headquarters 27 June 1971.  
Officers released from all other duties until investigation completed.

FOR THE COMMANDER:

OFFICIAL:

WALTER H. BOLT  
CPT, FA  
Adjutant

*Donald S. Hale*

DONALD S. HALE  
CPT, USA  
Asst Adjutant

1-1581-1-1  
1-2-11 1-1-11 1-1-11  
1-1-11

FOR THE COMMANDER'S INFORMATION:

7-CO, 1st Bn, 13th Avn Co  
8-CO, 2nd Bn, 13th Avn Co  
9-CO, 1st Bn, 13th Avn Co  
6-1st Bn, 13th Avn Co  
6-1st Bn, 13th Avn Co

DEPARTMENT OF THE ARMY  
HEADQUARTERS 17TH AVIATION GROUP (COMBAT)  
APO San Francisco 96316

SPECIAL ORDERS  
NUMBER 173  
EXTRACT

22 June 1971

10. TO 453. Following individual(s) APPOINTED/DESIGNATED/CERTIFIED  
As indicated.

PERSON: CHARLES S. [REDACTED] O-3 [REDACTED] 10th ASHC (WC5LAA) APO 96316 AV

Auth: VOCO 17th CAG

Designated as: N/A

Certified as: N/A

Appointed as: Investigating Officer

Period: Indefinite

Purpose: To conduct an accident investigation concerning the crash of  
a CH-47A piloted by CW2 Mervyn Robert O. 515-32-4752 on the after-  
noon of 31 May 71 at Phu Hiep

Effective date: 31 May 71 VOCO 17th CAG

Special Instr: Investigation will be conducted IAW appropriate regulations  
Coordinate with the 10th CAG accident prevention office and  
submit to them three (3) copies of completed report

FOR THE COMMANDER:

OFFICIAL;

SECRETZ

*William F. Hawkins*  
WILLIAM F. HAWKINS  
CAP, AG  
Asst Adjutant

DISTRIBUTION:

12-con files  
30-indiv conc  
5-indiv FDMF  
1-indiv 201 file  
5-10th ASH  
5-10th CAG  
1-Ma CLK



FROM: DAF, Det 56, 5 Wea Sq, APO 96516


5 Jun 1971

SUBJECT: Official Data Extract for Accident Investigation

TO: 10th CAB (Attn: Safety Officer)  
Long Ba Train

The following is a summary of weather observations for 31 May 1971,  
hours as indicated in local standard times for Tuy Hoa AAF.

TIME	WINDS IN KNOTS	VISIBILITY IN MILES	CLOUDS HEIGHTS OF FEET	TEMPERATURE/ DEW POINT DEGREES C	ALTI METER	PRESSURE ALTITUDE FEET
0855	240/07	15	20 SCTD 100 SCTD 140 BKN 300 BKN	28/24	2984	+2050
0955	270L/04	15	20 SCTD 100 SCTD 500 THEN BKN	29/24	2984	+2200
1055	100/08	15	20 SCTD 100 BKN 500 BKN	31/24	2984	+2300
1155	100/07	15	25 SCTD 100 BKN 300 BKN	30/26	2985	+2500
1255	090/06	15	50 SCTD 100 BKN 300 BKN	30/25	2981	+2500
1315	090/08	15	50 SCTD 100 BKN 300 BKN	31/25	2980	+2400
1355	090/00	15	50 SCTD 100 SCTD 300 BKN	31/25	2979	+2450
1455	100/08	15	50 SCTD 100 SCTD 300 BKN	32/24	2977	+2600



ROGER H. DAY, Capt USAF  
Commander

"FOR OFFICIAL USE ONLY"

DEPARTMENT OF THE ARMY  
HEADQUARTERS, 10TH COMBAT AVIATION BATTALION  
APO San Francisco 96377

5 June 1971

C E R T I F I C A T E

I hereby certify that Army Aircraft, CH-47A, serial number 64-13116, crashed and was destroyed by fire at Phu Hiep, RVN on 31 May 1971, and was a total loss. Catalogue cost of this CH-47A was \$ 1,072,838.00.

*John L. Shanahan Jr.*

JOHN L. SHANAHAN JR.

CPT, AR

President, Accident Investigation Board

**MAINTENANCE REQUEST**  
 Use of this form, see TM 38-750; the proponent's Agency Office of the Deputy Chief of Staff for Logistics.

\* See reverse of file copy for codes and additional data.  
 PAGE NO. 1 NO. PAGES 2

REPORTS CONTROL SYMBOL  
 CSGLD 1047 (RI)

CONTROL NUMBER **E53228**  
 1a. ORGANIZATION **243rd Avn Co**  
 1b. LOCATION **APO San Francisco 96377**  
 1c. UNIT IDEN CODE **WDTEA A**

2. SERIAL NUMBER **64-13116**  
 3. NOUN NOMENCLATURE **Helicopter**  
 4. LINE NUMBER  
 5. MODEL **UH-47A**  
 6. FEDERAL STOCK NUMBER **1520-633-6836**

7. STRAC  
 YES  NO  
 8. UTILIZATION CODE **OV**  
 9. SELECTED ITEM  
 YES  NO  
 10. HOURS **2398**  
 11. MILES  
 12. ROUNDS  
 13. STARTS

14. FAILURE DETECTED DURING (Select one - use I or V)  
 A SCHEDULED MAINTENANCE  B TEST  C STORAGE  D LIGHT  E INOPERATIVE  F OVERHEATING  G OUT OF ADJUSTMENT  
 H HANDLING  I NORMAL OPERATION  J INSPECTION  K OTHER  L LOOSE  M LOW PERFORMANCE  N OTHER

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND TROUBLESHOOTING PROCEDURE IN EQUIPMENT TM (Do not prescribe reasons)

**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PARTICULAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- AT THE ORGANIZATIONAL LEVEL**
  - a. Requesting repairs and maintenance services
  - b. Reporting accomplishment of Modification Work Orders
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Reporting receipt of defective material
  - e. It may be used to record maintenance accomplishments.
- AT SUPPORT MAINTENANCE LEVEL**
  - a. Recording maintenance work and/or services actually performed
  - b. Reporting the installation of equipment modifications
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures
  - e. Reporting receipt of defective material
  - f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Inter Shop Maintenance Request)
  - g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request)
- AT DEPOT MAINTENANCE LEVEL**
  - a. Reporting the installation of equipment modifications
  - b. Submission of Equipment Improvement Recommendations (EIR)

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S)  
 a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.  
 b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.  
 c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY  
 24. RECEIVED BY  
 JULIAN DATE **1159**  
 JULIAN DATE

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL REPLACEMENT (Select one - use Y or X)  
 1 YES  2 NO  
 30. IS THIS AN EMERGENCY?  
 1 URGENT  2 WOOD TIME  
 31. RECOMMENDATION (Select one - use I or X)  
 A IMPROVE DESIGN  B REVISE PROCEDURE  C MODIFY  D OTHER (Specify)  
 32a. ORGANIZATION/ACTIVITY  
**243rd Avn Co**  
 32b. LOCATION  
**APO San Francisco 96377**  
 33. FEDERAL STOCK NUMBER  
**1680-135-0284**  
 34. NOUN NOMENCLATURE  
**Actuator Electro**  
 35. OPINION OR REMARKS. DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES IF AVAILABLE.  
**W DYEAA**  
**S. Martin**

1. Mfg Part No. **114Pg200-2**  
 2. Item Serial No. **Unknown**  
 3. TM Number **55-1520-200-24P1 Page 231 Fig 66 Index 11**  
 4. Last Overhaul **N/A**  
 5. Quantity Inspected **one**



SECTION I  WORK REQUEST  MWO  EIR **02** ORGANIZATION ISSUE PRIORITY DESIGNATOR **WDYEAA**

CONTROL NUMBER **E53231** 1. ORGANIZATION **243D ASH CO** 2. LOCATION **APO SF 96377** 3. UNIT IDEN CODE **WDYEAA**

4. SERIAL NUMBER **64-13116** 5. NOUN NOMENCLATURE **HELICOPTER** 6. LINE NUMBER **CH-47A** 7. MODEL **CH-47A** 8. FEDERAL STOCK NUMBER **1520-633-6836**

9. STRAC  YES  NO **H** 10. UTILIZATION CODE\* **ON** 11. SELECTED ITEM  YES  NO 12. HOURS **2410** 13. MILES 14. ROUNDS 15. STARTS **0**

14. FAILURE DETECTED DURING (Select one - use Y or N)  SCHEDULED MAINTENANCE  TEST  STORAGE  FLIGHT  HANDLING  NORMAL OPERATION  RECEPTION  OTHER

15. FIRST INDICATION OF TROUBLE (Select one - use Y or N)  INOPERATIVE  OVERHEATING  OUT OF ADJUSTMENT  NOISY  LOW PERFORMANCE  OTHER **X099**

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not describe repairs)

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750.**  
**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- |   |   |   |
|---|---|---|
| <p><b>AT THE ORGANIZATIONAL LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Requesting repairs and maintenance services</li> <li>b. Reporting accomplishment of Modification Work Orders</li> <li>c. Submission of Equipment Improvement Recommendations (EIR)</li> <li>d. Reporting receipt of defective material.</li> <li>e. It may be used to record maintenance accomplishments</li> </ul> | <p><b>AT SUPPORT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Recording maintenance work and/or service actually performed</li> <li>b. Reporting the installation of equipment modifications</li> <li>c. Submission of Equipment Improvement Recommendations (EIR)</li> <li>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct-exchange procedures</li> <li>e. Reporting receipt of defective material</li> <li>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra Shop Maintenance Request)</li> <li>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request)</li> </ul> | <p><b>AT DEPOT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Reporting the installation of equipment modifications</li> <li>b. Submission of Equipment Improvement Recommendations (EIR)</li> </ul> |
|---|---|---|

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S)

- a. EMERGENCY EIR'S will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III, will be submitted with the message number indicated as part of the narrative remarks in Block 35.
- b. URGENT EIR'S will be air mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
- c. ROUTINE EIR'S prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY \_\_\_\_\_ 24. RECEIVED BY \_\_\_\_\_

JULIAN DATE **1156** JULIAN DATE \_\_\_\_\_

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL PLACEMENT (Select one - use Y or N)  EMERGENCY  URGENT  ROUTINE

30. RECOMMENDATION (Select one - use Y or N)  IMPROVE DESIGN  REVISE PROCEDURE  OTHER (Specify) \_\_\_\_\_

31. ORGANIZATION/ACTIVITY **243D ASH CO** 32. LOCATION **APO SF 96377** 33. FEDERAL STOCK NUMBER **2840-750-6875** 34. NOUN NOMENCLATURE **ENGINE, ACFT TURBO** 35. OPINION OR REMARKS **SEPARATE SHEET ATTACHED**

36. UNIT IDEN CODE **WDYEAA** 37. SUBMITTER'S NAME **CPT MARTIN**

1. Mfg part number- **2-000-030-18**
2. Item serial number- **LEO-1957**
3. TM number- **TM 55-1520-202-34-71 Page 353 Fig 62**
4. Last overhaul- **2384**
5. Quantity inspected- **Two**



**MAINTENANCE REQUEST**  
 For use of this form, see TM 38-750; the proponent agency is Office of the Deputy Chief of Staff for Logistics.

\* See reverse of file copy for codes and additional data.

PAGE NO. **1** NO. PAGES

REPORTS CONTROL SYMBOL  
 CSGLD-1047 (R1)

SECTION I		<input type="checkbox"/> ACOP REQUEST		<input type="checkbox"/> MWO		<input checked="" type="checkbox"/> EIR		<input type="checkbox"/> O2	
CONTROL NUMBER <b>E53232</b>		ORGANIZATION <b>243D ASH CO</b>		LOCATION <b>APO SF 96377</b>		ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE <b>WDYEAA</b>			
2. SERIAL NUMBER <b>64-13116</b>		3. NOUN NOMENCLATURE <b>HELICOPTER</b>		4. LINE NUMBER		5. MODEL <b>CH-47A</b>		6. FEDERAL STOCK NUMBER <b>1520-633-6836</b>	
7. STPAC <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		8. UTILIZATION CODE* <b>ON</b>		9. SELECTED ITEM <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		10. HOURS <b>2410</b>		11. MILES <b>m</b>	
14. FAILURE DETECTED DURING (Select one - use V or X) <input checked="" type="checkbox"/> SCHEDULED MAINTENANCE <input type="checkbox"/> HANDLING		15. FIRST INDICATION OF FAILURE (Select one use V or X) <input type="checkbox"/> TEST <input type="checkbox"/> NORMAL OPERATION <input type="checkbox"/> STORAGE <input checked="" type="checkbox"/> FLIGHT <input type="checkbox"/> REPAIR <input type="checkbox"/> OTHER		16. FIRST INDICATION OF FAILURE (Select one use V or X) <input checked="" type="checkbox"/> INOPERATIVE <input type="checkbox"/> ROISY		17. OVERHEATING <input type="checkbox"/> OUT OF ADJUSTMENT <input checked="" type="checkbox"/> OTHER		18. ROUNDS <b>0</b>	
16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)									

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750. USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

**AT THE ORGANIZATIONAL LEVEL**  
 a. Reporting repairs and maintenance services.  
 b. Reporting accomplishment of Modification Work Orders.  
 c. Submission of Equipment Improvement Recommendations (EIR).  
 d. Reporting receipt of defective material.  
 e. It may be used to record maintenance accomplishments.

**AT SUPPORT MAINTENANCE LEVEL**  
 a. Recording maintenance work and/or service actually performed.  
 b. Reporting the installation of equipment modifications.  
 c. Submission of Equipment Improvement Recommendations (EIR).  
 d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.  
 e. Reporting receipt of defective material.  
 f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra-Shop Maintenance Request).  
 g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter-Shop Maintenance Request).

**AT DEPOT MAINTENANCE LEVEL**  
 a. Reporting the installation of equipment modifications.  
 b. Submission of Equipment Improvement Recommendations (EIR).

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S)  
 a. EMERGENCY EIR'S will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.  
 b. URGENT EIR'S will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.  
 c. ROUTINE EIR'S prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency.  
 Check "Routine" in Section III.

23. SUBMITTED BY	24. RECEIVED BY
JULIAN DATE <b>1156</b>	JULIAN DATE

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL PLACEMENT (Select one - use V or X) <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		30. EMERGENCY (Select one - use V or X) <input type="checkbox"/> URGENT <input checked="" type="checkbox"/> ROUTINE		31. RECOMMENDATION (Select one - use V or X) <input type="checkbox"/> IMPROVE DESIGN <input type="checkbox"/> REVISE PROCEDURE <input type="checkbox"/> MODIFY <input checked="" type="checkbox"/> OTHER (Specify)		32a. ORGANIZATION/ACTIVITY <b>243D ASH CO</b>		32b. LOCATION <b>APO SF 96377</b>		32c. UNIT IDEN CODE <b>WDYEAA</b>	
33. FEDERAL STOCK NUMBER <b>2840-950-6875</b>		34. NOUN NOMENCLATURE <b>ENGINE, TURBO</b>		35. OPINION OR REMARKS DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED OR CATCHES, IF AVAILABLE <b>SEPARATE SHEET ATTACHED</b>							

1. Mfg part number- <b>2-000-030-18</b>											
2. Item serial number- <b>L30-4918</b>											
3. TM number- <b>TM 55-1520-209-34B-1 Page 358 Fig 62</b>											
4. Last overhaul- <b>1477</b>											
5. Quantity Inspected- <b>373</b>											

**MAINTENANCE REQUEST - CONTINUATION**

For use of this form, see TM 38-750; proponent agency is ODCSLOG.

\* See reverse of this copy for codes and additional data.

PAGE NO. 2 NO. PAGES

REPORTS CONTROL SYMBOL CSOLD-1047 (R1)

CONTROL NUMBER

B53232

WORK REQUEST

MWO

EIR

204. ACTION CODE	3. FAILURE CODE	4. COMPONENT / PART NOUN, SERVICE, OR MWO NO.			5. MANHOURS (Hours & Minutes)	6. FEDERAL STOCK NUMBER	7. QUANTITY	8. PARTS COST
		4a. CB CODE	4b. REFERENCE DESIGNATOR	4c. MPR. CODE				
		6. Quantity Defective - One						
		7. Time since new-1494						
		8. Since overhaul- 17						
		9. Circumstances prior to difficulty-			The weather was clear and warm. The pilot was flying the acft lifting off with a sling load with the AC monitoring the instruments.			
		10. Description of difficulty-			While lifting off with a sling load. The pilot noticed at approximately 75 ft AGL that the NI indicator was unwinding rapidly indicating a loss of power on the #2 engine. He immediately jettisoned the load. He then noticed that he had no indication of power on the #1 engine. The acft could not be controlled, it impacted with the ground and burned.			
		11. Cause-			Suspect failure of the torque output shaft in the fuel control on #2 engine			
		12. Action taken-			The fuel control has been removed and is being processed for teardown analysis.			
		13. Recommendation-			None at present pending results of teardown analysis.			
		14. Engine Turbine Checklist --			See Page 3			

"FOR OFFICIAL USE ONLY"



**MAINTENANCE REQUEST - CONTINUATION**

For use of this form, see TM 38-750; proponent agency is ODCSLOG.

\* See reverse of this copy for codes and additional data.

PAGE NO. 3

NO. 5 PAGES

REPORTS CONTROL SYMBOL CSOLD-1047 (R1)

CONTROL NUMBER

E 53232

WORK REQUEST

MWO

EIR

20a. ACTION CODE	b. FAILURE CODE	c. COMPONENT/PART NOUN, SERVICE, OR MWO NO.				g. MANHOURS* (Hours & tenths)	h. FEDERAL STOCK NUMBER	i. PART SOURCE CODE	j. QUANTITY	k. PARTS COST
		d. CB CODE	e. REFERENCE DESIGNATOR	f. MFR. CODE						
14		Turbine Engine Checklist				.				
	1.	Normal Rated power				.				
	2.	Set Power Rating				.				
	3.	No				.				
	4.	Weather Good Out 31°				.				
	5.	640	90.5°-91°	230 Rotor RPM		.				
	6.	Appx. 30 knots APPX 75-100ft				.				
	7.	640°				.				
	8.	Yes				.				
	9.	No caution Light				.				
	10.	Fuel Valve on Crossfeed Closed Fuel boost pumps on				.				
	11.	No				.				
	12.	No				.				
	13.	N/A				.				
	14.	Yes				.				
	15.	N/A				.				
	16.	No				.				
	17.	No				.				
	18.	No				.				
	19.	Not Prior to Failure				.				
	20.	No				.				
	21.	N/A				.				
	22.	No				.				
	23.	JP/4				.				
	24.	230.09				.				
	25.	No				.				
	26.	N/A				.				
	27.	No				.				

FOR OFFICIAL USE ONLY

MAINTENANCE REQUEST  
 For use of this form, see TM 38-750; the proponent Agency is Office of the Deputy Chief of Staff for Logistics.

\* See reverse of file copy for codes and additional data.

PAGE NO. 1 NO. PAGES 8

REPORTS CONTROL SYMBOL  
 CSGLD 1047 (RI)

SECTION I

CONTROL NUMBER: **E53230**  
 ORGANIZATION: **243D ASH CO**  
 LOCATION: **APO SF 96377**  
 UNIT IDEN CODE: **WDYEAA**

SERIAL NUMBER: **LEO\* 4918**  
 NOUN NOMENCLATURE: **ENGINE TURBO**  
 LINE NUMBER: **1**  
 MODEL: **T-55 L7**  
 FEDERAL STOCK NUMBER: **2840-950-6875**

STRAC:  YES  H  NO  
 UTILIZATION CODE: **ON**  
 SELECTED ITEM:  YES  NO  
 HOURS: **1494** MILES: **0** ROUNDS: **0** STARTS: **0**

FAILURE DETECTED DURING (Select one - use Y or X)  
 SCHEDULED MAINTENANCE  TEST  STORAGE  SERVICE  
 HANDLING  NORMAL OPERATION  INSPECTION  OTHER

INDICATION OF TROUBLE (Select one - use Y or X)  
 INOPERATIVE  OVERHEATING  OUT OF ADJUSTMENT  
 BLOCKED  LOW PERFORMANCE  OTHER **1099**

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)

PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750  
 USES AND INSTRUCTIONS

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- AT THE ORGANIZATIONAL LEVEL
  - a. Requesting repairs and maintenance services
  - b. Reporting accomplishment of Modification Work Orders
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Reporting receipt of defective material
  - e. It may be used to record maintenance accomplishment.
- AT SUPPORT MAINTENANCE LEVEL
  - a. Recording maintenance work and/or services actually performed
  - b. Reporting the installation of equipment modifications.
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.
  - e. Reporting receipt of defective material.
  - f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Inter Shop Maintenance Request)
  - g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request)
- AT DEPOT MAINTENANCE LEVEL
  - a. Reporting the installation of equipment modifications.
  - b. Submission of Equipment Improvement Recommendations (EIR).

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR\*)  
 a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.  
 b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.  
 c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY: \_\_\_\_\_ 24. RECEIVED BY: \_\_\_\_\_  
 JULIAN DATE: **1156** JULIAN DATE: \_\_\_\_\_

SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION

29. NORMAL REPLACEMENT (Select one - use Y or X)  
 YES  NO  
 30. EIR (Select one - use Y or X)  
 EMERGENCY  URGENT  ROUTINE  
 31. RECOMMENDATION (Select one - use Y or X)  
 IMPROVE DESIGN  REVISE PROCEDURE  OTHER (Specify) **1099**  
 MODIFY

FEDERAL STOCK NUMBER: **2915-761-0002**  
 NOUN NOMENCLATURE: **FUEL CONTROL**  
 ORGANIZATION/ACTIVITY: **243D ASH CO**  
 LOCATION: **APO SF 96377**  
 UNIT IDEN CODE: **WDYEAA**  
 SUBMITTED BY: **CPT MARTIN**

35. OPINION OR REMARKS. DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES IF AVAILABLE  
**TORQUE OUTPUT SHAFT SPLINES STRIPPED**  
 1. Mfg part number- **592964L13**  
 2. Item serial number. - **11441**  
 3. TM number- **55-2840-234-20P Page 59 Figure 35**  
 4. Last overhaul- **UNK**  
 5. Quantity inspected- **ONE**

**MAINTENANCE REQUEST - CONTINUATION SHEET**

For use of this form, see TM 38-750; proponent agency is ODCSLOG.

\* See reverse of this copy for codes and additional data.

PAGE NO.

2

NO. OF PAGES

1

REPORTS CONTROL SYMBOL  
CSOLD-1047 (RI)

CONTROL NUMBER

E53230

WORK REQUEST

MWO

EIR

204. ACTION CODE	b. FAILURE CODE	a. COMPONENT / PART NOUN, SERVICE, OR MWO NO.			f. MANHOURS* (Hours & tenths)	A. FEDERAL STOCK NUMBER	L. PART SOURCE CODE	J. QUANTITY	K. PARTS COST
		d. CB CODE	e. REFERENCE DESIGNATOR	f. MPR. CODE					
		6. Quantity defective -ONE							
		7. Time since new- 570							
		8. Since overhaul- 1h							
		9. Circumstances prior to difficulty-			The weather was clear and warm. The pilot was flying the aircraft lifting off with a slingload with an A6 monitoring instruments.				
		10. Description of difficulty- Upon lifting off with a sling load, the pilot noticed that on the #2 Eng, EXX the N <sup>1</sup> indicator was rapidly approaching 0. The load was immediately jettisoned and it was noticed that power was lost on the #1 Eng, the pilot attempted to control the aircraft, but the altitude was not enough to effectively regain control. The aircraft struck the ground and burned upon impact.							
		11. Cause - Current failure of the torque output shaft splines							
		12. Action taken -The fuel control has been removed from the remains of the engine and is being processed for teardown analysis							
		13 Recommendations- None at present pending results of teardown analysis							

**MAINTENANCE REQUEST**  
For use of this form, see TM 38-750; the proponent's Agency is Office of the Deputy Chief of Staff for Logistics.

\*See reverse of file copy for codes and additional data.

PAGE NO. 1

TOTAL PAGES 2

REPORTS CONTROL SYMBOL  
CSGLD-1047 (R1)

**SECTION I**

WORK REQUEST  PART  AIR

02

ORGANIZATION  
ISSUE PRIORITY  
DESIGNATOR CODE

CONTROL NUMBER

E53233

TO, ORGANIZATION

243rd Avn Co

B. LOCATION

APO San Francisco 96377

C. UNIT IDEN CODE

WDYEAA

2. SERIAL NUMBER

64-13116

3. NOUN NOMENCLATURE

Helicopter

4. LINE NUMBER

5. MODEL

CH-47A

6. FEDERAL STOCK NUMBER

1520-633-6836

7. STRAC

YES 0  NO

8. UTILIZATION CODE\*

ON

9. SELECTED ITEM

YES  NO

10. HOURS

2398

11. MILES

12. ROUNDS

13. STARTS

0

14. FAILURE DETECTED DURING (Select one use Y or N)

SCHEDULED MAINTENANCE  TEST

NORMAL HANDLING  OPERATION

STORAGE  EJECT

INSPECTION  OTHER

15. FIRST INDICATION OF TROUBLE (Select one use Y or N)

OPERATIVE  INSUPERATIVE

OVERHEATING  LOW PERFORMANCE

OUT OF ADJUSTMENT  OTHER

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE OVERHAUL AND DIAGNOSTIC PROCEDURE IN EQUIPMENT (Do not prescribe repairs)

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750**  
**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its combination or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

**AT THE ORGANIZATIONAL LEVEL**

- a. Requesting repairs and maintenance services.
- b. Reporting accomplishment of Modification Work Orders.
- c. Submission of Equipment Improvement Recommendations (EIR).
- d. Reporting receipt of defective material.
- e. It may be used to record maintenance accomplishments.

**AT SUPPORT MAINTENANCE LEVEL**

- a. Recording maintenance work and/or service actually performed.
- b. Reporting the installation of equipment modifications.
- c. Submission of Equipment Improvement Recommendations (EIR).
- d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.
- e. Reporting receipt of defective material.
- f. Requesting maintenance work and/or services between shops of a given field maintenance work and/or services between shops of another field maintenance shop (Intra Shop Maintenance Request).
- g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request).

**AT DEPOT MAINTENANCE LEVEL**

- a. Reporting the installation of equipment modifications.
- b. Submission of Equipment Improvement Recommendations (EIR).

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S).
- a. EMERGENCY EIR'S will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.
  - b. URGENT EIR'S will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
  - c. ROUTINE EIR'S prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY  
24. RECEIVED BY

JULIAN DATE  
11 5 9

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL PLACEMENT (Select one use Y or N)  
 YES  NO

30. EIR'S (Select one use Y or N)  
 EMERGENCY  URGENT  ROUTINE

31. RECOMMENDATION (Select one use Y or N)  
 IMPROVE DESIGN  REVISE PROCEDURE  MODIFY  OTHER (Specify)

32a. ORGANIZATION  
243rd Avn Co

32b. LOCATION  
APO San Francisco 96377

32c. UNIT IDEN CODE  
WDYEAA

32d. SUBMITTED BY  
L. M. S.

33. FEDERAL STOCK NUMBER  
2915-352-6813

34. NOUN NOMENCLATURE  
Pump Submerged

35. OPINION OR REMARKS (DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES, IF AVAILABLE)

1. Mfg Part number 114P4111-3

2. Item Serial No. Unknown

3. TM Number 55-1230-229-24P2 Page 1224 Fig 211 Index 20

4. Last overhaul I/A

5. Quantity Inspected two



**MAINTENANCE REQUEST (EIR)**  
 For use of this form, see TM 38-750; the proponent agency is Office of the Deputy Chief of Staff for Logistics.

\* See reverse of file copy for codes and additional data.

PAGE NO. 1 NO. OF PAGES 2

REPORTS CONTROL SYMBOL  
CSGLD-1047 (R1)

**SECTION I**

CONTROL NUMBER <b>E53234</b>		1a. ORGANIZATION <b>2 43rd Avn Co</b>		b. LOCATION <b>APO San Francisco 96377</b>		c. UNIT IDEN CODE <b>WDYFAA</b>	
2. SERIAL NUMBER <b>64-13116</b>		3. NOUN NOMENCLATURE <b>HELICOPTER</b>		4. LINE NUMBER		5. MODEL <b>CH -47A</b>	
7. STRAC <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		8. UTILIZATION CODE <input type="checkbox"/> C <input checked="" type="checkbox"/> O		9. SELECTED ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		6. FEDERAL STOCK NUMBER <b>1520-633-6836</b>	
14. FAILURE DETECTED DURING (Select one - use Y or X) <input checked="" type="checkbox"/> SCHEDULED MAINTENANCE <input type="checkbox"/> TEST <input type="checkbox"/> STORAGE <input type="checkbox"/> FLIGHT		10. HOURS <b>2393</b>		11. MILES		12. ROUNDS	
<input type="checkbox"/> A) ANDLING <input type="checkbox"/> B) NORMAL OPERATION <input type="checkbox"/> C) INSPECTION <input checked="" type="checkbox"/> D) OTHER		15. PRIMARY INDICATION OF TROUBLE (Select one - use Y or X) <input type="checkbox"/> INOPERATIVE <input checked="" type="checkbox"/> OVERHEATING <input type="checkbox"/> OUT OF ADJUSTMENT		<input type="checkbox"/> E) NOISY <input type="checkbox"/> F) LOW PERFORMANCE <input checked="" type="checkbox"/> G) OTHER		13. STARTS <b>0</b>	
16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)							

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-760.**  
**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

**AT THE ORGANIZATIONAL LEVEL**

- a. Requesting repairs and maintenance services
- b. Reporting accomplishment of Modification Work Orders
- c. Submission of Equipment Improvement Recommendations (EIR)
- d. Reporting receipt of defective materiel
- e. It may be used to record maintenance accomplishments.

**AT SUPPORT MAINTENANCE LEVEL**

- a. Recording maintenance work and/or service actually performed
- b. Reporting the installation of equipment modifications
- c. Submission of Equipment Improvement Recommendations (EIR)
- d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures
- e. Reporting receipt of defective materiel
- f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Inter Shop Maintenance Request)
- g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request)

**AT DEPOT MAINTENANCE LEVEL**

- a. Reporting the installation of equipment modifications
- b. Submission of Equipment Improvement Recommendations (EIR)

**2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's)**

- a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.
- b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
- c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY	24. RECEIVED BY
JULIAN DATE <b>11 59</b>	JULIAN DATE

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL RE-PLACEMENT (Select one - use Y or X) <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	30. EIR (Select one - use Y or X) <input type="checkbox"/> EMERGENCY <input type="checkbox"/> URGENT <input checked="" type="checkbox"/> ROUTINE	31. RECOMMENDATION (Select one - use Y or X) <input type="checkbox"/> IMPROVE DESIGN <input type="checkbox"/> REVISE PROCEDURE <input type="checkbox"/> MODIFY <input checked="" type="checkbox"/> OTHER (Specify)	32a. ORGANIZATION/ACTIVITY <b>243rd Avn Co</b>	c. UNIT IDEN CODE <b>WDYFAA</b>
33. FEDERAL STOCK NUMBER <b>1650-691-3026</b>	34. NOUN NOMENCLATURE <b>HandSola hyd</b>	b. LOCATION <b>AFPO San Francisco 96377</b>	d. SUBMITTED BY <i>S Martin</i>	

- 1. Mfg Part Number **HP M0100-3**
- 2. Item Serial No. **Unknown**
- 3. TM Number **55-1500-200-34P1** Page 752 Fig 117 Index 70
- 4. Indt overhaul **N/A**
- 5. Quantity Inspected **one**



MP CO	MAINTENANCE REQUEST of this form, see TM 38-750; the proponent Agency of the Deputy Chief of Staff for Logistics.	* See reverse of file copy for codes and additional data.	PAGE NO.	NO. OF PAGES	REPORTS CONTROL SYMBOL
			1	2	CSGLD 1047 (RI)

<input type="checkbox"/> WORK REQUEST	<input type="checkbox"/> MWO	<input checked="" type="checkbox"/> LIR	02	ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE
---------------------------------------	------------------------------	---	----	---

1. ITEM NUMBER <b>E53235</b>	1a. ORGANIZATION <b>243rd Avn Co</b>	8. LOCATION <b>APO San Francisco 96377</b>	6. UNIT IDEN CODE <b>WDYEA</b>
---------------------------------	---	---	-----------------------------------

2. SERIAL NUMBER <b>64-13116</b>	3. NOUN NOMENCLATURE <b>Helicopter</b>	4. LINE NUMBER	5. MODEL <b>OH-47A</b>	6. FEDERAL STOCK NUMBER <b>1520-632-6836</b>
-------------------------------------	---	----------------	---------------------------	---

7. STRAC <input type="checkbox"/> YES <input type="checkbox"/> NO	8. UTILIZATION CODE <b>OW</b>	9. SELECTED ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	10. HOURS <b>2398</b>	11. MILES	12. ROUNDS	13. STARTS <b>0</b>
--	----------------------------------	---	--------------------------	-----------	------------	------------------------

14. FAILURE DETECTED DURING (Select one - use Y or X) <input checked="" type="checkbox"/> SCHEDULED MAINTENANCE <input type="checkbox"/> TEST <input type="checkbox"/> STORAGE <input type="checkbox"/> FLIGHT <input type="checkbox"/> HANDLING <input type="checkbox"/> NORMAL OPERATION <input type="checkbox"/> INSPECTION <input checked="" type="checkbox"/> OTHER				15. FIRST INDICATION OF TROUBLE (Select one-use Y or X) <input type="checkbox"/> INOPERATIVE <input type="checkbox"/> OVERHEATING <input type="checkbox"/> OUT OF ADJUSTMENT <input checked="" type="checkbox"/> OTHER			
---	--	--	--	---	--	--	--

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750**

**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- |  |   |  |
|--|---|--|
| <p><b>AT THE ORGANIZATIONAL LEVEL</b></p> <p>a. Requesting repairs and maintenance services.</p> <p>b. Reporting accomplishment of Modification Work Orders.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Reporting receipt of defective material.</p> <p>e. It may be used to record maintenance accomplishments.</p> | <p><b>AT SUPPORT MAINTENANCE LEVEL</b></p> <p>a. Recording maintenance work and/or service actually performed.</p> <p>b. Reporting the installation of equipment modifications.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.</p> <p>e. Reporting receipt of defective material.</p> <p>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra-Shop Maintenance Request).</p> <p>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter-Shop Maintenance Request).</p> | <p><b>AT DEPOT MAINTENANCE LEVEL</b></p> <p>a. Reporting the installation of equipment modifications.</p> <p>b. Submission of Equipment Improvement Recommendations (EIR).</p> |
|--|---|--|

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's)

a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.

b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.

c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY	24. RECEIVED BY
JULIAN DATE <b>1159</b>	JULIAN DATE

SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION			
29. NORMAL REPLACEMENT (Select one - use Y or X) <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	30. EIR (Select one - use Y or X) <input type="checkbox"/> EMERGENCY <input checked="" type="checkbox"/> URGENT <input checked="" type="checkbox"/> ROUTINE	31. RECOMMENDATION (Select one - use Y or X) <input checked="" type="checkbox"/> IMPROVE DESIGN <input type="checkbox"/> REVISE PROCEDURE <input type="checkbox"/> MODIFY <input checked="" type="checkbox"/> OTHER/Specify	32a. ORGANIZATION/ACTIVITY <b>243rd Avn Co</b>
33. FEDERAL STOCK NUMBER <b>1650-055-7537</b>	34. NOUN NOMENCLATURE <b>Accumulator H yd</b>	32b. LOCATION <b>APO San Francisco 96377</b>	6. UNIT IDEN CODE <b>WDYEA</b>

35. OPINION OR REMARKS DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED ATTACH PHOTOS OR SKETCHES, IF AVAILABLE
1. Mfg Part Number <b>11/HS123-1</b>
2. Item Serial No <b>Unknown</b>
3. TM Number <b>52-120-200-24P1</b> Page 754 Fig 117 Index 32
4. Last Overhaul <b>N/A</b>
5. Quantity Inspected <b>One</b>

**"FOR OFFICIAL USE ONLY"**





**SECTION I**

CONTROL NUMBER: **E53236**

TO ORGANIZATION: **243rd Avn Co**

LOCATION: **APO San Francisco 96377**

UNIT IDEN CODE: **WDYEAA**

SERIAL NUMBER: **64-13116**

3. NOUN NOMENCLATURE: **Helicopter**

4. LINE NUMBER: **CH-47 A**

5. MODEL: **CH-47 A**

6. FEDERAL STOCK NUMBER: **1520-633-6336**

7. STRAC:  YES  NO

8. UTILIZATION CODE:  ON

9. SELECTED ITEM:  YES  NO

10. HOURS: **2398**

11. MILES: **0**

12. ROUNDS: **0**

13. STARTS: **0**

14. FAILURE DETECTED DURING (Select one - use I or X)  
 SCHEDULED MAINTENANCE  TEST  STORAGE  FLIGHT  
 HANDLING  NORMAL OPERATION  INSPECTION  OTHER

15. FIRST INDICATION OF TROUBLE (Select one - use I or X)  
 INOPERATIVE  OVERHEATING  OUT OF ADJUSTMENT  
 NOISY  LOW PERFORMANCE  OTHER

16. DESCRIBE DEFECTS OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750.  
 USES AND INSTRUCTIONS

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- AT THE ORGANIZATIONAL LEVEL**
- a. Requesting repairs and maintenance services
  - b. Reporting accomplishment of Modification Work Orders
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Reporting receipt of defective material
  - e. It may be used to record maintenance accomplishments.
- AT SUPPORT MAINTENANCE LEVEL**
- a. Recording maintenance work and/or services actually performed
  - b. Reporting the installation of equipment modifications
  - c. Submission of Equipment Improvement Recommendations (EIR)
  - d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures
  - e. Reporting receipt of defective material
  - f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Inter Shop Maintenance Request)
  - g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request)
- AT DEPOT MAINTENANCE LEVEL**
- a. Reporting the installation of equipment modifications
  - b. Submission of Equipment Improvement Recommendations (EIR)

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S)

- a. EMERGENCY EIR'S will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III, will be submitted with the message number indicated as part of the narrative remarks in Block 35.
- b. URGENT EIR'S will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
- c. ROUTINE EIR'S prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY: \_\_\_\_\_

24. RECEIVED BY: \_\_\_\_\_

JULIAN DATE: **1159**

DIAGN. DATE: \_\_\_\_\_

*7172*

*213-58*

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

29. NORMAL RECOMMENDATION (Select one - use I or X)  
 YES  NO

30. RECOMMENDATION (Select one - use I or X)  
 EMERGENCY  URGENT  ROUTINE

31. RECOMMENDATION (Select one - use I or X)  
 IMPROVE DESIGN  REVISE PROCEDURE  MODIFY

32. ORGANIZATION/ACTIVITY: **243rd Avn Co**

LOCATION: **APC San Francisco 96377**

UNIT IDEN CODE: **WDYEAA**

33. FEDERAL STOCK NUMBER: **5930-843-2346**

34. NOUN NOMENCLATURE: **Switch Procedure**

35. OPINION OR REMARKS (DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES IF AVAILABLE)  
**CONFIDENTIAL USE ONLY**

1. Mfg Part Number: **11/PS407-1**

2. Item Serial No.: **Unknown**

3. TM Number: **55-15 --202-34P2 Page 1241 Fig 213 Index 58**

4. Last Overhaul: **11/2**

5. Quantity Inspected: **One**



**SECTION I**       ACRQ REQUEST       MWO       EIR       02 ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE

**CONTROL NUMBER**      **1a. ORGANIZATION**      **b. LOCATION**      **c. UNIT IDEN CODE**  
 E53243      243rd Avn Co      APO San Francisco 96377      MDYEAA

**2. SERIAL NUMBER**      **3. NOUN NOMENCLATURE**      **4. LINE NUMBER**      **5. MODEL**      **6. FEDERAL STOCK NUMBER**  
 64-13116      Helicopter           CH-47A      1520-633-6836

**7. STRAC**      **B. UTILIZATION CODE\***      **9. SELECTED ITEM**      **10. HOURS**      **11. MILES**      **12. ROUNDS**      **13. STARTS**  
 YES    0     NO     ON     YES     NO    2398             0

**14. FAILURE DETECTED DURING (Select one - use V or X)**      **15. FIRST INDICATION OF TROUBLE (Select one-use V or X)**  
 A SCHEDULED MAINTENANCE     B TEST     C STORAGE     D FLIGHT     E INOPERATIVE     F OVERHEATING     G OUT OF ADJUSTMENT  
 H HANDLING     I NORMAL OPERATION     J INSPECTION     K OTHER     L NOISY     M LOW PERFORMANCE     N OTHER

**16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)**

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750**  
**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- |   |  |   |
|---|--|---|
| <p><b>AT THE ORGANIZATIONAL LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Requesting repairs and maintenance services.</li> <li>b. Reporting accomplishment of Modification Work Orders.</li> <li>c. Submission of Equipment Improvement Recommendations (EIR).</li> <li>d. Reporting receipt of defective material.</li> <li>e. It may be used to record maintenance accomplishments.</li> </ul> | <p><b>AT SUPPORT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Recording maintenance work and/or service actually performed.</li> <li>b. Reporting the installation of equipment modifications.</li> <li>c. Submission of Equipment Improvement Recommendations (EIR).</li> <li>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.</li> <li>e. Reporting receipt of defective material.</li> <li>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Ultra Shop Maintenance Request).</li> <li>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request).</li> </ul> | <p><b>AT DEPOT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Reporting the installation of equipment modifications.</li> <li>b. Submission of Equipment Improvement Recommendations (EIR).</li> </ul> |
|---|--|---|

**2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's)**

- a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.
- b. URGENT EIR's will be air mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
- c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

**23. SUBMITTED BY**      **24. RECEIVED BY**

\_\_\_\_\_  
 \_\_\_\_\_

**JULIAN DATE**      **JULIAN DATE**

1159      \_\_\_\_\_

**SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION**

**29. NORMAL REPLACEMENT (Select one - use V or X)**      **30. URGENT/ROUTINE (Select one - use V or X)**      **31. RECOMMENDATION (Select one - use V or X)**      **32a. ORGANIZATION/ACTIVITY**      **c. UNIT IDEN CODE**  
 YES     URGENT     IMPROVE DESIGN     REVISE PROCEDURE    243rd Avn Co    MDYEAA  
 NO     ROUTINE     MODIFY     OTHER (Specify)    **b. LOCATION**    **d. SUBMITTED BY**  
 APO San Francisco 96377    L Martin

**33. FEDERAL STOCK NUMBER**      **34. NOUN NOMENCLATURE**      **35. OPINION OR REMARKS - DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED - ATTACH PHOTOS OR SKETCHES, IF AVAILABLE**  
 2915-739-2548      Valve, Gate      \_\_\_\_\_

**1. Mfg part number**      114PS401-1

**2. Item Serial No.**      Unknown

**3. TM Number**      55-1520-209 -34P2      Page 1235      Fig. 213      Index 4

**4. Last Overhaul**      H/A

**5. Quantity Inspected**      three



MAINTENANCE REQUEST		* See reverse of file copy for codes and additional data.	PAGE NO. 1	OF PAGES 2	REPORTS CONTROL SYMBOL CSGLD 1047 (R1)
For use of this form, see TM 38-750; the proper Office of the Deputy Chief of Staff for Logistics.					
SECTION I		<input type="checkbox"/> WORK REQUEST	<input type="checkbox"/> MWO	<input checked="" type="checkbox"/> EIR	69 ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE
CONTROL NUMBER <b>E53244</b>	ORGANIZATION <b>243rd Avn Co</b>	LOCATION <b>APO San Francisco 96377</b>		UNIT IDEN CODE <b>WDYEAA</b>	
2. SERIAL NUMBER <b>64-13116</b>	3. NOUN NOMENCLATURE <b>Helicopter</b>	4. LINE NUMBER	5. MODEL <b>CH-47A</b>	6. FEDERAL STOCK NUMBER <b>1520-633-6836</b>	
7. STRAC <input type="checkbox"/> YES <b>0</b> <input type="checkbox"/> NO	8. UTILIZATION CODE* <input type="checkbox"/> ON	9. SELECTED ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		10. HOURS <b>2398</b>	11. MILES
14. FAILURE DETECTED DURING (Select one - use X)		15. FIRST INDICATION OF TROUBLE (Select one-use X)			
<input type="checkbox"/> A SCHEDULED MAINTENANCE <input type="checkbox"/> B HANDLING <input type="checkbox"/> C TEST <input type="checkbox"/> D NORMAL OPERATION <input type="checkbox"/> E STORAGE <input type="checkbox"/> F REPAIR <input checked="" type="checkbox"/> G OTHER		<input type="checkbox"/> H INOPERATIVE <input checked="" type="checkbox"/> I OVERHEATING <input type="checkbox"/> J NOISY <input type="checkbox"/> K LOW PERFORMANCE <input checked="" type="checkbox"/> L OTHER			
16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)					
<p>PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750.</p> <p>USES AND INSTRUCTIONS</p> <p>1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:</p> <p>AT THE ORGANIZATIONAL LEVEL</p> <p>a. Requesting repairs and maintenance services.</p> <p>b. Reporting accomplishment of Modification Work Orders.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Reporting receipt of defective material.</p> <p>e. It may be used to record maintenance accomplishments.</p> <p>AT SUPPORT MAINTENANCE LEVEL</p> <p>a. Recording maintenance work and/or service actually performed.</p> <p>b. Reporting the installation of equipment modifications.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.</p> <p>e. Reporting receipt of defective material.</p> <p>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra Shop Maintenance Request).</p> <p>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request).</p> <p>AT DEPOT MAINTENANCE LEVEL</p> <p>a. Reporting the installation of equipment modifications.</p> <p>b. Submission of Equipment Improvement Recommendations (EIR).</p> <p>2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR'S)</p> <p>a. EMERGENCY EIR'S will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III, will be submitted with the message number indicated as part of the narrative remarks in Block 35.</p> <p>b. URGENT EIR'S will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.</p> <p>c. ROUTINE EIR'S prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.</p>					
23. SUBMITTED BY		24. RECEIVED BY			
JULIAN DATE		JULIAN DATE			
1159					
SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION					
29. NORMAL REPLACEMENT (Select one - use X)	30. URGENT (Select one - use X)	31. RECOMMENDATION (Select one - use X)		32a. ORGANIZATION/ACTIVITY	3. UNIT IDEN CODE
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> EMERGENCY <input checked="" type="checkbox"/> URGENT <input type="checkbox"/> ROUTINE	<input checked="" type="checkbox"/> A IMPROVE DESIGN <input type="checkbox"/> B REVISE PROCEDURE <input type="checkbox"/> C MODIFY <input checked="" type="checkbox"/> D OTHER (Specify)		<b>243rd Avn Co</b>	<b>WDYEAA</b>
23. FEDERAL STOCK NUMBER	34. NOUN NOMENCLATURE	35. OPINION OR REMARKS - DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES, IF AVAILABLE.		d. SUBMITTED BY	
<b>1650-128-7429</b>	<b>Pump, Axial</b>			<b>S. Martin</b>	
1. Mfg part number	<b>114HS127-3</b>				
2. Item Serial No.	<b>Unknown</b>				
3. TM Number	<b>55-1520-209-3/P-1 Page 551 Fig. 13 Index 12</b>				
4. Last Overhaul	<b>1/1</b>				
5. Quantity Inspected	<b>10</b>				



MAINTENANCE REQUEST		* See reverse of file copy for codes and additional data.		PAGE NO.	PAGES	REPORTS CONTROL SYMBOL	
For use of this form, see TM 38-750; the proper agency is Office of the Deputy Chief of Staff for Logistics.				1	2	CSGLD-1047 (RI)	
SECTION I		<input type="checkbox"/> WORK REQUEST		<input checked="" type="checkbox"/> MWO		<input checked="" type="checkbox"/> EIR	
CONTROL NUMBER		1a. ORGANIZATION		b. LOCATION		c. ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE	
E53245		2 43rd Avn Co		APO San Francisco 96 377		WDYBAA	
2. SERIAL NUMBER		3. NOUN NOMENCLATURE		5. MODEL		6. FEDERAL STOCK NUMBER	
64-13 116		Helicopter		GH-47A		1520-633-6336	
7. STRAC		8. UTILIZATION CODE*		9. SELECTED ITEM		10. HOURS 11. MILES 12. ROUNDS 13. STARTS	
<input type="checkbox"/> YES 0 <input checked="" type="checkbox"/> NO		<input checked="" type="checkbox"/> 0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		2398	
14. FAILURE DETECTED DURING (Select one - use Y or X)				15. FIRST INDICATION OF TROUBLE (Select one-use Y or X)			
<input type="checkbox"/> A SCHEDULED MAINTENANCE <input type="checkbox"/> B HANDLING				<input type="checkbox"/> C TEST <input type="checkbox"/> D STORAGE <input type="checkbox"/> E FLIGHT <input type="checkbox"/> F INOPERATIVE <input type="checkbox"/> G OVERHEATING <input type="checkbox"/> H OUT OF ADJUSTMENT			
<input type="checkbox"/> NORMAL OPERATION <input type="checkbox"/> IMPROPER OPERATION <input checked="" type="checkbox"/> OTHER				<input type="checkbox"/> I NOISY <input type="checkbox"/> J LOW PERFORMANCE <input checked="" type="checkbox"/> K			
16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)							
<p>PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750.</p> <p>USES AND INSTRUCTIONS</p> <p>1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:</p> <p>AT THE ORGANIZATIONAL LEVEL</p> <p>a. Requesting repairs and maintenance services.</p> <p>b. Reporting accomplishment of Modification Work Orders.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Reporting receipt of defective material.</p> <p>e. It may be used to record maintenance accomplishments.</p> <p>AT SUPPORT MAINTENANCE LEVEL</p> <p>a. Recording maintenance work and/or service actually performed.</p> <p>b. Reporting the installation of equipment modifications.</p> <p>c. Submission of Equipment Improvement Recommendations (EIR).</p> <p>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.</p> <p>e. Reporting receipt of defective material.</p> <p>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra-Shop Maintenance Request).</p> <p>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter-Shop Maintenance Request).</p> <p>2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's)</p> <p>a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.</p> <p>b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.</p> <p>c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.</p>							
23. SUBMITTED BY		24. RECEIVED BY					
JULIAN DATE		JULIAN DATE					
1159							
SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION							
29. NORMAL REPLACEMENT (Select one - use Y or X)		31. RECOMMENDATION (Select one - use Y or X)		32a. ORGANIZATION/ACTIVITY		c. UNIT IDEN CODE	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> EMERGENCY <input type="checkbox"/> URGENT <input checked="" type="checkbox"/> ROUTINE		<input type="checkbox"/> IMPROVE DESIGN <input type="checkbox"/> REVISE PROCEDURE <input checked="" type="checkbox"/> MODIFY		243rd Avn Co	
				b. LOCATION		d. SUBMITTED BY	
				APO San Francisco 96377		S Martin	
33. FEDERAL STOCK NUMBER		34. NOUN NOMENCLATURE		35. OPINION OR REMARKS (DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES, IF AVAILABLE)			
2915-9-2-7478		Switch Float					
1. Mfg Part number		FA202-2		"OFFICIAL USE ONLY"			
2. Item Serial No.		Unknown					
3. TM Number		55-1520-209-34P-2		Page 1224		Fig 211 Index 23	
4. Last Overhaul		N/A					
5. Quantity Inspected		two					





1. WORK REQUEST  NWO  EIR  OIR  
 ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE 03

CONTROL NUMBER E53453  
 1A. ORGANIZATION 243rd Avn Co  
 1B. LOCATION APO San Francisco 96377  
 1C. UNIT IDEN CODE WDYTEA

2. SERIAL NUMBER UNK  
 3. NOUN NOMENCLATURE Engine, Turbine  
 4. LINE NUMBER  
 5. MODEL T55-I7  
 6. FEDERAL STOCK NUMBER 2840-981-9717

7. STRAC  YES 0  NO  
 8. UTILIZATION CODE\*  OI  
 9. SELECTED ITEM  YES  NO  
 10. HOURS UNK  
 11. MILES  
 12. ROUNDS  
 13. STARTS UNK

14. FAILURE DETECTED DURING (Select one - use Y or X)  
 A SCHEDULED MAINTENANCE  B HANDLING  
 C TEST  D NORMAL OPERATION  
 E STORAGE  F INSPECTION  
 G FLIGHT  H OTHER  
 15. FIRST INDICATION OF TROUBLE (Select one use Y or X)  
 I INOPERATIVE  J NOISY  
 K OVERHEATING  L LOW PERFORMANCE  
 M OUT OF ADJUSTMENT  N OTHER

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750.  
 USES AND INSTRUCTIONS

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- |  |  |   |
|--|--|---|
| <p><b>AT THE ORGANIZATIONAL LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Requesting repairs and maintenance services.</li> <li>b. Reporting an accomplishment of Modification Work Orders.</li> <li>c. Submission of Equipment Improvement Recommendations (EIR).</li> <li>d. Reporting receipt of defective material.</li> <li>e. It may be used to record maintenance accomplishments.</li> </ul> | <p><b>AT SUPPORT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Recording maintenance work and/or service actually performed.</li> <li>b. Reporting the installation of equipment modifications.</li> <li>c. Submission of Equipment Improvement Recommendations (EIR).</li> <li>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.</li> <li>e. Reporting receipt of defective material.</li> <li>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra Shop Maintenance Request).</li> <li>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter-Shop Maintenance Request).</li> </ul> | <p><b>AT DEPOT MAINTENANCE LEVEL</b></p> <ul style="list-style-type: none"> <li>a. Reporting the installation of equipment modifications.</li> <li>b. Submission of Equipment Improvement Recommendations (EIR).</li> </ul> |
|--|--|---|
2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's):
- a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.
  - b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.
  - c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY  
 24. RECEIVED BY  
 JULIAN DATE 1159

SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION

29. NORMAL REPLACEMENT  YES  NO  
 30. EIR (Select one - use Y or X)  
 EMERGENCY  URGENT  ROUTINE  
 31. RECOMMENDATION (Select one - use Y or X)  
 IMPROVE DESIGN  REVISE PROCEDURE  
 MODIFY  OTHER (Specify)

32a. ORGANIZATION/ACTIVITY 243rd Avn Co  
 b. LOCATION APO San Francisco 96377  
 c. UNIT IDEN CODE WDYTEA A  
 d. SUBMITTED BY S. Martin

33. FEDERAL STOCK NUMBER 2840-981-9717  
 34. NOUN NOMENCLATURE Torquemeter Drive  
 35. OPINION OR REMARKS DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES, IF AVAILABLE

1. MFG Part No 2-60-040-08  
 2. Item Serial No UNK  
 3. TM Number 55-2840-224-25P Page 175 Fig 56  
 4. Last Overhaul N/A  
 5. Quantity Inspected One



<b>MAINTENANCE REQUEST</b> <small>For use of this form, see TM 38-750; the proxy is the agency is Office of the Deputy Chief of Staff for Logistics.</small>		<small>* See reverse of file copy for codes and additional data.</small>	PAGE NO. <b>1</b>	T6.9GES <b>2</b>	REPORTS CONTROL SYMBOL CSGLD-1047 (R1)
---	--	--	-------------------	------------------	---

SECTION I <input type="checkbox"/> WORK REQUEST <input type="checkbox"/> MWO <input checked="" type="checkbox"/> EIR <input checked="" type="checkbox"/> ON		ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE			
CONTROL NUMBER <b>E53460</b>	1a. ORGANIZATION <b>243rd Avn Co</b>	A. LOCATION <b>APO San Francisco 96377</b>		4. UNIT IDEN CODE <b>W DYFAA</b>	
2. SERIAL NUMBER <b>64-13116</b>	3. NOUN NOMENCLATURE <b>Helicopte r</b>	4. LINE NUMBER	5. MODEL <b>CH-47A</b>	6. FEDERAL STOCK NUMBER <b>1520-633-6836</b>	
7. STRAC <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	8. UTILIZATION CODE <input checked="" type="checkbox"/> ON	9. SELECTED ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		10. HOURS <b>2398</b>	11. MILES
14. FAILURE DETECTED DURING (Select one - use I or V)		15. FIRST INDICATION OF TROUBLE (Select one use I or X)			
<input type="checkbox"/> A SCHEDULED MAINTENANCE <input type="checkbox"/> B HANDLING <input type="checkbox"/> C TEST <input type="checkbox"/> D NORMAL OPERATION <input type="checkbox"/> E STORAGE <input type="checkbox"/> F INSPECTION <input type="checkbox"/> G FLIGHT <input checked="" type="checkbox"/> H OTHER		<input type="checkbox"/> I INOPERATIVE <input type="checkbox"/> J OVERHEATING <input checked="" type="checkbox"/> K OUT OF ADJUSTMENT <input type="checkbox"/> L NOISY <input type="checkbox"/> M LOW PERFORMANCE <input checked="" type="checkbox"/> N OTHER			

16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not prescribe repairs)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

PRIOR TO USING THIS FORM READ CAREFULLY THE STEP-BY-STEP INSTRUCTIONS IN TM 38-750  
**USES AND INSTRUCTIONS**

1. When all appropriate entries are made in Section I, THIS FORM BECOMES A FORM PECULIAR to a specific weapon system, item of equipment or its component or separate assembly, or a group of similar items with the same FSN. This Section, when combined with either Section II or III or a combination of all three, provides the basis for controlled maintenance actions. This form will be used for:

- |   |  |   |
|---|--|---|
| <b>AT THE ORGANIZATIONAL LEVEL</b><br>a. Requesting repairs and maintenance services.<br>b. Reporting accomplishment of Modification Work Orders.<br>c. Submission of Equipment Improvement Recommendations (EIR).<br>d. Reporting receipt of defective material.<br>e. It may be used to record maintenance accomplishments. | <b>AT SUPPORT MAINTENANCE LEVEL</b><br>a. Recording maintenance work and/or service actually performed.<br>b. Reporting the installation of equipment modifications.<br>c. Submission of Equipment Improvement Recommendations (EIR).<br>d. Requesting repair of unserviceable components, assemblies and subassemblies as a result of direct exchange procedures.<br>e. Reporting receipt of defective material.<br>f. Requesting maintenance work and/or services between shops of a given field maintenance shop (Intra Shop Maintenance Request).<br>g. Requesting maintenance work and/or services of another field maintenance unit or activity within the same echelon or at a higher echelon (Inter Shop Maintenance Request). | <b>AT DEPOT MAINTENANCE LEVEL</b><br>a. Reporting the installation of equipment modifications.<br>b. Submission of Equipment Improvement Recommendations (EIR). |
|---|--|---|

2. SUBMITTING SEPARATE EQUIPMENT IMPROVEMENT RECOMMENDATIONS (EIR's):  
 a. EMERGENCY EIR's will be submitted to the designated Department of the Army agency by electrical message. A follow-up DA Form 2407, checked "Emergency" in Section III will be submitted with the message number indicated as part of the narrative remarks in Block 35.  
 b. URGENT EIR's will be air-mailed to the designated Department of the Army agency. Check "Urgent" in Section III.  
 c. ROUTINE EIR's prepared as a separate action will require only normal mailing of the NMP Copy 2 to the designated Department of the Army agency. Check "Routine" in Section III.

23. SUBMITTED BY	24. RECEIVED BY
JULIAN DATE <b>1159</b>	JULIAN DATE

SECTION III - EQUIPMENT IMPROVEMENT RECOMMENDATION			
29. NORMAL RE-PLACEMENT (Select one - use I or X) <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	30. EIR (Select one - use I or X) <input type="checkbox"/> EMERGENCY <input checked="" type="checkbox"/> URGENT <input type="checkbox"/> ROUTINE	31. RECOMMENDATION (Select one - use I or X) <input checked="" type="checkbox"/> IMPROVE DESIGN <input type="checkbox"/> REVISE PROCEDURE <input type="checkbox"/> MODIFY <input checked="" type="checkbox"/> OTHER (Specify)	32a. ORGANIZATION/ACTIVITY <b>243rd Avn Co</b>
		b. LOCATION <b>APO San Francisco 96377</b>	c. UNIT IDEN CODE <b>WDTEAA</b>
		d. SUBMITTED BY <i>S Martin</i>	

33. FEDERAL STOCK NUMBER <b>2995-120-5226</b>	34. NOUN NOMENCLATURE <b>Actuator</b>	35. OPINION OR REMARKS DESCRIBE CONDITIONS UNDER WHICH FAILURE OCCURRED. ATTACH PHOTOS OR SKETCHES, IF AVAILABLE
1. Mfg Part No <b>11 4P3205-2</b>	2. Item Serial No <b>Unknown</b>	<b>"FOR OFFICIAL USE ONLY"</b> Page 381 Fig 66 Index 10
3. TM Number <b>55-1520-209-34P1</b>	4. Last Overhaul <b>N/A</b>	
5. Quantity Inspected <b>One</b>		



PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8104	
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade, JP-4				SPEC NO. MIL-T-5624H		
SAMPLE SUBMITTED BY (Installation) THAAF				AMT PROD SAMPLE REPRESENTS N/A		
MANUFACTURER OR SUPPLIER OF PRODUCT				SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Point #5		
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.		ITEM NO.	FSN	
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE TAKEN 31 May 71		
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238				DATE SAMPLE REC 31 May 71		
				DATE TESTS STARTED 31 May 71		
				DATE TESTS COMPL 31 May 71		
TEST		SPEC/QUAL	RESULT	TEST	SPEC/QUAL	RESULT
1. GRAVITY (API/SP GR 600/600F TOP				27. WATER AND SEDIMENT % VOL MAX		
a.	MID			28. FSII % VOL TOP		
b.	BOT			a.		
c.	AVG	45-57	55.8	b.		
2. APPEARANCE/WORKMANSHIP		REPORT	C1/Br	c.		
3. COLOR VISUAL		REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)				30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN				a.		
c. SAYB AFTER HEAT MIN				31. SULFIDES (Tank Water BTMS)		
d. ODOR				32. WATER SEPAROMETER INDEX MIN		
5. DISTILLATION 1BP OF		REPORT	138	33. % ASH PLAIN/SULF MAX		
a.	10 % REC. EVAP AT	REPORT	214	34. % LEAD		
b.	% REC. EVAP AT 290°F	20 min	43	35. % PHOSPHORUS		
c.	% REC. EVAP AT 370°F	50 min	78	36. % CHLORINE		
d.	% REC. EVAP AT 400°F	REPORT	88	37. BURNING TEST (16 hrs)		
e.	% REC. EVAP AT 470°F	90 min	--	38. KIN CS/SSU AT OF		
f.	% RESIDUE END POINT	REPORT	156	a.		
g.	% LOSS max	1.5	1.0	b.		
h.	% RESIDUE max	1.5	1.0	c.		
i. 10% + 50% EVAP OF MIN				d.		
6. ENGINE RATING Q.M. MOTOR METHOD				39. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD				40. EVAP LOSS % MAX		
b. LMR AVIATION METHOD				41. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD				42. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN				43. ACID NO/BASE NO MAX		
7. RVP (PSI)		2.0-3.0	2.3	44. CHANNEL PT OF MAX		
8. GUM EXISTENT MG/100 ML MAX				45. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX				46. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX				47. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX				a.		
9. TEL/TML (ML/GM/GAL) MAX				b.		
10. OXIDATION STABILITY MINUTES				48. SEQ 3. MLS MAX (TND/STAB)		
11. DR TEST/MERC % MAX				49. PENETRATION UNWORKED 77°F		
12. SULFUR BY LAMP BOMB % MAX				a.		
13. FREEZING PT OF				50. PENETRATION WORKED 77°F		
14. CORROSION COPPER STRIP				51. DROP PT/MELT PT OF MIN		
15. AROMATICS % VOL MAX				52. CORR AND OXIDATION STAB		
16. OLEFINS % VOL MAX				53. SWELLING SYN RUBBER %		
17. SMOKE POINT MM MIN				54. LOW TEMP STABILITY		
18. SMOKE VOLAT INDEX MIN				55. SALT SPRAY TEST		
19. ANILINE PT OF/ANILINE GRAY PROD MIN				56. WORK STABILITY		
20. FLASH/FIRE POINT OF MIN				57. WATER STABILITY		
21. CLOUD POINT OF MAX				58. THICKENER TYPE		
22. POUR POINT OF MAX				59. THICKENER CONTENT %		
23. WATER REACT INTERFACE RATING MAX				60. CORROSION PROTECTION		
a.				61. REMOVAL		
b.				62. APPARENT VISC AT OF		
24. CARBON RESIDUE % W: MAX				a.		
25. WATER % VOL MAX				b.		
26. SEDIMENT % VOL MAX				63. SHEAR RATE POISES		
REMARKS				64. SED CONTAM. MILLIPORE, MG/L. MAX		2.0 0.1
PRODUCT TESTED ON GRADE				65. EFFECTIVENESS OF FILTRATION		
DATE FORWARDED		SIGNATURE		TITLE		
18 June 71		James E. Lawton		Lab NOIC		

7A FORM 1 NOV 67 2077

EDITION OF 1 MAR 62, IS OBSOLETE.  
FOR OFFICIAL USE ONLY

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8105
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade, JP-4				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS N/A		
MANUFACTURER OR SUPPLIER OF PRODUCT				SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Point #8	
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	FSN	DATE SAMPLE TAKEN 31 May 71
QUAL NC.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE REC 31 May 71	
NAME AND LOCATION OF LABORATORY 959th OI DET PPL(M) APO 96238				DATE TESTS STARTED 31 May 71	
				DATE TESTS COMPL 31 May 71	
TEST		SPEC/QUAL	RESULT	TEST	
1. GRAVITY (API/SP GR 60°/60°F TOP				27. WATER AND SEDIMENT % VOL MAX	
a.	MID			28. FSII % VOL TOP	
b.	BOT			a.	MID
c.	AVG	45-57	55.8	b.	BOT
2. APPEARANCE/WORKMANSHIP		REPORT	CL/Bc	c.	AVG
3. COLOR VISUAL		REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL	
a. HELLIGE (Colorimeter)				30. THERMAL STABILITY INCHES HG	
b. ASTM MAX/SAYB MIN				a.	PREHEATER RATING
c. SAYB AFTER HEAT MIN				31. SULFIDES (Tank Water BTMS)	
d. ODOR				32. WATER SEPAROMETER INDEX MIN	
5. DISTILLATION 1BP OF		REPORT	140	33. % ASH PLAIN/SULF MAX	
a.	10 % REC. EVAP AT 290°F	REPORT	220	34. % LEAD	
b.	% REC. EVAP AT 370°F	20 min	42	35. % PHOSPHORUS	
c.	% REC. EVAP AT 400°F	50 min	78	36. % CHLORINE	
d.	% REC. EVAP AT 470°F	REPORT	87	37. BURNING TEST (16 hrs)	
e.	% REC. EVAP AT 470°F	90 min	—	38. KIN CS/SSU AT OF	
f.	***** END POINT	REPORT	456	a.	KIN CS/SSU AT OF
g.	% LOSS	MAX	1.5	b.	KIN CS/SSU AT OF
h.	% RESIDUE	MAX	1.5	c.	KIN CS/SSU AT OF
i. 10% + 50% EVAP OF MIN				d.	SSF AT OF
6. ENGINE RATING O.N. MOTOR METHOD				e. VISCOSITY INDEX MIN	
a. ON RESEARCH METHOD				39. EVAP LOSS % MAX	
b. LMR AVIATION METHOD				40. PRECIPITATION NO MAX	
c. RMR SUPER CH METHOD				41. SEPARATION % MAX	
d. CETANE NUMBER/INDEX MIN				42. ACID NO/BASE NO MAX	
7. RVP (PSI)		2.0-3.0	2.1	43. CHANNEL PT OF MAX	
8. GUM EXISTENT MG/100 ML MAX				44. SAPONIFICATION NO MAX	
GUM (Wash) MG/100 ML MAX				45. DIELECTRIC STRENGTH KV MIN	
GUM POTENTIAL MG/100 ML MAX				46. FOAM SEQ 1. MLS MAX (TND/STAB)	
PRECIPITATE MG/100 ML MAX				a. SEQ 2. MLS MAX (TND/STAB)	
9. TEL/TML (ML/CM/GAL) MAX				b. SEQ 3. MLS MAX (TND/STAB)	
10. OXIDATION STABILITY MINUTES				47. PENETRATION UNWORKED 77°F	
11. DR TEST/MERC % MAX				a. PENETRATION WORKED 77°F	
12. SULFUR BY LAMP BOMB % MAX				48. DROP PT/MELT PT OF MIN	
13. FREEZING PT OF				49. CORR AND OXIDATION STAB	
14. CORROSION COPPER STRIP				50. SWELLING SYN RUBBER %	
15. AROMATICS % VOL MAX				51. LOW TEMP STABILITY	
16. OLEFINS % VOL MAX				52. SALT SPRAY TEST	
17. SMOKE POINT MM MIN				53. WORK STABILITY	
18. SMOKE VOLAT INDEX MIN				54. WATER STABILITY	
19. ANILINE PT OF/ANILINE GRAY PROD MIN				55. THICKENER TYPE	
20. FLASH/FIRE POINT OF MIN				56. THICKENER CONTENT %	
21. CLOUD POINT OF MAX				57. CORROSION PROTECTION	
22. POUR POINT OF MAX				58. REMOVAL	
23. WATER REACT INTERFACE RATING MAX				59. APPARENT VISC AT OF	
a. VOLUME CHANGE MAX				a. SHEAR RATE POISES	
24. CARBON RESIDUE % WT MAX				60. SED CONTAM. MILLIPORE, MG/L. MAX	
25. WATER % VOL MAX				61. EFFECTIVENESS OF FILTRATION	
26. SEDIMENT % VOL MAX				62. OTHER (Specify) FREE WATER	
REMARKS					

PRODUCT TESTED ON GRADE

DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Lawton</i>	TITLE Lab NCOIC
------------------------------	-------------------------------------	--------------------

DA FORM 2077  
1 NOV 67

EDITION OF 1 MAR 62, IS OBSOLETE.

FOR OFFICIAL USE ONLY

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8106	
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade, JP-4				SPEC NO. MIL-T-5624H		
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS N/A			
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Point #10			
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	FSN	DATE SAMPLE TAKEN 31 May 71	
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE REC 31 May 71		
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238				DATE TESTS STARTED 31 May 71		
				DATE TESTS COMPL 31 May 71		
TEST		SPEC/QUAL	RESULT	TEST	SPEC/QUAL RESULT	
1. GRAVITY PAPI/SP GR 600/600F TOP				27. WATER AND SEDIMENT % VOL MAX		
a.	MID			28. FSII % VOL TOP		
b.	BOT			a.	MID	
c.	AVG	45-57	55.8	b.	BOT	
2. APPEARANCE/WORKMANSHIP		REPORT	Cl/Br	c.	AVG	.10-.15 .12
3. COLOR VISUAL		REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)				30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN				a. PREHEATER RATING		
c. SAYB AFTER HEAT MIN				31. SULFIDES (Tank Water BTMS)		
4. ODOR				32. WATER SEPAROMETER INDEX MIN		
5. DISTILLATION IBP OF		REPORT	146	33. % ASH PLAIN/SULF MAX		
a.	10 % REC. EVAP AT OF	REPORT	220	34. % LEAD		
b.	% REC. EVAP AT 290 OF	20 min	46	35. % PHOSPHORUS		
c.	% REC. EVAP AT 370 OF	50 min	80	36. % CHLORINE		
d.	% REC. EVAP AT 400 OF	REPORT	88	37. BURNING TEST (16 hrs)		
e.	% REC. EVAP AT 470 OF	90 min	--	38. KIN CS/SSU AT OF		
f.	% ***** END POINT	REPORT	458	a.	KIN CS/SSU AT OF	
g.	% LOSS MAX	1.5	1.0	b.	KIN CS/SSU AT OF	
h.	% RESIDUE MAX	1.5	1.0	c.	KIN CS/SSU AT OF	
i.	10% + 80% EVAP OF MIN			d.	SSF AT OF	
6. ENGINE RATING O.N. MOTOR METHOD				39. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD				40. EVAP LOSS % MAX		
b. LMR AVIATION METHOD				41. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD				42. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN				43. ACID NO/BASE NO MAX		
7. RVP (PSI)		2.0-3.0	2.2	44. CHANNEL PT OF MAX		
8. GUM EXISTENT MG/100 ML MAX				45. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX				46. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX				47. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX				a. SEQ 2. MLS MAX (TND/STAB)		
9. TEL/TML (ML/GM/GAL) MAX				b. SEQ 3. MLS MAX (TND/STAB)		
10. OXIDATION STABILITY MINUTES				48. PENETRATION UNWORKED 77 OF		
11. DR TEST/MERC % MAX				a. PENETRATION WORKED 77 OF		
12. SULFUR BY LAMP BOMB % MAX				49. DROP PT/MELT PT OF MIN		
13. FREEZING PT OF				50. CORR AND OXIDATION STAB		
14. CORROSION COPPER STRIP				51. SWELLING SYN RUBBER %		
15. AROMATICS % VOL MAX				52. LOW TEMP STABILITY		
16. OLEFINS % VOL MAX				53. SALT SPRAY TEST		
17. SMOKE POINT MM MIN				54. WORK STABILITY		
18. SMOKE VOLAT INDEX MIN				55. WATER STABILITY		
19. ANILINE PT OF/ANILINE GRAY PROD MIN				56. THICKENER TYPE		
20. FLASH/FIRE POINT OF MIN				57. THICKENER CONTENT %		
21. CLOUD POINT OF MAX				58. CORROSION PROTECTION		
22. POUR POINT OF MAX				59. REMOVAL		
23. WATER REACT INTERFACE RATING MAX				a. APPARENT VISC AT OF		
a. VOLUME CHANGE MAX				a. SHEAR RATE POISES		
24. CARBON RESIDUE % WT MAX				60. SED CONTAM. MILLIPORE, MG/L. MAX		2.0 0.2
25. WATER % VOL MAX				61. EFFECTIVENESS OF FILTRATION		
26. SEDIMENT % VOL MAX				62. OTHER (Specify) FREE WATER		NONE NONE

REMARKS  
PRODUCT TESTED ON GRADE

DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Lawton</i>	TITLE James E. Lawton	TITLE Lab NCOIC
------------------------------	-------------------------------------	--------------------------	--------------------



PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8107
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade, JP-4				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS N/A		
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) AC-23 Tanker		
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	FSN	DATE SAMPLE TAKEN 31 May 71
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE REC 31 May 71	
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238		<input type="checkbox"/> FUEL BULK STORAGE	<input type="checkbox"/> ROUTINE SURVEILLANCE	DATE TESTS STARTED 31 May 71	
		<input type="checkbox"/> FUEL PACKAGED	<input type="checkbox"/> PROCUREMENT ORIGIN	DATE TESTS COMPL 31 May 71	
		<input type="checkbox"/> ALLIED PRODUCTS	<input type="checkbox"/> PROCUREMENT		
		<input type="checkbox"/> FILTER EFFECTIVENESS	<input type="checkbox"/> SPECIAL		
		<input type="checkbox"/> QUALIFICATION CONTRACT	<input type="checkbox"/> DEPOT		
TEST	SPEC/QUAL	RESULT	TEST	SPEC/QUAL	RESULT
1. GRAVITY @API/SP GR 60°/60°F TOP			27. WATER AND SEDIMENT % VOL MAX		
a. MID			28. FSII % VOL TOP		
b. BOT			a. MID		
c. AVG	45-57	56.0	b. BOT		
2. APPEARANCE/WORKMANSHIP	REPORT	Cl/Br	c. AVG	10-15	.11
3. COLOR VISUAL	REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)			30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN			a. PREHEATER RATING		
c. SAYB AFTER HEAT MIN			31. SULFIDES (Tank Water BTMS)		
4. ODOR			32. WATER SEPAROMETER INDEX MIN		
5. DISTILLATION IBP OF	REPORT	146	33. % ASH PLAIN/SULF MAX		
a. 10 % REC - EVAP AT 290°F	REPORT	218	34. % LEAD		
b. % REC - EVAP AT 370°F	20 min	42	35. % PHOSPHORUS		
c. % REC - EVAP AT 400°F	50 min	79	36. % CHLORINE		
d. % REC - EVAP AT 400°F	REPORT	88	37. BURNING TEST (16 hrs)		
e. % REC - EVAP AT 470°F	90 min	-	38. KIN CS/SSU AT OF		
f. % LOSS END POINT	REPORT	160	a. KIN CS/SSU AT OF		
g. % LOSS max	1.5	1.0	b. KIN CS/SSU AT OF		
h. % RESIDUE max	1.5	1.0	c. KIN CS/SSU AT OF		
i. 10% + 50% EVAP OF MIN			d. SSF AT OF		
6. ENGINE RATING O.N. MOTOR METHOD			e. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD			39. EVAP LOSS % MAX		
b. LMR AVIATION METHOD			40. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD			41. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN			42. ACID NO/BASE NO MAX		
7. RVP (PSI)	2.0-3.0	2.1	43. CHANNEL PT OF MAX		
8. GUM EXISTENT MG/100 ML MAX			44. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX			45. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX			46. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX			a. SEQ 2. MLS MAX (TND/STAB)		
9. TEL/TML (ML/GM/GAL) MAX			b. SEQ 3. MLS MAX (TND/STAB)		
10. OXIDATION STABILITY MINUTES			47. PENETRATION UNWORKED 77°F		
11. DR TEST/MERC % MAX			a. PENETRATION WORKED 77°F		
12. SULFUR BY LAMP BOMB % MAX			48. DROP PT/MELT PT OF MIN		
13. FREEZING PT OF			49. CORR AND OXIDATION STAB		
14. CORROSION COPPER STRIP			50. SWELLING SYN RUBBER %		
15. AROMATICS % VOL MAX			51. LOW TEMP STABILITY		
16. OLEFINS % VOL MAX			52. SALT SPRAY TEST		
17. SMOKE POINT MM MIN			53. WORK STABILITY		
18. SMOKE VOLAT INDEX MIN			54. WATER STABILITY		
19. ANILINE PT OF/ANILINE GRAY PROD MIN			55. THICKENER TYPE		
20. FLASH/FIRE POINT OF MIN			56. THICKENER CONTENT %		
21. CLOUD POINT OF MAX			57. CORROSION PROTECTION		
22. POUR POINT OF MAX			58. REMOVAL		
23. WATER REACT INTERFACE RATING MAX			59. APPARENT VISC AT OF		
a. VOLUME CHANGE MAX			a. SHEAR RATE POISES		
24. CARBON RESIDUE % WT MAX			60. SED CONTAM. MILLIPORE, MG/L. MAX	2.0	0.9
25. WATER % VOL MAX			61. EFFECTIVENESS OF FILTRATION		
26. SEDIMENT % VOL MAX			62. OTHER (Specify) FREE WATER	NONE	NONE
REMARKS PRODUCT TESTED ON GRADE					
DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Sawton</i> James E. Sawton			TITLE Lab NCOIC	

DA FORM 2077  
1 NOV 67

EDITION OF 1 MAR 62, IS OBSOLETE.

FOR OFFICIAL USE ONLY

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8108
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel Aviation Grade, JP-4				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS N/A		
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Point #9		
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	F5N	DATE SAMPLE TAKEN 31 May 71
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE REC 31 May 71	
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238			<input type="checkbox"/> FUEL BULK STORAGE <input type="checkbox"/> ROUTINE SURVEILLANCE <input type="checkbox"/> FUEL PACKAGED <input type="checkbox"/> PROCUREMENT ORIGIN <input type="checkbox"/> ALLIED PRODUCTS <input type="checkbox"/> PROCUREMENT <input type="checkbox"/> FILTER EFFECTIVENESS <input type="checkbox"/> SPECIAL <input type="checkbox"/> QUALIFICATION CONTRACT <input type="checkbox"/> DEPOT		DATE TESTS STARTED 31 May 71
					DATE TESTS COMPL 31 May 71
TEST	SPEC/QUAL	RESULT	TEST	SPEC/QUAL	RESULT
1. GRAVITY CAPI/SP GR 800/800F TOP			27. WATER AND SEDIMENT % VOL MAX		
a. MID			28. F5II % VOL TOP		
b. BOT			a. MID		
c. AVG	45-57	56.0	b. BOT		
2. APPEARANCE/WORKMANSHIP	REPORT	Cl/Br	c. AVG	.10-.15	.12
3. COLOR VISUAL	REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)			30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN			a. PREHEATER RATING		
c. SAYB AFTER HEAT MIN			31. SULFIDES (Tank Water BTMS)		
4. ODOR			32. WATER SEPAROMETER INDEX MIN		
b. DISTILLATION IBP OF	REPORT	112	33. % ASH PLAIN/SULF MAX		
a. 10 % REC - EVAP AT OF	REPORT	218	34. % LEAD		
b. % REC - EVAP AT 290°F	20 min	44	35. % PHOSPHORUS		
c. % REC - EVAP AT 370°F	50 min	78	36. % CHLORINE		
d. % REC - EVAP AT 400°F	REPORT	87	37. BURNING TEST (16 hrs)		
e. % rec ***** 470 OF	90 min	--	38. KIN CS/SSU AT OF		
f. % ***** END POINT	REPORT	458	a. KIN CS/SSU AT OF		
g. % LOSS max	1.5	1.0	b. KIN CS/SSU AT OF		
h. % RESIDUE max	1.5	1.0	c. KIN CS/SSU AT OF		
i. 10% + 50% EVAP OF MIN			d. SSF AT OF		
6. ENGINE RATING O.N. MOTOR METHOD			e. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD			39. EVAP LOSS % MAX		
b. LMR AVIATION METHOD			40. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD			41. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN			42. ACID NO/BASE NO MAX		
7. RVP (PSI)	2.0-3.0	2.2	43. CHANNEL PT OF MAX		
8. GUM EXISTENT MG/100 ML MAX			44. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX			45. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX			46. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX			a. SEQ 2. MLS MAX (TND/STAB)		
9. TEL/TML (ML/GM/GAL) MAX			b. SEQ 3. MLS MAX (TND/STAB)		
10. OXIDATION STABILITY MINUTES			47. PENETRATION UNWORKED 77°F		
11. DR TEST/MERC % MAX			a. PENETRATION WORKED 77°F		
12. SULFUR BY LAMP BOMB % MAX			48. DROP PT/MELT PT OF MIN		
13. FREEZING PT OF			49. CORR AND OXIDATION STAB		
14. CORROSION COPPER STRIP			50. SWELLING SYN RUBBER %		
15. AROMATICS % VOL MAX			51. LOW TEMP STABILITY		
16. OLEFINS % VOL MAX			52. SALT SPRAY TEST		
17. SMOKE POINT MM MIN			53. WORK STABILITY		
18. SMOKE VOL AT INDEX MIN			54. WATER STABILITY		
19. ANILINE PT OF/ANILINE GRAY PROD MIN			55. THICKENER TYPE		
20. FLASH/FIRE POINT OF MIN			56. THICKENER CONTENT %		
21. CLOUD POINT OF MAX			57. CORROSION PROTECTION		
22. POUR POINT OF MAX			58. REMOVAL		
23. WATER REACT INTERFACE RATING MAX			59. APPARENT VISC AT OF		
a. VOLUME CHANGE MAX			a. SHEAR RATE POISES		
24. CARBON RESIDUE % WT MAX			60. SED CONTAM. MILLIPORE, MG/L. MAX	2.0	0.3
25. WATER % VOL MAX			61. EFFECTIVENESS OF FILTRATION		
26. SEDIMENT % VOL MAX			62. OTHER (Specify) FREE WATER	NONE	NONE
REMARKS  PRODUCT TESTED ON GRADE					
DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Lawton</i> James E. Lawton			TITLE Lab NCOIC	

DA FORM 1 NOV 67, 2077

EDITION OF 1 MAR 62, IS OBSOLETE.

FOR OFFICIAL USE ONLY

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8102
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade JP-4				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS N/A		
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Point #2		
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	F3N	DATE SAMPLE TAKEN 31 May 71
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE		DATE SAMPLE REC 31 May 71
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238		<input type="checkbox"/> FUEL BULK STORAGE	<input type="checkbox"/> ROUTINE SURVEILLANCE	DATE TESTS STARTED 31 May 71	
		<input type="checkbox"/> FUEL PACKAGED	<input type="checkbox"/> PROCUREMENT ORIGIN	DATE TESTS COMPL 31 May 71	
		<input type="checkbox"/> ALLIED PRODUCTS	<input type="checkbox"/> PROCUREMENT		
		<input type="checkbox"/> FILTER EFFECTIVENESS	<input type="checkbox"/> SPECIAL		
		<input type="checkbox"/> QUALIFICATION CONTRACT	<input type="checkbox"/> DEPOT		
TEST	SPEC/QUAL	RESULT	TEST	SPEC/QUAL	RESULT
1. GRAVITY @API/SP GR 600/600F TOP			27. WATER AND SEDIMENT % VOL MAX		
a. MID			28. F311 % VOL TOP		
b. BOT			a. MID		
c. AVG	15-57	55.8	b. BOT		
2. APPEARANCE/WORKMANSHIP	REPORT	CL/Br	c. AVG	.10-.15	.12
3. COLOR VISUAL	REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)			30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN			a. PREHEATER RATING		
c. SAYB AFTER HEAT MIN			31. SULFIDES (Tank Water BTMS)		
4. ODOR			32. WATER SEPAROMETER INDEX MIN		
5. DISTILLATION IBP °F	REPORT	139	33. % ASH PLAIN/SULF MAX		
a. 10 % REC. EVAP AT °F	REPORT	215	34. % LEAD		
b. % REC. EVAP AT 290°F	20 min	42	35. % PHOSPHORUS		
c. % REC. EVAP AT 370°F	50 min	77	36. % CHLORINE		
d. % REC. EVAP AT 400°F	REPORT	84	37. BURNING TEST (16 hrs)		
e. % REC. EVAP AT 470°F	90 min	--	38. KIN CS/SSU AT °F		
f. % ***** END POINT	REPORT	458	a. KIN CS/SSU AT °F		
g. % LOSS max	1.5	1.0	b. KIN CS/SSU AT °F		
h. % RESIDUE max	1.5	1.0	c. KIN CS/SSU AT °F		
i. 10% + 80% EVAP °F MIN			d. SSF AT °F		
6. ENGINE RATING O.N. MOTOR METHOD			e. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD			39. EVAP LOSS % MAX		
b. LMR AVIATION METHOD			40. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD			41. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN			42. ACID NO/BASE NO MAX		
7. RVP (PSI)	2.0-3.0	2.2	43. CHANNEL PT °F MAX		
8. GUM EXISTENT MG/100 ML MAX			44. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX			45. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX			46. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX			a. SEQ 2. MLS MAX (TND/STAB)		
9. TEL/TML (ML/GM/GAL) MAX			b. SEQ 3. MLS MAX (TND/STAB)		
10. OXIDATION STABILITY MINUTES			47. PENETRATION UNWORKED 77°F		
11. DR TEST/MERC % MAX			a. PENETRATION WORKED 77°F		
12. SULFUR BY LAMP BOMB % MAX			48. DROP PT/MELT PT °F MIN		
13. FREEZING PT °F			49. CORR AND OXIDATION STAB		
14. CORROSION COPPER STRIP			50. SWELLING SYN RUBBER %		
15. AROMATICS % VOL MAX			51. LOW TEMP STABILITY		
16. OLEFINS % VOL MAX			52. SALT SPRAY TEST		
17. SMOKE POINT MM MIN			53. WORK STABILITY		
18. SMOKE VOLAT INDEX MIN			54. WATER STABILITY		
19. ANILINE PT °F/ANILINE GRAY PROD MIN			55. THICKENER TYPE		
20. FLASH/FIRE POINT °F MIN			56. THICKENER CONTENT %		
21. CLOUD POINT °F MAX			57. CORROSION PROTECTION		
22. POUR POINT °F MAX			58. REMOVAL		
23. WATER REACT INTERFACE RATING MAX			59. APPARENT VISC AT °F		
a. VOLUME CHANGE MAX			a. SHEAR RATE POISES		
24. CARBON RESIDUE % WT MAX			60. SED CONTAM. MILLIPORE, MG/L, MAX	2.0	0.1
25. WATER % VOL MAX			61. EFFECTIVENESS OF FILTRATION		
26. SEDIMENT % VOL MAX			62. OTHER (Specify) FREE WATER	NONE	NONE
REMARKS					
PRODUCT TESTED ON GRADE					
DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Lawton</i>	TITLE James E. Lawton		TITLE Lab NCOIC	

DA FORM 2077  
1 NOV 67

EDITION OF 1 MAR 67 IS OBSOLETE.

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1103)				SAMPLE NO. N/A	LAB REPORT NO. 8110
PRODUCT NOMENCLATURE AND TYPE <b>Turbine Fuel, Aviation Grade, JP-4</b>				SPEC NO. <b>MIL-T-5624H</b>	
SAMPLE SUBMITTED BY (Installation) <b>THAAF</b>			AMT PROD SAMPLE REPRESENTS <b>N/A</b>		
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) <b>UNK</b>		
SAMPLE TAKEN BY (Name) <b>N/A</b>		CONTRACT NO.	ITEM NO.	FSN	DATE SAMPLE TAKEN <b>31 May 71</b>
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE		DATE SAMPLE REC <b>31 May 71</b>
NAME AND LOCATION OF LABORATORY <b>959th QM Det PPL(M) APO 96238</b>		<input type="checkbox"/> FUEL BULK STORAGE	<input type="checkbox"/> ROUTINE SURVEILLANCE		DATE TESTS STARTED <b>31 May 71</b>
		<input type="checkbox"/> FUEL PACKAGED	<input type="checkbox"/> PROCUREMENT ORIGIN		DATE TESTS COMPL <b>31 May 71</b>
		<input type="checkbox"/> ALLIED PRODUCTS	<input type="checkbox"/> PROCUREMENT		
		<input type="checkbox"/> FILTER EFFECTIVENESS	<input type="checkbox"/> SPECIAL		
		<input type="checkbox"/> QUALIFICATION CONTRACT	<input type="checkbox"/> DEPOT		
TEST	SPEC/QUAL	RESULT	TEST	SPEC/QUAL	RESULT
1. GRAVITY @API/SP GR 800/800F TOP			27. WATER AND SEDIMENT % VOL MAX		
a. MID			28. FSII % VOL	TOP	
b. BOT			a. MID	MID	
c. AVG	<b>45-57</b>	<b>55.6</b>	b. BOT	BOT	
2. APPEARANCE/WORKMANSHIP	<b>REPORT</b>	<b>Cl/Br</b>	c. AVG	<b>0.10-0.15</b>	<b>0.11</b>
3. COLOR VISUAL	<b>REPORT</b>	<b>W/W</b>	29. PARTICULATE CONTAMINANT MGS/GAL		
a. HELLIGE (Colorimeter)			30. THERMAL STABILITY INCHES HG		
b. ASTM MAX/SAYB MIN			a. PREHEATER RATING		
c. SAYB AFTER HEAT MIN			31. SULFIDES (Tank Water BTMS)		
4. ODOR			32. WATER SEPAROMETER INDEX MIN		
5. DISTILLATION IBP OF	<b>REPORT</b>	<b>118</b>	33. % ASH PLAIN/SULF MAX		
a. 10 % REC. EVAP AT 290 OF	<b>REPORT</b>	<b>220</b>	34. % LEAD		
b. % REC. EVAP AT 290 OF	<b>20 min</b>	<b>42</b>	35. % PHOSPHORUS		
c. % REC. EVAP AT 370 OF	<b>50 min</b>	<b>80</b>	36. % CHLORINE		
d. % REC. EVAP AT 400 OF	<b>REPORT</b>	<b>0.8</b>	37. BURNING TEST (16 hrs)		
e. % REC. EVAP AT 470 OF	<b>90 min</b>	<b>--</b>	38. KIN CS/SSU AT OF		
f. <del>*****</del> END POINT	<b>REPORT</b>	<b>458</b>	a. KIN CS/SSU AT OF		
g. % LOSS max	<b>1.5</b>	<b>1.0</b>	b. KIN CS/SSU AT OF		
h. % RESIDUE max	<b>1.5</b>	<b>1.0</b>	c. KIN CS/SSU AT OF		
i. 10% + 80% EVAP OF MIN			d. SSF AT OF		
6. ENGINE RATING O.N. MOTOR METHOD			e. VISCOSITY INDEX MIN		
a. ON RESEARCH METHOD			39. EVAP LOSS % MAX		
b. LMR AVIATION METHOD			40. PRECIPITATION NO MAX		
c. RMR SUPER CH METHOD			41. SEPARATION % MAX		
d. CETANE NUMBER/INDEX MIN			42. ACID NO/BASE NO MAX		
7. RVP (PSI)	<b>2.0-3.0</b>	<b>2.2</b>	43. CHANNEL PT OF MAX		
8. GUM EXISTENT MG/100 ML MAX			44. SAPONIFICATION NO MAX		
GUM (Wash) MG/100 ML MAX			45. DIELECTRIC STRENGTH KV MIN		
GUM POTENTIAL MG/100 ML MAX			46. FOAM SEQ 1. MLS MAX (TND/STAB)		
PRECIPITATE MG/100 ML MAX			a. SEQ 2. MLS MAX (TND/STAB)		
9. TEL/TML (ML/GM/GAL) MAX			b. SEQ 3. MLS MAX (TND/STAB)		
10. OXIDATION STABILITY MINUTES			47. PENETRATION UNWORKED 77 OF		
11. DR TEST/MERC 5% MAX			a. PENETRATION WORKED 77 OF		
12. SULFUR BY LAMP BOMB % MAX			48. DROP PT/MELT PT OF MIN		
13. FREEZING PT OF			49. CORR AND OXIDATION STAB		
14. CORROSION COPPER STRIP			50. SWELLING SYN RUBBER %		
15. AROMATICS % VOL MAX			51. LOW TEMP STABILITY		
16. OLEFINS % VOL MAX			52. SALT SPRAY TEST		
17. SMOKE POINT MM MIN			53. WORK STABILITY		
18. SMOKE VOLAT INDEX MIN			54. WATER STABILITY		
19. ANILINE PT OF/ANILINE GRAY PROD MIN			55. THICKENER TYPE		
20. FLASH/FIRE POINT OF MIN			56. THICKENER CONTENT %		
21. CLOUD POINT OF MAX			57. CORROSION PROTECTION		
22. POUR POINT OF MAX			58. REMOVAL		
23. WATER REACT INTERFACE RATING MAX			59. APPARENT VISC AT OF		
a. VOLUME CHANGE MAX			a. SHEAR RATE POISES		
24. CARBON RESIDUE % WT MAX			60. SED CONTAM. MILLIPORE, MG/L. MAX	<b>2.0</b>	<b>1.2</b>
25. WATER % VOL MAX			61. EFFECTIVENESS OF FILTRATION		
26. SEDIMENT % VOL MAX			62. OTHER (Specify) <b>FREE WATER</b>	<b>NONE</b>	<b>NONE</b>
REMARKS <b>PRODUCT TESTED ON GRADE</b>					
DATE FORWARDED <b>18 June 71</b>	SIGNATURE <i>James E. Lawton</i> <b>James E. Lawton</b>			TITLE <b>Lab NCOIC</b>	

DA FORM 2077  
1 NOV 67

EDITION OF 1 MAR 67 IS OBSOLETE.

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1105)				SAMPLE NO. N/A	LAB REPORT NO. 8111
PRODUCT NOMENCLATURE AND TYPE Turbine Fuel, Aviation Grade, JP-4				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF			AMT PROD SAMPLE REPRESENTS 50,000 Gal.		
MANUFACTURER OR SUPPLIER OF PRODUCT			SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) WZIX03		
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	F3N	DATE SAMPLE TAKEN 31 May 71
QUAL NO.	BATCH NO.	FILL DATE	DLVR DATE	DATE SAMPLE REC 31 May 71	
NAME AND LOCATION OF LABORATORY 959th MM DET PPL(M) APO 96238				DATE TESTS STARTED 31 May 71	
				DATE TESTS COMPL 31 May 71	
TEST		SPEC/QUAL	RESULT	TEST	SPEC/QUAL RESULT
1. GRAVITY PAPI/SP GR 600/800F TOP				27. WATER AND SEDIMENT % VOL MAX	
a.	MID			28. F311 % VOL TOP	
b.	BOT			a.	MID
c.	AVG	45-57	56.0	b.	BOT
2. APPEARANCE/WORKMANSHIP		REPORT	Cl/Br	c.	AVG
3. COLOR VISUAL		REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL	
a. HELLIGE (Colorimeter)				30. THERMAL STABILITY INCHES HG	
b. ASTM MAX/SAYD MIN				a. PREHEATER RATING	
c. SAYD AFTER HEAT MIN				31. SULFIDES (Tank Water BTMS)	
4. ODOR				32. WATER SEPAROMETER INDEX MIN	
5. DISTILLATION IBP OF		REPORT	142	33. % ASH PLAIN/SULF MAX	
a.	10 % REC - EVAP AT	REPORT	218	34. % LEAD	
b.	% REC - EVAP AT 200°F	20 min	40	35. % PHOSPHORUS	
c.	% REC - EVAP AT 370°F	50 min	78	36. % CHLORINE	
d.	% REC - EVAP AT 400°F	REPORT	87	37. BURNING TEST (16 hrs)	
e.	% REC - EVAP AT 470°F	90 min	--	38. KIN CS/SSU AT OF	
f.	% <del>RESEARCH</del> END POINT	REPORT	458	a.	KIN CS/SSU AT OF
g.	% LOSS max	1.5	1.0	b.	KIN CS/SSU AT OF
h.	% RESIDUE max	1.5	1.0	c.	KIN CS/SSU AT OF
i.	1.10% + 80% EVAP OF MIN			d.	SSF AT OF
6. ENGINE RATING O.N. MOTOR METHOD				e. VISCOSITY INDEX MIN	
a. ON RESEARCH METHOD				39. EVAP LOSS % MAX	
b. LMR AVIATION METHOD				40. PRECIPITATION NO MAX	
c. RMR SUPER CH METHOD				41. SEPARATION % MAX	
d. CETANE NUMBER/INDEX MIN				42. ACID NO/BASE NO MAX	
7. RVP (PSI)		2.0-3.0	2.2	43. CHANNEL PT OF MAX	
8. GUM EXISTENT MG/100 ML MAX				44. SAPONIFICATION NO MAX	
GUM (Wash) MG/100 ML MAX				45. DIELECTRIC STRENGTH KV MIN	
GUM POTENTIAL MG/100 ML MAX				46. FOAM SEQ 1. MLS MAX (TND/STAB)	
PRECIPITATE MG/100 ML MAX				a. SEQ 2. MLS MAX (TND/STAB)	
9. TEL/TML (ML/GM/GAL) MAX				b. SEQ 3. MLS MAX (TND/STAB)	
10. OXIDATION STABILITY MINUTES				47. PENETRATION UNWORKED 77°F	
11. DR TEST/MERC 5% MAX				a. PENETRATION WORKED 77°F	
12. SULFUR BY LAMP BOMB % MAX				48. DROP PT/MELT PT OF MIN	
13. FREEZING PT OF				49. CORR AND OXIDATION STAB	
14. CORROSION COPPER STRIP				50. SWELLING SYN RUBBER %	
15. AROMATICS % VOL MAX				51. LOW TEMP STABILITY	
16. OLEFINS % VOL MAX				52. SALT SPRAY TEST	
17. SMOKE POINT MM MIN				53. WORK STABILITY	
18. SMOKE VOLAT INDEX MIN				54. WATER STABILITY	
19. ANILINE PT OF/ANILINE GRAY PROD MIN				55. THICKENER TYPE	
20. FLASH/FIRE POINT OF MIN				56. THICKENER CONTENT %	
21. CLOUD POINT OF MAX				57. CORROSION PROTECTION	
22. POUR POINT OF MAX				58. REMOVAL	
23. WATER REACT INTERFACE RATING MAX				59. APPARENT VISC AT OF	
a. VOLUME CHANGE MAX				a. SHEAR RATE POISES	
24. CARBON RESIDUE % WT MAX				60. SED CONTAM. MILLIPORE, MG/L MAX	
25. WATER % VOL MAX				61. EFFECTIVENESS OF FILTRATION	
26. SEDIMENT % VOL MAX				62. OTHER (Specify) FREE WATER	
REMARKS				NONE NONE	
PRODUCT TESTED ON GRADE					
DATE FORWARDED 18 June 71	SIGNATURE <i>James E. Lawton</i>			TITLE Lab NCOIC	

DA FORM 1 NOV 67 2077

SECTION OF 3 MAR 62 IS OBSOLETE.

PETROLEUM PRODUCTS LABORATORY ANALYSIS REPORT (TM 10-1103)				SAMPLE NO. N/A	LAB REPORT NO. 8109
PRODUCT NOMENCLATURE AND TYPE <b>Turbine Fuel, Aviation Grade, JP-4</b>				SPEC NO. MIL-T-5624H	
SAMPLE SUBMITTED BY (Installation) THAAF				AMT PROD SAMPLE REPRESENTS N/A	
MANUFACTURER OR SUPPLIER OF PRODUCT				SOURCE OF SAMPLE (Truck, Tank, Aircraft, etc.) Flight Line	
SAMPLE TAKEN BY (Name) N/A		CONTRACT NO.	ITEM NO.	FSN	DATE SAMPLE TAKEN 31 May 71
QUAL NO.	BATCH NO.	FILL DATE		DLVR DATE	DATE SAMPLE REC 31 May 71
NAME AND LOCATION OF LABORATORY 959th QM DET PPL(M) APO 96238	<input type="checkbox"/> FUEL BULK STORAGE	<input type="checkbox"/> ROUTINE SURVEILLANCE	DATE TESTS STARTED 31 May 71	DATE TESTS COMPL 31 May 71	SPEC/QUAL RESULT
	<input type="checkbox"/> FUEL PACKAGED	<input type="checkbox"/> PROCUREMENT ORIGIN			
	<input type="checkbox"/> ALLIED PRODUCTS	<input type="checkbox"/> PROCUREMENT			
	<input type="checkbox"/> FILTER EFFECTIVENESS	<input type="checkbox"/> SPECIAL			
<input type="checkbox"/> QUALIFICATION CONTRACT	<input type="checkbox"/> DEPOT				
TEST		SPEC/QUAL	RESULT	TEST	
1. GRAVITY PAPl/SP GR 600/500P TOP				27. WATER AND SEDIMENT % VOL MAX	
a. MID				28. FSII % VOL TOP	
b. BOT				a. MID	
c. AVG		45-57	55.9	b. BOT	
2. APPEARANCE/WORKMANSHIP		REPORT	C1/Br	c. AVG .10-.15 .12	
3. COLOR VISUAL		REPORT	W/W	29. PARTICULATE CONTAMINANT MGS/GAL	
a. HELLIGE (Colorimeter)				30. THERMAL STABILITY INCHES HG	
b. ASTM MAX/SAYB MIN				a. PREHEATER RATING	
c. SAYB AFTER HEAT MIN				31. SULFIDES (Tank Water BTMS)	
4. ODOR				32. WATER SEPAROMETER INDEX MIN	
5. DISTILLATION IBP OF		REPORT	142	33. % ASH PLAIN/SULF MAX	
a. 10 % REC. EVAP AT OF		REPORT	216	34. % LEAD	
b. % REC. EVAP AT 290 OF		20 min	40	35. % PHOSPHORUS	
c. % REC. EVAP AT 370 OF		50 min	78	36. % CHLORINE	
d. % REC. EVAP AT 400 OF		REPORT	86	37. BURNING TEST (16 hrs)	
e. % rec ***** 470 OF		90 min	--	38. KIN CS/SSU AT OF	
f. % ***** END POINT		REPORT	459	a. KIN CS/SSU AT OF	
g. % LOSS max		1.5	1.0	b. KIN CS/SSU AT OF	
h. % RESIDUE max		1.5	1.0	c. KIN CS/SSU AT OF	
i. 10% + 50% EVAP OF MIN				d. SSF AT OF	
6. ENGINE RATING O.N. MOTOR METHOD				e. VISCOSITY INDEX MIN	
a. ON RESEARCH METHOD				39. EVAP LOSS % MAX	
b. LMR AVIATION METHOD				40. PRECIPITATION NO MAX	
c. RMR SUPER CH METHOD				41. SEPARATION % MAX	
d. CETANE NUMBER/INDEX MIN				42. ACID NO/BASE NO MAX	
7. RVP (PSI)		2.0-3.0	2.1	43. CHANNEL PT OF MAX	
8. GUM EXISTENT MG/100 ML MAX				44. SAPONIFICATION NO MAX	
GUM (Wash) MG/100 ML MAX				45. DIELECTRIC STRENGTH KV MIN	
GUM POTENTIAL MG/100 ML MAX				46. FOAM SEQ 1. MLS MAX (TND/STAB)	
PRECIPITATE MG/100 ML MAX				a. SEQ 2. MLS MAX (TND/STAB)	
9. TEL/TML (ML/GM/GAL) MAX				b. SEQ 3. MLS MAX (TND/STAB)	
10. OXIDATION STABILITY MINUTES				47. PENETRATION UNWORKED 77 OF	
11. DR TEST/MERC % MAX				a. PENETRATION WORKED 77 OF	
12. SULFUR BY LAMP BOMB % MAX				48. DROP PT/MELT PT OF MIN	
13. FREEZING PT OF				49. CORR AND OXIDATION STAB	
14. CORROSION COPPER STRIP				50. SWELLING SYN RUBBER %	
15. AROMATICS % VOL MAX				51. LOW TEMP STABILITY	
16. OLEFINS % VOL MAX				52. SALT SPRAY TEST	
17. SMOKE POINT MM MIN				53. WORK STABILITY	
18. SMOKE VOLAT INDEX MIN				54. WATER STABILITY	
19. ANILINE PT OF/ANILINE GRAY PROD MIN				55. THICKENER TYPE	
20. FLASH/FIRE POINT OF MIN				56. THICKENER CONTENT %	
21. CLOUD POINT OF MAX				57. CORROSION PROTECTION	
22. POUR POINT OF MAX				58. REMOVAL	
23. WATER REACT INTERFACE RATING MAX				59. APPARENT VISC AT OF	
a. VOLUME CHANGE MAX				a. SHEAR RATE POISES	
24. CARBON RESIDUE % W MAX				60. % SED CONTAM. MILLIPORE. MG/L. MAX	
25. WATER % VOL MAX				61. EFFECTIVENESS OF FILTRATION	
26. SEDIMENT % VOL MAX				62. OTHER (Specify) FREE WATER	
REMARKS				NONE NONE	
PRODUCT TESTED ON GRADE					
DATE FORWARDED 18 June 71		SIGNATURE <i>James E. Lawton</i>		TITLE James E. Lawton	Lab NCOIC

# WEIGHT AND BALANCE CLEARANCE FORM F

TRANSPORT  
(USE REVERSE FOR TACTICAL MISSIONS)

Cross Reference  
RAF Form 2870  
RCAF Form F. 113 C  
ROM 8-81 (8792)

FOR USE IN  
T.O. 1-1B-40  
AN 01-1B-40 &  
TM 55-40.5-9

DATE <b>4 Jun 71</b>	AIRCRAFT TYPE <b>UH-1H</b>	FROM <b>Fuy Hog</b>	HOME STATION <b>10 26377</b>
MISSION/TRIP/FLIGHT NO.	SERIAL NO. <b>67-12116</b>	TO <b>28th Regt, 1st Avn Bde</b>	PILOT <b>10 26377</b>

CONDITION	LIMITATIONS		R E F	ITEM	WEIGHT	INDEX OR MOM/
	TAKEOFF	LANDING				
ALLOWABLE GROSS WEIGHT	13000	13000	1	BASIC AIRCRAFT (From Chart C)	12577	64308
TOTAL AIRCRAFT WEIGHT (Ref. 1)			2	OIL (Gal.)	23	135
OPERATING WEIGHT PLUS ESTIMATED LANDING FUEL WEIGHT			3	CREW (No.)	1000	1800
OPERATING WEIGHT (Ref. 3)			4	CREW'S BAGGAGE		
ALLOWABLE LOAD (Ref. 1) (Use SMAF/EST Appr)			5	STEWARD'S EQUIPMENT		
PERMISSIBLE C.G. TAKEOFF	FROM 30-20	TO 40-40 IN	6	EMERGENCY EQUIPMENT		
PERMISSIBLE C.G. LANDING	FROM 31-20	TO 40-40 IN	7	EXTRA EQUIPMENT	124 (2)	270
			8	OPERATING WEIGHT	12797	65513
			9	TAKEOFF FUEL (Gal.)	270	12057
			10	WATER INJ. FLUID (Gal.)		
			11	TOTAL AIRCRAFT WEIGHT	13067	73560

REMARKS	12 DISTRIBUTION OF ALLOWABLE LOAD (PAYLOAD)					
	UPPER COMPARTMENTS			LOWER COMPARTMENTS		
	COMPT	PASSENGERS	CARGO	COMPT	PASSENGERS	CARGO
	NO.	WEIGHT		NO.	WEIGHT	
	A					
	B					
	C					
	D					
	E			1	150	
	F					
	G					
	H					
	I					
	J					
	K					
	L					
	M					
	N					
	O					
	P					
	FWD BULLY					
	AFT BULLY					

COMPT	ITEM	CORRECTIONS (Ref. 14)		13 TAKEOFF CONDITION (Uncorrected)	14 CORRECTIONS (If required)
		CHANGES (+ or -)	WEIGHT		
				129605	98917
				129605	98917
				129605	98917
				235	
				630	2157
				6000	19860
				23025	76900
				300	

**FOR OFFICIAL USE ONLY**

COMPUTED BY: **CPT John L. Shanahan Jr.**

WEIGHT AND BALANCE AUTHORITY: **CPT Larry K. Martin**


PILOT: **10 26377**

NET DIFFERENCE (Ref. 14): **0**

COM. Robert C. Moree SIGNATURE

NOTE.—THIS TRANSPORT CLEARANCE FORM HAS RESULTED FROM TRIPARTITE AGREEMENT AND NO FURTHER CHANGES MAY BE MADE TO IT WITHOUT PRIOR CONSIDERATION BY TRIPARTITE AUTHORITIES.

CRASH SITE CH47A, S/N 64-13116



"FOR OFFICIAL USE ONLY"

1. external load
2. blades struck fence post
3. A/C left aft wheel impact (18" hole)
4. piece of left aft gear strut, upper attaching point
5. actuator shaft, rescue hatch lower door
6. first aid kit
7. fire bottle holder

scale: 1"=50 yds.



DEPARTMENT OF THE ARMY  
 FIELD MARSHALS, 10TH AVIATION BATTALION  
 APO San Francisco 96377

AVIATION

4 June 1971

SUBJECT: Release of OH-47 aircraft, 64-13116.

TO: Commanding Officer  
 243rd Assault Support Helicopter Company  
 APO 96377


1. Request that the following items be turned in for Teardown/Analysis of possible damage as soon as possible:

<u>REQUIREMENTS</u>	<u>Prod. Stock No.</u>	<u>Part No.</u>
a. Engine, aircraft, turbo-prop P-55 L-95, SN L-04997, Fuel control SN 50197 WH control #109-31116	2940-950-6875	2-000-030-18
b. Engine, aircraft, turbo-prop P-55 L-95, SN L-04910, Fuel Control SN 41471, WH control #109-31116-1	2940-950-6875	2-000-030-18
c. Valve, gate, aircraft, (2)	2915-739-2540	114 S401-1
d. Pump, axial piston, (2)	1350-120-7429	114MS127-3
e. Switch, float, liquid level, (2)	2915-992-9470	FA203-2
f. Pump, submerged, (2)	2915-552-6813	114F4111-3
g. Manifold, hydraulic, (1)	1350-391-3036	1E 710100-3
h. Accumulator, hydraulic, (1)	1390-039-7507	114MS133-1
i. Switch, pressure, (1)	5990-13-2366	114 S401-1
j. Actuator, electrohydraulic, (2)		
M1	1390-139-0234	114 S200-2
M2	2915-420-2826	114 S201-2
k. Torque output shaft (engine unknown)	None	None

RELEASE OF CH-47 AIRCRAFT, 64-12116, 10TH CAB, 4 JUNE 1971.

2. U. S. Army CH-47 aircraft, serial number 64-13116, is released from all accident investigation purposes to the commanding officer, for disposition as he sees fit.

"A CERTIFIED TRUE COPY"



JOHN L. SLAUGHTER JR.

CPT, AR

President, Accident Investigation Board



DEPARTMENT OF THE ARMY  
HEADQUARTERS 17TH AVIATION GROUP (COMBAT)  
APO SAN FRANCISCO ~~96316~~ 96316

AVEAV-FS

12 June 1971

SUBJECT: Request for Assistance from USABAAR

Commanding Officer  
10th Combat Aviation Battalion  
ATTN: Aviation Safety Officer  
APO SF 96377

On 1 June 1971 this office requested assistance from USABAAR through USARV to assist in an accident investigation involving a CH-47A SN 64-13116. This request was denied by telephone conversation with Mr. Marty USARV Safety.

A handwritten signature in cursive script, reading "Coy D. Campbell", is positioned above the typed name.

COY D. CAMPBELL  
CW-2, AV  
Asst Safety Officer

FOR OFFICIAL USE ONLY

SECRETARY OF THE ARMY  
U. S. ARMY AIRCRAFT INVESTIGATION BOARD  
110. AV 200, WALKER OFFICE  
31. 10410, ISSUANCE 63166

DAK7-1-116

5 June 1971

Subject: Crash Investigation Report 64-47-116: 64-1,116

President  
Accident Investigation Board  
64-47-116: 64-1,116

This writer was requested to give technical assistance in investigation of the crash and total burn of the above aircraft.

After viewing the wreckage, I give the following as the primary reason for the crash:

On 31 May 1971, with a full crew of six and a full fuel load on board, the aircraft was working a regular mission. In lifting a sling load weighing approximately 6,000 pounds, the aircraft attained an altitude of approximately 70 feet in a hovering takeoff, at about 30 knots forward speed when the Number 2 engine had a complete power failure, (the engine serial number was 4918). This failure, in the writer's opinion, was caused by failure of the fuel control (serial number 4111) fuel pump, which was found badly burned, but with the following conditions: the #1 governor drive shaft (part 22-2447-234-34; Part 12, 12497, Fuel Rod Stock Part: 2915-293-0018, Part Number: 02-15920) was found broken and the small splines excessively worn. They were worn to a degree that caused fuel pump failure. The #1 control actuator was on the open stop, and the fuel actuator was at 70.0%. When the Number 2 engine failed, the number 1 engine took the load with a known range of 20 to 30 pounds. The outside air temperature was 22 degrees centigrade. The number 1 engine (S/N: 4959) lost power due to the fuel band failure. The propeller was in the low pitch. The #2 fuel was too low and the engine flamed out. The fuel control (S/N: 4237) mounted on the number 1 engine was found with the #1 actuator on the full open stop, the #2 was at 72.0%.

The engine was sent into the Army's Steam for transportation to a higher headquarters for local inspection.

This writer was furnished the following information for the purpose of insurance for the crash.

*John D. Simpson*  
John D. Simpson

"FOR OFFICIAL USE ONLY"

c/ George D. Simpson  
110. AV 200, WALKER OFFICE  
31. 10410

DEPARTMENT OF THE ARMY  
U.S. ARMY AVIATION MATERIEL COMMAND  
P.O. BOX 209, MAIN OFFICE  
ST. LOUIS, MISSOURI 63166

ANSAV-L-ATC

15 June 1971

SUBJECT: Summary of Accident Investigation of CH-47A Helicopter  
64-13116, which Crashed and Burned Due to Reported #2  
and #1 Engine Failure.

President  
Accident Investigation Board  
CH-47 SN: 64-13116

a. On 31 May 1971, aircraft 64-13116 crashed and burned. This writer was asked to serve with the accident investigating board as a technical advisor on the airframe.

On 1 June 1971, we went to the crash site outside a Korean Compound at Phu Hiep, RVN. At the site searched the wreckage for visual evidence of what could have caused the crash. Recovered the #2 engine shut off fuel valve, which was open, #1 engine shut off fuel valve. Only the motor was available and the cross feed valve. It was assumed as the #2 valve was open—that fuel starvation was not the cause of engine failure.

b. On 2 June 1971, listened to the statements of W/O [redacted] pilot, W/O Schliep pilot, gunner [redacted] and crew chief [redacted]

c. On 3 June 1971, went back to the crash site to search further, hopefully of finding some evidence of cause for failure. At this time the fuel control of the #2 engine was examined and it was found that the input drive shaft for the N1 governor, the splines were rounded off. This is believed to be the contributing factor for the loss of power on the #2 engine. No inspection of the #1 engine fuel control was made, as it was fairly intact. It is mentioned at this time the reason for the inspection of the #2 fuel control was made, it had been burned so bad the fuel pump and N1 and N2 portion was readily accessible for inspection.

"FOR OFFICIAL USE ONLY"

*from confidential witness statement*

AMSAV-L-ATC

SUBJECT: Summary of Accident Investigation of CH-47A Helicopter  
64-13116, Which crashed and Burned Due to Reported #2  
and #1 Engine Failure.

d. 4 June 1971, the entire crew at one time was interviewed and at this time they more or less all concurred with each others statements.

e. In summary-it is the opinion of this technical advisor-AVSCOM, the contributing factor for the crash is as follows:

1. The N1 drive portion of the fuel control for number two engine failed, causing fuel stoppage to the engine.
2. It is believed the number one engine was running under partial power. In accordance with TM 55-1520-209-10 power curve for single engine operation if power from the number one engine had been full power, the best the pilot could have done was to hover a 22,000 lb aircraft at 40 feet. This aircraft weighed approximately 23000 lbs after dropping sling load.
3. It is not believed in any way this accident should be labeled as pilot error for reasons explained in 2 above.
4. It is not believed this aircraft lost any hydraulic control of the flight control system as explained in para b.



ROBERT J. HEADY  
Equipment Specialist  
Airframe and Airframe Equipment  
U.S. Army Aviation Systems Command

"FOR OFFICIAL USE ONLY"




Figure 7-2. Deviation in regulated gas producer speed (nI)

b. From figure 7-2, determine the nI correction for the existing outside air temperature.

c. This correction is either added to or subtracted from the speed shown on the instrument panel or in the production engine acceptance test log.

d. The resulting percent of nI is the maximum allowable speed at which the engine should operate at military or maximum power for this temperature.

#### 7-17. ENGINE OVERSPEED.

7-18. An engine overspeed condition on the T55 series engines exists whenever either of the following occurs:

a. A gas producer (nI) overspeed exists when the nI limit specified in table 1 of the production engine acceptance test log or DA Form 2408-5, as compensated for by the temperature bias curve, has been exceeded for more than 1 minute or by more than 2 percent. (Refer to paragraph 7-15 and see figure 7-2.)

#### Caution

Any operation that exceeds the above nI limit may cause excessive temperatures in the engine.

b. A power turbine (nII) overspeed condition may exist when 233 rotor rpm has been exceeded by 5 percent for more than 5 seconds. To aid maintenance personnel in determining if an actual nII overspeed has occurred, the pilot must record the following in the DA Form 2408-13 when noting an nII overspeed: Pressure altitude, outside air temperature, peak torque, peak rotor rpm, and duration of overspeed.

#### NOTE

Although no maintenance action is required when the rotor rpm exceeds 233 and does not exceed the overspeed limits, willful operation should not be conducted in excess of 233 rotor rpm.

7-19. CAUSES OF ENGINE OVERSPEED. An nII overspeed may be caused by one or more of the following:

- a. Fuel control governor overshoot.
- b. An abrupt load decrease.

7-20. RESULTS OF ENGINE OVERSPEED. The results of an engine overspeed are as follows:

a. An nI overspeed may result in one or more of the following:

- (1) Overpower
- (2) Overtemperature
- (3) Overtorque

b. An nII overspeed may result in a reduction of power turbine rotor tip clearance.

#### NOTE

(See figures 7-3, 7-4, and 7-5, for the purpose of defining overtemperature.) They do not necessarily indicate the normal operating temperature for any individual engine. Significant changes in exhaust gas temperature at any power level are cause for investigation, even though these limits are not exceeded. A transient is defined as any 1-time cycle of the exhaust gas temperature (an increase, then a decrease).

7-21. ENGINE OVERTEMPERATURE (T55-L-5).

7-22. An overtemperature exists when the time/temperature limits shown on figure 7-3 are exceeded.


7-23. ENGINE OVERTEMPERATURE (T55-L-7 AND T55-L-7B).

7-24. An overtemperature exists when the time/temperature limits shown on figure 7-4 are exceeded.



Model: CH-47A  
 Date: 7 June 1966.  
 Data Basis: Estimated.

Engines: T55-L-7  
 Fuel Grade: JP-4  
 Fuel Density: 6.5 lb/gal.



114-45-10H(2)

POINT A : #2 Engine failure


POINT B : #1 Engine failure / load release

Figure 7-6. Height-velocity diagram for safe landing after single-engine failure

"FOR OFFICIAL USE ONLY"

Model: CH-47A  
Date: 7 June 1966  
Data Basis: Estimated

Engines: T55-L-7  
Fuel Grade: JP-4  
Fuel Density: 6.5 lb/gal.




114-45-10H

Figure 7-9. Single engine and autorotative landing corridor

Model: CH-47A  
 Date: 7 June 1966  
 Data Basis: Estimated

Engines: T55-L-7  
 Fuel Grade: JP-4  
 Fuel Density: 6.5 lb/gal.



POINT A : #2 Engine failure

POINT B : #1 Engine failure / load release


114-45-104

Figure 7-9. Single engine and autorotative landing corridor

Model: CH-47A  
Date: 7 June 1966.  
Data Basis: Estimated.

Engines: T55-L-7  
Fuel Grade: JP-4  
Fuel Density: 6.5 lb/gal.

FE



Large at Po

114-45-10H(2)

Figure 7-8. Height-velocity diagram for safe landing after single-engine failure

**OPERATING WEIGHT  
FERRY FUEL TANK INSTALLED  
19,416 POUNDS**

**OPERATING WEIGHT  
FERRY FUEL TANK REMOVED  
18,812 POUNDS**

**MAXIMUM TAKEOFF AND  
DESIGN ALTERNATE GROSS WEIGHT  
33,000 POUNDS**

**Load Factor = 2.0g  
Landing Gear Sink Speed = 6 Feet/Second**

1. Hover Ceiling (O.G.E.)(2 Engines) = 7,900 Feet  
Hover Ceiling (O.G.E.)(1 Engine) = See Note 1.
2. Rate of Climb at Normal Power (2 Engines) = 1,734 FPM  
Rate of Climb at Military Power (1 Engine) = 161 FPM
3. Service Ceiling at Normal Power (2 Engines) = 9,200 Feet (See Note 2.)  
Service Ceiling at Military Power (1 Engine) = 2,500 Feet

**DESIGN GROSS WEIGHT 28,550 POUNDS**


**Load Factor = 2.67g  
Landing Gear Sink Speed = 8 Feet/Second**




1. Hover Ceiling (O.G.E.)(2 Engines) = 11,900 Feet (See Note 2.)  
Hover Ceiling (O.G.E.)(1 Engine) = See Note 1. \*
2. Rate of Climb at Normal Power (2 Engines) = 2,290 FPM  
Rate of Climb at Military Power (1 Engine) = 600 FPM
3. Service Ceiling at Normal Power (2 Engines) = 11,900 Feet (See Note 2.)  
Service Ceiling at Military Power (1 Engine) = 7,700 Feet

- \* **Notes:**
1. No capability on one engine. \*
  2. Actual service ceiling exceeds altitude limit.

**NOTE**

All performance data shown on this chart is to be used as a guide only, since this data is based on standard day conditions. For exact performance data as affected by temperature and pressure altitude, refer to Chapter 14.



-  **RECOMMENDED LOADING**
-  **CAUTIONARY LOADING**
-  **LOADING NOT RECOMMENDED**

114-19 A-10F

Figure 7-12. Weight limitations chart (T55-L-7 series engines)

POINT A : #2 Engine failure - 29, 035 lbs.

7-21

POINT B : #1 Engine failure / load release - 23,035 lbs.

FOR OFFICIAL USE ONLY

CH 7--SEC II

engines and figure 7-12 is used when the helicopter is equipped with T55-L-7 series engines. The weight limitations charts are intended to provide a rapid means of determining the load carrying capabilities of the helicopter while remaining within safe operating limits. It is not the intent of these charts or the following discussion to establish maximum or minimum limits, but to provide operating personnel with the detail criteria upon which the importance of the mission can be weighed against the degree of risk to be assumed. Depending upon the importance of the mission, the commander will be able, by the use of these charts, to decide whether the mission warrants assuming the risk of exceeding a limitation. The following paragraphs are provided to illustrate the various aspects of the weights limitations charts.

7-65. OPERATING WEIGHT. Operating weight is defined as the weight of the complete helicopter ready for flight less fuel and payload. The operating weight includes the standard crew, full oil load, and all standard equipment. The operating weight is specified on both weight limitations charts for two configurations and is the

basis from which the Alternate (Cargo or Passenger) load is developed. The operating weight was determined as shown on table 7-5. It is necessary to know the operating weight of the helicopter to accurately determine the Alternate Load. The origin of the Alternate Load and Fuel Load axes represents the operating weight specified on the individual chart. Since it is not likely that all helicopters will have the same operating weight it will be necessary to compute the actual operating weight and apply this value to the weight limitations chart. The operating weight is determined as follows:

- a. Determine the basic weight of the helicopter from the DD Form 365C.
- b. To this weight add the following:
  - (1) Engine oil (28 pounds).
  - (2) Crew weight (200 pounds/man).
  - (3) Cargo tiedown devices (50 pounds).
  - (4) Ferry fuel tank components (if installed) (604 pounds).
  - (5) Miscellaneous weight (if applicable) (200 pounds). (Refer to step c. and paragraph 7-73.)


Table 7-5. Operating weight determination

	With T55-L-5 Engines	With T55-L-7 Series Engines
Weight Empty	17,071 pounds	18,134 pounds
Engine Oil	28	28
Crew of 3 (200 Pounds/Man)	600	600
Cargo Tiedown Devices	50	50
Operating Weight (Ferry Fuel Tank Removed)	17,749 pounds	18,812 pounds
Ferry Fuel Tank Components	+604	+604
Operating Weight (Ferry Fuel Tank Installed)	18,353 pounds	19,416 pounds

MILITARY POWER  
(30-MINUTE OPERATION)  
230 ROTOR RPM

Data Basis: Engine Specification  
(Lycoming Report 124.20-A, Amendment No. 4)  
Date: 30 June 1966  
Engines: T55-L-7/7B  
Fuel Grade: JP-4  
Fuel Density: 6.5 Lb/Gal

Notes: 1. The data presented includes installation losses.



114-225-10J

Figure 14-26. Military power available vs altitude

14-36

(1) 780 lbs. - observed torque transient at #1 Engine failure / load release.

NO SPECIAL USE ONLY

FOR OFFICIAL USE ONLY

**A R A D M A C**



YR MO DA

TIME

A/C SERIAL


71 05 31

1300(H)


64-13116

CONTROL NO. RVN LOG 105-31116 -1 thru

Page



**DIRECTORATE FOR QUALITY**



FOR OFFICIAL USE ONLY  
CORPUS CHRISTI, TEXAS



FOR OFFICIAL USE ONLY

9 SEP 1971

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

AIRCRAFT MISHAP CASE NO.		
YR MO DA	TIME	A/C SERIAL
71 05 31	1300(H)	64-13116

CONTROL NO. RVN LOG 105-31116 -1 thru -12

Page 1 of 8

U.S. ARMY AERONAUTICAL DEPOT MAINTENANCE CENTER  
(ARADMAC)  
MATERIEL ANALYSIS DIVISION  
CORPUS CHRISTI, TEXAS 78419

Prepared by:

*T. E. Adams, Jr.*  
T. E. ADAMS, JR.  
Equipment Specialist (Aircraft)

Approved by:

*Eugene A. Wilson*  
EUGENE A. WILSON  
Chief, Materiel Analysis Division

COPY NO 6

THIS PROTECTIVE MARKING CANCELLED EFFECTIVE 10 YEARS FROM DATE OF THIS REPORT.

FOR OFFICIAL USE ONLY

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

USABAAR/THEATRE CONTROL NUMBER  
RVN 105-31116 -1 thru -12

FOR OFFICIAL USE ONLY Page 2 of 8

AIRCRAFT				
1. o. MODEL	b. S/N	c. TIME SINCE NEW	d. TIME SINCE O/H	e. OVERHAUL ACTIVITY AND DATE
CH-47A	64-13116	UNK	UNK	UNK

2. OPERATIONAL CONTROL: 243RD AVN CO UIC: A5C

3. COMPONENTS RECEIVED:

a. NOMENCLATURE	b. PART NUMBER	c. FSN	d. S/N	e. OPERATING TIME
(1) Engine Gas Turb	2-000-030-12	2840-987-9717	LE04957	UNK
(2) Engine Gas Turb	2-000-030-12	2840-987-9717	LE04918	UNK
(3) Misc Parts				
(4)				
(5)				

f. DATE RECEIVED: 2 July 1971

g. TRANS-MODE: (1)  LAND (2)  AIR (3)  SEA

4. SHIPPING CONDITIONS: SPECIFY: Parts received in wooden crate. No packing or padding. Parts were loose in crate.

a.  GOOD b.  POOR

5. REMARKS:  
No EIR (DA Form 2407) received. Positive identification of engines was made from past overhaul and minor repair records at ARADMAC. Number 2 engine on Form 400 and shipping containers listed as T55L7C, LE04198, actual T55L7, LE04918. Number 1 engine listed as T55L7C, actual T55L7. Some miscellaneous parts not identifiable.

6. FINDINGS:  BASIC (MFG/DESIGN) DISCREPANCY  NON-BASIC (MAINT/OPER) DISCREPANCY  FOREIGN OBJECT DAMAGE

7. FAILED OR MALFUNCTIONED MATERIEL DID PART NUMBER OF FAILED OR MALFUNCTIONED MATERIEL MATCH THAT LISTED IN TM? YES  NO  UNK  (IF "NO" OR "UNK", SPECIFY IN BLOCK 8F, EXPLANATION)

IDENTIFICATION AND HISTORICAL DATA	A. MAJOR COMPONENT	B. SUBASSEMBLY	C. COMPONENT	D. PART
1. NOMENCLATURE	Engine Gas Turb		Fuel Control	Shaft, Drive, Int
2. TYPE, MODEL, SERIES	T55L7		JFC-31-12	
3. PART NUMBER	2-000-030-12		592964L13	02-13920
4. FSN	2840-987-9717		2915-761-0002	2915-963-0978
5. MFG CODE	91547		73030	77200
6. TM DATA:				
A. TM NUMBER	55-2840-234-34P		55-2840-234-34P	55-2840-234-34P
B. DATE	Oct 70		Oct 70	Oct 70
C. FUNCTIONAL GROUP	03		03	03
D. FIGURE NUMBER	3		35	52
E. INDEX NUMBER			9	30
7. SERIAL NUMBER	LE04918		41441	NA

AIRCRAFT MISHAP CASE NO.				OTHER AIRCRAFT	
YR	MO	DA	TIME	A/C SERIAL	T/M/S
71	05	31	1300 (H)	64-13116	SERIAL

FOR OFFICIAL USE ONLY

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP

TEARDOWN ANALYSIS

(Continuation Sheet)

USABAAR/THEATRE CONTROL NUMBER

RVN 105-31116

FOR OFFICIAL USE ONLY Page 3 of 8

3. TAMMS DATA:					
A. NO. OF OVERHAULS		UNK			
B. HR. SINCE OVERHAUL		UNK			
C. HR. SINCE NEW		UNK			
D. HR. SINCE LAST INSTALL.		UNK			
E. LAST OVERHAUL-FACILITY		ARADMAC			
9. LAST SPECIAL INSPECTION: (INDICATE FOR THESE COMPONENT(S))					
A. TYPE		UNK			
B. DATE		UNK			
C. HOURS SINCE		UNK			
10. TYPE FAILURE		386			
11. CAUSE OF FAILURE		920			
12. EIR CONTROL NUMBER		None			

8. ANALYSIS

1. POL CLASS	T Y P E	SAMPLE				CONTAMINATED			CAUSATIVE ROLE				FILTER COND.				
		(1)	(0)	DATE TAKEN		(1)	(0)	(7)	(0)	(7)	(N)	(B)	(C)	(W)			
		YES	NO	YR	MO	DAY	YES	NO	UNK	D	S	NONE	UNK	MAL	PASS	CLOGGED	N/A
1. FUEL			X														
2. OIL, ENGINE			X														
3. OIL, TRANSMISSION(S)																	
4. HYDRAULIC FLUID																	
5. OTHER																	

B. LAST ASOAP SAMPLE TAKEN (SPECIFY LABORATORY) LAB: \_\_\_\_\_ C. SPECIAL ANALYSIS (SPECIFY LABORATORY) LAB: \_\_\_\_\_

AFFECTED COMPONENT	DATE YR MO DAY	A/CHR	HR SINCE	ITEM	TYPE ANALYSIS	FINDINGS

D. TEARDOWN ANALYSIS REQUEST: WAS TEARDOWN ANALYSIS REQUESTED? YES  NO  USABAAR/THEATRE CONTROL NO. \_\_\_\_\_

F. EXPLANATION OF FAILURE/MALFUNCTION:

- The inlet housing and accessory drive gear box were consumed by fire (Incl 1 & 2).
- There was no evidence of FOD or rotational damage on the inlet guide vanes, the compressor, or the stator vanes (Incl 2 & 3).
- There was no rotational, or overtemperature damage in the first stage turbine area (Incl 4).
- There was no rotational or overtemperature damage in the second stage turbine area (Incl 5).
- There was no rotational or overtemperature damage in the third stage turbine area (Incl 6).

AIRCRAFT MISHAP CASE NO.					OTHER AIRCRAFT	
YR	MO	DA	TIME	A/C SERIAL	T/WAS	SERIAL
71	05	31	1300(H)	64-13116	FOR OFFICIAL USE ONLY	

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP

USABAAR/THEATRE CONTROL NUMBER

RVN 105-31116

TEARDOWN ANALYSIS

FOR OFFICIAL USE ONLY

Page 4 of 8

F. (Continued)

6. The second and third stage turbine assembly turned free and quiet.
7. The fuel control was intact but exposure to intense heat melted the lead indium and copper tin plating on the fuel pump drive bearing, P/N 02-13503, 04, and 09, and caused them to seize. Disassembly of the fuel control failed to reveal physical damage, other than exposure to intense heat, that would have caused an engine failure.

G. CONCLUSIONS:

1. Disassembly and inspection of parts and components from this engine, T55L7, LE04957, that were not destroyed by fire, failed to reveal a physical failure that would have caused an engine failure.
2. The absence of rotational damage on the compressor and turbine assemblies, the even coating of magnesium ash throughout the engine and on the tail pipe indicated that the engine was probably not producing power at impact.

AIRCRAFT MISHAP CASE NO.

YR	MO	DA	TIME	A/C SERIAL
71	05	31	1300(H)	64-13116

OTHER AIRCRAFT

T/M/S	SERIAL

FOR OFFICIAL USE ONLY

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

USABAAR/THEATRE CONTROL NUMBER

RVN 105-31116 -1

(Continuation Sheet)

FOR OFFICIAL USE ONLY

Page 5 of 8

9. TAMMS DATA:				
A. NO. OF OVERHAULS	UNK		UNK	UNK
B. HR. SINCE OVERHAUL	UNK		UNK	UNK
C. HR. SINCE NEW	UNK		UNK	UNK
D. HR. SINCE LAST INSTALL.	UNK		UNK	UNK
E. LAST OVERHAUL-FACILITY	Minor @ ARADMAC		UNK	UNK
9. LAST SPECIAL INSPECTION: (INDICATE FOR THESE COMPONENT(S))				
A. TYPE	UNK		UNK	UNK
B. DATE	UNK		UNK	UNK
C. HOURS SINCE	UNK		UNK	UNK
10. TYPE FAILURE				
				020
11. CAUSE OF FAILURE				
				920
12. EIR CONTROL NUMBER				
None Received				

8. ANALYSIS																	
POL CLASS	TYPE	SAMPLE					CONTAMINATED			CAUSATIVE ROLE			FILTER COND.				
		(1) YES	(0) NO	DATE TAKEN			(1) YES	(0) NO	(7) UNK	D	S	(0) NONE	(7) UNK	(N) NOR-MAL	(B) BY PASS	(C) CLOGGED	(W) N/A
FUEL			X														
OIL, ENGINE			X														
3. OIL, TRANSMISSION(S)																	
HYDRAULIC FLUID																	
OTHER																	

b. LAST ASOAP SAMPLE TAKEN (SPECIFY LABORATORY) LAB:						c. SPECIAL ANALYSIS (SPECIFY LABORATORY) LAB:					
AFFECTED COMPONENT	DATE YR MO DAY	A/CHR	HR SINCE	ITEM	TYPE ANALYSIS	FINDINGS					
				Shaft, Drive	Metal	020 Abrasive wear					

d. TEARDOWN ANALYSIS REQUEST: WAS TEARDOWN ANALYSIS REQUESTED? YES  NO  USABAAR/THEATRE CONTROL NO. RVN 105-31116 -1

f. EXPLANATION OF FAILURE/MALFUNCTION:

- All magnesium housings were consumed by fire (Incl 7).
- There was no evidence of FOD or rotational damage on the inlet guide vanes, the compressor, or the stator vanes (Incl 3 & 7).
- There was no rotational or overtemperature damage in the first stage turbine area (Incl 8).
- There was no rotational or overtemperature damage in the second stage turbine area (Incl 9).
- There was no rotational or overtemperature damage in the third stage turbine area (Incl 10).
- The second and third stage turbines turned free and quiet.

AIRCRAFT MISHAP CASE NO.					OTHER AIRCRAFT				
YR	MO	DA	TIME	A/C SERIAL	FOR OFFICIAL USE ONLY			T/W/S	SERIAL
71	05	31	1300(H)	64-13116					

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

USABAAR/THEATRE CONTROL NUMBER  
RVN 105-31116-1

Page 6 of 8

FOR OFFICIAL USE ONLY

F. (Continued)

F7. The fuel pump housing on the fuel control was melted; however, the drive coupling, P/N 02-14311, (Incl 11), and the intermediate drive shaft, P/N 02-13920, were intact (Incl 11). Both parts showed evidence of spline failure (Incl 12). Both parts were sent to the metallurgical laboratory for evaluation.

G. CONCLUSIONS:

1. Disassembly and inspection of the parts of this engine received for analysis, revealed that failure of the splines in the intermediate drive shaft, P/N 02-13920, could have caused the Number 1 fuel pump and the N1 governor fly weights to stop turning which would have caused the fuel control to go to minimum flow or possibly no flow condition. This condition could have caused a flame out in this engine.
2. Failure of the fuel control intermediate drive shaft, P/N 02-13920, can be attributed to abrasive wear (See Laboratory report No 71MX178, Incl 13).

H. RECOMMENDATIONS:

1. It is recommended that AVSCOM engineering investigate the possibility of a one time inspection of all T55 engine fuel controls with 500 or more hours since new or overhaul.
2. A copy of D/F request for ARADMAC to perform a 100% inspection on all intermediate drive shaft lower splines, P/N 02-13920, is attached (Incl 16). It appears prudent that this information be incorporated as a revision of contract specifications with Hamilton Standard Corporation.

AIRCRAFT MISHAP CASE NO.					OTHER AIRCRAFT	
YR	MO	DA	TIME	A/C SERIAL	T/M/S	SERIAL
71	05	31	1300(H)	64-13116		

FOR OFFICIAL USE ONLY

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

USABAAR/THEATRE CONTROL NUMBER  
RVN 105-31116 -2 thru -12

(Continuation Sheet)

FOR OFFICIAL USE ONLY Page 7 of 8

TAMMS DATA:				
A. NO. OF OVERHAULS		UNK		
B. HR. SINCE OVERHAUL		UNK		
C. HR. SINCE NEW		UNK		
D. HR. SINCE LAST INSTALL.		UNK		
E. LAST OVERHAUL-FACILITY		UNK		
9. LAST SPECIAL INSPECTION: (INDICATE FOR THESE COMPONENT(S))				
A. TYPE		UNK		
B. DATE		UNK		
C. HOURS SINCE		UNK		
D. TYPE FAILURE		900		
E. CAUSE OF FAILURE		712		
12. EIR CONTROL NUMBER		None received		

POL CLASS	TYPE	SAMPLE			CONTAMINATED	CAUSATIVE ROLE				FILTER COND.							
		(1) YES	(0) NO	DATE TAKEN		ANALYSIS RESULTS	(1) YES	(0) NO	(7) UNK	D	S	(0) NONE	(7) UNK	(N) NOR-MAL	(B) BY PASS	(C) CLOG-GED	(W) N/A
FUEL			X														
OIL, ENGINE			X														
OIL, TRANSMISSION(S)			X														
HYDRAULIC FLUID			X														
OTHER			X														

B. LAST ASOAP SAMPLE TAKEN (SPECIFY LABORATORY)				C. SPECIAL ANALYSIS (SPECIFY LABORATORY)			
LAB:				LAB:			
AFFECTED COMPONENT	DATE	A/C HR	HR SINCE	ITEM	TYPE ANALYSIS	FINDINGS	
	YR MO DAY						

TEARDOWN ANALYSIS REQUEST: WAS TEARDOWN ANALYSIS REQUESTED? YES  NO  USABAAR/THEATRE CONTROL NO. RVN 105-31116 -2 thru -12

F. EXPLANATION OF FAILURE/MALFUNCTION:

Item 7, Page 1  
Part Numbers not legible on most miscellaneous parts, extensive fire damage.

1. Miscellaneous parts received, cargo hook and hoist assembly, number 1 left fuel valve, number 1 N1 and N2 actuators, number 1 flight boost pump, torquemeter output shaft, 2 engine to transmission quill shafts, right aft fuel level float switch, right aft fuel boost pump, left forward fuel boost pump, number 2 N1, & 2 actuators, mechanical transmission parts, hydraulic accumulator, several unidentifiable small gears and shafts, pieces of engine cowling and fairing (Incl 1).

2. All parts had been exposed to intense heat and were extensively damaged.

3. It was not possible to functional test, x-ray, or flow test these parts because of extensive heat damage.

AIRCRAFT MISHAP CASE NO.					OTHER AIRCRAFT		
YR	MO	DA	TIME	A/C SERIAL	T/M/S	SERIAL	
71	05	31	1300(H)	64-13116			

FOR OFFICIAL USE ONLY

TECHNICAL REPORT OF U.S. ARMY AIRCRAFT MISHAP  
TEARDOWN ANALYSIS

USABAAR/THEATRE CONTROL NUMBER  
RVN 105-31116 -2 thru -12

FOR OFFICIAL USE ONLY

Page 8 of 8

F. (Continued)

4. Parts and components that could be examined showed no evidence of failure prior to impact and fire.

G. CONCLUSIONS:

Visual and microscopic inspection of the miscellaneous parts failed to reveal a physical failure that could have caused the loss of power to either engine.

16 Incl  
as

AIRCRAFT MISHAP CASE NO.


YR	MO	DA	TIME	A/C SERIAL
71	05	31	1300(H)	64-13116

OTHER AIRCRAFT

T/M/S	SERIAL

FOR OFFICIAL USE ONLY





MISCELLANEOUS PARTS  
CHATA, SIN 6A-13116

LEASS


LEASS

INCL 1.



GENERAL USE

INCL 2




75522  
2628957  
RM 45-3116  
Compressor Rotor  
No. 201-1000-1000

75527-168-498  
RM 45-3116-1  
Compressor Rotor  
No. 201-1000-1000

75527-168-498

FOR OFFICIAL USE ONLY




73527  
LE04957  
RM 195-3116  
1ST STAGE TURBINE  
NO DAMAGE!

FOR OFFICIAL USE ONLY

INCL. 4.


FOR OFFICIAL USE ONLY



75527  
LEP 4957  
R/N 105-31116  
2ND STAGE TURBINE  
No Damage!


FOR OFFICIAL USE ONLY

INCL 5




FOR OFFICIAL USE ONLY

INCL. G.



INCL. 7


FOR OFFICIAL USE ONLY



IN 118



FUR UFFI... USE CIVIL




75527  
LEØ4918  
R/L 1053116-1  
in Sims 120mm  
No Drainer!

LEØ4918

6-22-68

FOR OFFICIAL USE ONLY


T55L7 LED4910  
RYN 105-31116-1  
3RD STAGE TURBINE  
NO DAMAGE



Incl. 10.

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY



R/VN. 105-31116, -1 TMR 12  
F/C DRIVE SHAFT. FIC SIN 4144

FOR OFFICIAL USE ONLY

INCL. 11.

FOR OFFICIAL USE ONLY



FOR OFFICIAL USE ONLY

ENC. 02.

FOR OFFICIAL USE ONLY

DEPARTMENT OF THE ARMY  
U.S. ARMY AERONAUTICAL DEPOT MAINTENANCE CENTER  
CORPUS CHRISTI, TEXAS 78419



Chemical-Metallurgical Division  
Laboratory Report Number 71MX178

19 August 1971

SUBJECT: RVN Log Number 105-31116  
T55-L7 Engine, S/N LE04198  
Failure of Fuel Control  
Drive Shaft Coupling, P/N 02-14311  
Internal Drive Shaft, P/N 02-13920

HISTORY: The subject engine was reported to have failed in flight. The magnesium and aluminum components of the engine were destroyed in the post crash fire. Teardown analysis of the remaining components disclosed the failure of the splined coupling between the internal drive shaft and drive shaft coupling of the fuel control. The total time for this engine was reported to be 1368 hours and the time since overhaul was 172 hours. The TT and TSO for the fuel control are unknown.

OBJECTIVE: To determine the mode and cause of the fuel control coupling failure.

ANALYSIS:

1. The damage to the male splines on the internal drive shaft and the female splines on the drive shaft coupling occurred by abrasive wear (See Incl 14 and Incl 15). This is a form of progressive or time dependent damage in which time is a function of coupling design and the torque transmitted by the coupling. This coupling is located in the fuel system and is not lubricated. The damage to both the male and female splines is typical of spline failures in unlubricated splines or the splines in couplings where the lubricating system has failed.
2. The cause of the coupling failure cannot be determined because of fire damage and the absence of positive information on the materials and specified properties of the splines. The failure was probably initiated by either fretting corrosion or the introduction of a foreign abrasive material into the coupling. In either case, abrasive wear would occur at an increasing rate until one of the splines (the male splines on the internal drive shaft) failed. The acceleration of the wear rate results from the retention of wear particles in the coupling.

FOR OFFICIAL USE ONLY

BUY AND HOLD U.S. SAVINGS BONDS

FOR OFFICIAL USE ONLY


Chemical-Metallurgical Division  
Laboratory Report Number 71MX178

19 August 1971  
Page 2

3. Metallographic examination of sections through the splines indicated that both splines had received surface hardening treatments. The male splines on the internal drive shaft appeared to be carburized AISI 9310 (AMS 6260) or a similar carburizing steel. Microhardness measurements indicate some decarburization about 0.001 inches at the surface but below that, a hardness which is substantially the same across the diameter of the shaft, about RC 40. The female splines in the drive shaft coupling appear to be nitrided AMS 6470 or a similar nitriding steel. Microhardness measurement on a section of the coupling indicates the coupling was probably nitrided nitralloy. The average hardness of the surface is RC 54 and the average hardness of the core was RC 30. The loss of hardness in both components was caused by overtempering and decarburization during the post crash fire.

RECOMMENDATION:

No history of failures or impending failures in this coupling is available. The total operating time and time since overhaul for the fuel control are unknown and probably can not be determined with certainty. Because the failure of the internal drive shaft splines can result in engine failure, the effect of operating time on wear damage in this coupling should be evaluated. This evaluation should include the removal and inspection of the drive shaft coupling and internal drive shaft from 10 or more high time fuel controls with known operating times. Any splines showing a preceptable wear depth should be submitted to the laboratory for metallurgical evaluation.



W. H. ROBERTS  
METALLURGIST




E. E. JUEG, CHIEF  
CHEM/MET DIVISION

FOR OFFICIAL USE ONLY

FOR OFFICIAL USE ONLY

COMPLETE FAILURE AT END  
OF MALE SPLINES.  
INTERMEDIATE  
DRIVE SHAFT  
PIN Ø 2-1390



INCOMPLETE FAILURE  
OF MALE SPLINES.

1 INCHES

FOR OFFICIAL USE ONLY

ENC. 14.

FOR OFFICIAL USE ONLY



FOR OFFICIAL USE ONLY

INCL. 15.



FOR OFFICIAL USE ONLY

# DISPOSITION FORM

For use of this form, see AR 340-15; the proponent agency is The Adjutant General's Office.

REFERENCE OR OFFICE SYMBOL

SAVAE-QA

SUBJECT

Inspection of All T-55 Fuel Controls

THRU: DFQ

FROM CH/MATL ANAL DIV

DATE 27 Aug 71

CMT 1

T. Adams/ps/2902

TO: CH/MAINT QUAL CONT DIV

1. This division completed a teardown investigation on the engines and fuel controls of a CH-47 accident. Fatalities were involved.
2. It was determined from the results of this investigation that the primary cause of engine failure was the failure of the intermediate drive shaft in the fuel control, P/N 02-13920, from extensive wear between the lower shaft splines and the female splines in the drive coupling.
3. On 23 August 1971, another T-55 fuel control was inducted for teardown investigation. The results of this failure was identical to the above failure.
4. Mr. Shipley, fuel control supervisor, has verbally advised that he estimates that he is experiencing approximately 30% rejection rate on this intermediate drive shaft, P/N 02-13920, on all T-55 fuel controls processed through the fuel control shop.
5. In view of the above, request that the work specifications be reviewed to insure that all T-55 fuel controls received at ARADMAC are inspected 100% for excessive wear of the intermediate drive shaft and drive coupling.

*Eugene A. Wilson*  
 EUGENE A. WILSON  
 Chief, Materiel Analysis Division

Incl 16

FOR OFFICIAL USE ONLY

DA FORM 2496  
1 FEB 62

REPLACES DD FORM 96, EXISTING SUPPLIES OF WHICH WILL BE ISSUED AND USED UNTIL 1 FEB 63 UNLESS SOONER EXHAUSTED.

GPO: 1970-341-701







