

* EMPLOYEE BULLETIN

No. 75-38

November 25, 1975

UTTAS 001 ACCIDENT SEQUENCE ESTABLISHED- AIRCRAFT REPAIRABLE

The sequence of events in UTTAS aircraft 001 accident have been clearly established. During buildup maneuvers toward the 85 knot autorotative pull-out point of the structural demonstration an RPM overshoot to approximately 125% of normal RPM was encountered. During the RPM overshoot the most forward section of the tail rotor drive shafting (between the main transmission and the intermediate transmission) contacted a work step in the aft transmission compartment. The contact with this step tore the first section of shaft causing it to fail and eliminating the drive torque to the tailrotor. This, of course, resulted in the loss of directional control. Due to the low airspeed and low altitude existing following this occurrence, it was impossible to get the aircraft into a forward flight speed regime where adequate vertical tail effectiveness would provide directional control of the aircraft. The aircraft came down into a patch of dense oak woods.

Accident Investigation Board

The U. S. Army has established an official military accident investigation board headed by Colonel Dennis Boyle to investigate the accident. The Company is cooperating fully with the Board. Any official public releases will be made by the Army Board.

UTTAS aircraft 002 and 003 have been cleared by the Army to resume their flight test program. Also, the Army's Pilot Evaluation Program is proceeding as planned, operating with autorotative RPM restrictions which will avoid the recurrence of the 001 problem.

001 Repairable

On Saturday, November 22, a CH-47 Chinook piloted by A. J. Hutto and Al Santa Maria airlifted the UTTAS aircraft from the crash site to the company's facility at the Calverton, Long Island test center. Today, 001 is being brought back to Center 3 at Boeing Center.

Since shortly after the accident took place, a team from Boeing Vertol has been "on the scene" determining the extent of damage to the aircraft.

The main fuselage structure is essentially undamaged. The tail rotor has four blades still attached to the straps in proper connection to the tail rotor hub and shaft even though the tail boom broke loose from the aircraft. Based upon detailed examinations of the damaged aircraft, the company is recommending to the U. S. Army that 001 be repaired and returned to flight status.

Impact on Program

We are reviewing the impact of the accident on our schedule for delivery of aircraft for the Government Competitive Test. A delay of approximately one month is currently indicated based on developing and qualifying an adequate fix for the tail rotor shaft and then completing the aircraft Structural Demonstration program.

Crashworthiness Demonstrated


Just as every dark cloud has its bright lining, this accident was a spectacular demonstration of the crashworthiness of the YUH-61 design. Both of our pilots, Frank Duke and Ron Mecklin, were uninjured and there was no fire.

During entry into the woods the main rotor blades and tail rotor blades contacted a number of oak trees ranging in diameter from 6" to 15". The transmission is firmly in place in the aircraft structure with no evidence of any movement of the transmission and transmission mounting structure. For example, it was possible to open the hatch immediately aft of the transmission with no evidence that any structural deformation of the butt line beams on which the hatch tracks are mounted had taken place.



CH-47C Chinook, piloted by A. J. Hutto and Al Santa Maria, returns 001 UTTAS to Calverton flight test facility.

The following photographs taken at the Calverton test center on Saturday, November 22, show the structural integrity demonstrated by the rotor system and airframe structure.



Y
FT

| | | | | | |
|---------|---|-----------------------------------|--|--|---------------------|
| GENERAL | MODEL YUH-61A | IDENTIFICATION Tab 001 | LOCATION Peconic River A/P Calverton, N.Y. | DATE 11/18/75 | TIME 1400 |
| | DEPARTURE POINT Peconic River A/P | TIME 1330 | DESTINATION POINT Local Flight | DURATION 2 hours | |
| | MISSION Test | ASSIGN TO Boeing Vertol | | BASE Peconic River A/P Calverton, N.Y. | |
| | START 236:42 | TIME TO FLIGHT 0:35 | HOURS SINCE PERIODIC | HOURS SINCE MINOR | TIME OF LAST |

| | | | | | |
|-----------------------|--|---|---|---|--|
| DAMAGE CLASSIFICATION | WEIGHT AT TAKE-OFF 15,920 lbs | WEIGHT AT MISHAP 15,400 lbs | CENTER OF GRAVITY AT TAKE-OFF <input type="checkbox"/> FOREAFT X <input type="checkbox"/> AFT c.g. 15.3"A | | |
| | ACCIDENT: <input type="checkbox"/> MAJOR <input type="checkbox"/> MINOR | LANDING: <input type="checkbox"/> PRECAUTIONARY FORCED <input type="checkbox"/> COMBAT DAMAGE | <input type="checkbox"/> STRUCK ALPHA <input type="checkbox"/> MAJOR SUBSTANTIAL | <input type="checkbox"/> OVERHAUL <input type="checkbox"/> MINOR <input type="checkbox"/> LAME TO | <input type="checkbox"/> NOT REPAIRABLE <input checked="" type="checkbox"/> NO DAMAGE <input type="checkbox"/> OTHER |

| PHASE OF OPERATIONS | OPERATION | | OPERATION | | OPERATION | | OPERATION | |
|----------------------------|-----------|---|---------------------|---|---------------------|---|-------------------------|----------|
| | | ✓ | | ✓ | | ✓ | | ✓ |
| 1. TAXI | | | 8. REAR FLIGHT | | 15. LANDING RT | | 22. TAXIING | |
| 2. ROTOR ENGAGE | | | 9. SIDE FLIGHT | | 16. GO AROUND | | 23. SLING/HOIST PICK-UP | |
| 3. TAKE-OFF | | | 10. CLIMB | | 17. ROTOR SHUT-DOWN | | 24. SLING/HOIST RELEASE | |
| 4. TAKE-OFF TO GROUND ROLL | | | 11. DESCENT | | 18. ROTOR FOLD | | 25. GROUND SERVICE | |
| 5. FLARE | | | 12. ALTITUDE CHANGE | | 19. LAND APPROACH | | 26. GROUND OPERATIONS | |
| 6. TRANSITION | | | 13. FLARE | | 20. PARKED - GROUND | | 27. Level Flight | X |
| 7. PARKED - TAXI | | | 14. TOUCH-DOWN | | 21. PARKED - WATER | | 28. | |

| | | | |
|----------------------------|----------------------------------|------------|----------|
| NUMBER OF CREW 2 | NUMBER OF PASSENGERS 2 | FATALITIES | INJURIES |
| CREW | PASS. | CREW | PASS. |

| PERSONNEL | NAME | CREDENTIALS | STATUS | TOTAL FLIGHT TIME | TIME THIS MODEL |
|----------------------|-------------------|--------------|-------------|-------------------|-----------------|
| | F. H. Duke | Pilot | None | | |
| J. R. Mecklin | Copilot | None | | | |

PASSENGERS
None

| | | | | | |
|---------------------------------|---------------------------------|---|--------------------------------|---------------------------|--|
| <input type="checkbox"/> I.F.R. | <input type="checkbox"/> V.F.R. | <input checked="" type="checkbox"/> LOCAL | <input type="checkbox"/> OTHER | TIME OF LAST RADIO REPORT | TROUBLE REPORTED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
|---------------------------------|---------------------------------|---|--------------------------------|---------------------------|--|

STATE OF TROUBLE
No. 2 engine transmission oil pressure dropped to minimum in-flight limit. A/C landed at Mattituck A/P & reserviced, hover checked & returned to Peconic River

to Peconic River & Chase Plane

| | | | | |
|---|--------------------------------|--|--|---|
| No factor | TEMP. (F.) No factor | DEW POINT No factor | WIND DIRECTION No factor | WIND VELOCITY No factor |
| <input type="checkbox"/> FOG | <input type="checkbox"/> HAIL | <input type="checkbox"/> THUNDERSTORMS | <input type="checkbox"/> TURBULENCE MODERATE <input type="checkbox"/> SEVERE | <input type="checkbox"/> LIGHTNING OTHER Not Applicable |
| <input type="checkbox"/> DRIZZLE | <input type="checkbox"/> DUST | <input type="checkbox"/> LOW CLOUDS | | |
| <input checked="" type="checkbox"/> OTHER Not Applicable | | | | |

| | | | | | | |
|-----------------------|---|----------------------------------|------------------------------------|---------------------------------|--------------------------------|---------------------------------|
| Not Applicable | <input type="checkbox"/> LEVEL | <input type="checkbox"/> ROLLING | <input type="checkbox"/> MOUNTAINS | <input type="checkbox"/> WOODED | <input type="checkbox"/> WATER | <input type="checkbox"/> DESERT |
| | <input checked="" type="checkbox"/> OTHER Not Applicable | | | | | |

REMARKS

MISHAP REPORT

REPORT DATE **8/2/76** FROM **A. J. Hutto**

GENERAL

MODEL **179** S/N **N179BV/101** LOCATION **Salem, N.J.** DATE **7/30/76** TIME **12:10**

DEPARTURE POINT **Wilmington** TIME **11:31** DESTINATION POINT **Wilmington** E.T.A. **12:30**

MISSION **TRIS Development Flight** SLING TOWING ASSIGN TO **Boeing Vertol** BASE **Wilmington**

A/C T.T. **232 hours** TIME THIS FLIGHT **:42** HOURS SINCE PERIODIC **-** HOURS SINCE MINOR **-** TIME OF LAST O/H **-**

GROSS WEIGHT AT TAKE-OFF **14,500** WEIGHT AT MISHAP **14,200** CENTER OF GRAVITY AT TAKE-OFF FOREWARD AFT **Mid**

DAMAGE CLASSIFICATION

ACCIDENT: MAJOR MINOR PRECAUTIONARY FORCED INCIDENT COMBAT DAMAGE

LANDING: PRECAUTIONARY FORCED COMBAT DAMAGE

STRIKE-ALPHA MAJOR SUBSTANTIAL LIMITED

OVERHAUL MINOR LIMITED

NON-RECOVERABLE NO DAMAGE OTHER

FIRE EXPLOSION PRE-MISHAP AT MISHAP POST MISHAP

PHASE OF OPERATIONS

| OPERATION | ✓ | OPERATION | ✓ | OPERATION | ✓ | OPERATION | ✓ |
|-------------------------------|---|-----------------|---|--------------------|---|------------------------|---|
| 1 START | | 8 REAR FLIGHT | | 15 LANDING ROLL | | 22 TOWING | |
| 2 ROTOR ENGAGE | | 9 SIDE FLIGHT | | 16 GO AROUND | | 23 SLING/HOIST HOOK-UP | |
| 3 TAXIING | | 10 CLIMB | | 17 ROTOR SHUTDOWN | | 24 SLING/HOIST RELEASE | |
| 4 LIFT OFF T.O. - GROUND ROLL | | 11 DESCENT | | 18 ROTOR FOLD | | 25 GROUND SERVICE | |
| 5 HOVER | | 12 AUTOROTATION | | 19 LAND APPROACH | | 26 GROUND OPERATIONS | |
| 6 TRANSITION | | 13 FLARE | | 20 PARKED - GROUND | | 27 Cruise | |
| 7 FORWARD FLIGHT | | 14 TOUCHDOWN | | 21 PARKED - WATER | | 28 | |

NUMBER ABOARD **2** NUMBER IN CREW **2** FATALITIES: **None** INJURIES: **None**

CREW **None** PASS. **None** CREW **None** PASS. **None**

PERSONNEL

| NAME | CREW DUTY | INJURY | TOTAL FLIGHT TIME | TIME THIS MODEL |
|--------------------|----------------|--------|-------------------|-----------------|
| A. J. Hutto | Copilot | | | |
| A. Mehofer | Pilot | | | |

PASSENGERS **None**

RADIO DATA

I.F.R. V.F.R. LOCAL OTHER

TIME OF LAST RADIO REPORT **-** TROUBLE REPORTED? YES NO

NATURE OF TROUBLE
Developed leak in #2 hydraulic boost system. Low quantity caution light was followed by loss of oil pressure and loss of #2 SAS.

WEATHER

CEILING **No factor** TEMP. (F.) **27°C** DEW POINT **-** WIND DIRECTION **NW at 10** WIND VELOCITY **10 knots**

FOG HAIL THUNDERSTORMS TURBULENCE MODERATE LIGHTNING OTHER

ICING DUST LOW CLOUDS SEVERE

OTHER

TERRAIN

ELEVATION **FT.** LEVEL ROLLING MOUNTAINS WOODED WATER DESERT

OTHER

REMARKS

Aircraft landed at Salem Airport. Determined leak to be tail rotor control actuator. Isolated the #2 boost lines to the tail rotor and re-serviced the system and returned to Wilmington.

