

MISHAP REPORT


CH47C 69-17118 (B633)
271st Aviation Co.
KOREA
5 August 1977

MAJOR ACCIDENT - STRIKE

Aircraft had completed MOC (Maintenance Operation Check) flight and was sitting on end of runway. Pilots were conducting engine check, and were light on the gear, when two thumps were heard and immediately the aircraft went into a shuffle. The pilots shut down and pulled both fire handles.

The aft pylon was found to be displaced from its normal position on the airframe but had not completely separated. There was evidence of rotor blade intermeshing. There were no reports of any injuries.

Aircraft may be considered a Strike at this time.


R. G. ORR

RGO:aty
P41-37/X7937